

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 10 Apr 2018

Preliminary Advice

Insured Vehicle No : SDY2210T
TP Vehicle No : FBK5061J Accident Date : 02/04/2018
Make : YAMAHA YBR125 Assignment Date : 06/04/2018
Date of Inspection : 06/04/2018 Est. Duration of Repair : 3 days
Inspection At : Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear, n/s and o/s body portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|--------|
| Repairer's Estimate (Gross) | :S\$ | 706.00 |
| Revised Amount | :S\$ | 398.00 |
| Check Items (Estimated) | :S\$ | 1.50 |
| Total | :S\$ | 399.50 |
| Lump Sum Repair | | :S\$ |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.