

REF:

NS/TNC18006380/Stbm2

Signature

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SKP 1761R

Policy No:

5092256495

270617 - 0510-18

Claims No:

MT/0988974-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

SHF 4744P - X

SKP 1761R - X

Confirmed L1s \$9200, 8 days
 Rd: \$22,589.66, 71%

RECEIVED 27 APR 2018

Date/Time. File Pass to?

☐ : Prel. Report☒ : Final Report

1) tjpst

Date/Time. File Return to?

2)

Report Format:

Lump Sum / LB.1: (\$

7P

9200

Veh No:

SHF 4744P

Yr Regn:

30/7/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prime

C.C. 1798

Colour:

Magenta

A/C: Insured / Std / NI / NA

Sp. Reading

264997

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN364703751766

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU4 PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/4/18

D.O.I.

5/4/18

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

TAX/04/18/2017

LKK

NTUC

SKP 1761R

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

- ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Invs (\$
☐ : Weekend (\$

Survey Fee:

Transportation.

) \$ + RS. \$

: Photos

: Others

TOTAL

160
35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006385/Srb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 06-04-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 1761R	Veh. Inspected	SHF 474P
Policy No.	5092256495	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/04/2018	Inspection Date	05/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

[Search](#)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5092256495	S.M.CHIA	53365467W	GCV	Comprehensive	SKP1761R	SKP1761R	27/06/2017	05/10/2018

[Continue](#)

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0991340-002	COMFORT TRANSPORTATION PTE LTD	SH 7013A	SJL 3277S
2	MT/0990420-002	COMFORT TRANSPORTATION PTE LTD	SHC 1833X	GBG 6935C
3	MT/0991001-002	COMFORT TRANSPORTATION PTE LTD	SHB 4181D	SJF 4165G
4	MT/0987576-002	SMRT TAXIS	SHB 5490E	SGN 2724A
5	MT/0988974-002	SMRT TAXIS	SHF 474P	SKP 1761R
6	MT/0988606-002	SMRT TAXIS	SHF 287M	SHD 1850R
7	MT/0988375-002	SMRT TAXIS	SHB 5737U	SKZ 9804X
8	MT/0991050-002	COMFORT TRANSPORTATION PTE LTD	SHD 6647D	SLM 4176P
9	MT/0991603-001	COMFORT TRANSPORTATION PTE LTD	SH 9594B	SJF 8421R
10	MT/0989297-002	SMRT TAXIS	SHB 5445L	GZ 8719M
11	MT/0989010-002	SMRT TAXIS	SHB 668T	SLV 3014H
12	MT/0988555-002	SMRT TAXIS	SHB 5515T	SLS 2028R
13	MT/0981124-002	SMRT BUSES	SMB 8039Y	SJC 8146B
14	MT/0991610-001	COMFORT TRANSPORTATION PTE LTD	SHC 8728X	GBG 2031L
15	MT/0991074-002	COMFORT TRANSPORTATION PTE LTD	SHC 2948S	GZ 1977E
16	MT/0990979-002	COMFORT TRANSPORTATION PTE LTD	SHD 6658Y	FBK 791T
17	MT/0990696-002	COMFORT TRANSPORTATION PTE LTD	SHD 4138U	PC 2948Y
18	MT/0990960-002	COMFORT TRANSPORTATION PTE LTD	SHD 4928G	YP 6440T

Janice Lee (LKKAuto)

From: Sebastian Yeang (LKK Auto)
Sent: Monday, April 23, 2018 9:33 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team; Leong Chee Kwong
Subject: RE: SHF474P
Attachments: SHF_474_P_ESTIMATE_REPLY.pdf

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,
Sebastian | Automotive Assessor
LKK Auto Consultants
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 17 April 2018 6:41 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team; Leong Chee Kwong
Subject: SHF474P

Hi Sebastian,

Attached herewith the repair estimate of SHF 474P having Case No: TAX/04/18/2017.

There is no change to the approved amount of \$9,200 @ 8 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Tuesday, 17 April 2018 5:31 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/04/2018 10:54
Date Of Accident	03/04/2018 15:45
Exact Location Of Accident	STEVEN ROAD TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF474P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	KOH SEOW HEONG
NRIC No	S7225548H
Date Of Birth	22/07/1972
Occupation	OUTDOOR
Date Of Driving Pass	30/08/1993
Driving Experience	24 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 6-193
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 3
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 4
 NAME: : UNKNOWN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG STEVEN ROAD TOWARDS PIE WITH FOUR PASSENGERS (1 COUPLE /2 CHILDREN-BOY /GIRL) ON BOARD. THE LANE I WAS TRAVELLING ON WAS STRAIGHT AND TURN LEFT. A VEHICLE SKP1761R WHICH WAS ON MY RIGHT ON THE STRAIGHT ONLY LANE, CUT TOWARDS MY LANE AS HE WANTED TO TURN LEFT INTO DRAYCOTT DRIVE. AS SUCH COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKP1761R
 Vehicle Make/Model/Colour
 Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



4/4/2018.

are the foreign

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 11/1/18

4/4/18

✓ 2/4/2018

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, its workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/nailed packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agent(s) including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NOC/TIN No:

4/4/18

2:05pm

4/4/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHF474P
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1439150
Chassis No.:	JTDKN36U705751766
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$28,397.00
Total Rebate Amount:	\$34,463.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Apr 2018

OK

SMRT Accident Vehicle Repair Estimates

C.A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF474P
 Ref. No : TAX/04/18/2017
 Reg. Date : 30/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : KOH SEOW HEONG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 03/04/2018 03:42:00 PM
 Accident Reported Date / Time : 04/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 03/04/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095365
 Special Instruction to ARC, if any :
 TOWED \$40 / SKP1761R
 Prepared Date : 04/04/2018 02:27:47 PM



Sebastian.
5/4/18.
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Paint

9/4/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U705751766

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 3,348.00	0.00
Total Material Charges	: 14,928.01	14,928.01
Other Charges	: 1,970.00	0.00
TOTAL	: 21,598.01	0.00
Lum Sum Total	: 21,600.00	0.00
No. of Repair Days	: 8.00	0.00
Prepared / Adjusted By	:	6 days
Arc / Surveyor Sign Off Date	: 04/04/2018 03:54:30 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/04/2018 03:53:52 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0.00 100
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 50
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY FRONT PILLAR RH	180.00	0.00 100
TO RESPRAY APRON PANEL RH	180.00	0.00 ?
TO RESPRAY FRT MEMBER,RH	180.00	0.00 ?
TO RESPRAY RH REAR DOOR	378.00	0.00 X
TO RESPRAY RIM	180.00	0.00 50
Total Spray Painting & Panel Beating	3,348.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO CHECK & RESET SYSTEM FUNCTION	350.00	0.00 200
TO ALIGN CHASSIS	350.00	0.00 ?
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 ?
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0.00 ?
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO TOP UP A/C GAS	120.00	0.00 ?
Total Other Costs	1,970.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace ✓ CRK	No
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace X	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace ✓ NFE	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ✓ CRK	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ✓ OT	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace ?	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace ?	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace ✓ CRK	No
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace ✓ CRK	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace R	No
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Replace ?	No
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Replace ?	No
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace ✓ SCR	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace ?	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace R	No
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace X	No
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace ✓ OT	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace ?	No
88710-47150			TUBE & ACCESSORY	1	631.90	25.00	473.92	Replace	Replace ?	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace ✓ CRK	No
65319-47120			WIPER WASHER INLET	1	36.90	25.00	27.67	Replace	Replace ?	No
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace ✓ Def for	No
85330-47010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Replace ?	No
85330-60180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Replace ?	No
85371 / 90099-62091			HOSE, WINDSHIELD WASHER (FROM MOTOR TO JOINT)	1	17.60	25.00	13.20	Replace	Replace ?	No
	COMMO N		COOLANT	1	12.32	0.00	12.32	Replace	Replace ?	No
16480-28080			COOLANT RESERVE TANK	1	395.30	25.00	296.47	Replace	Replace ?	No

8227.82

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
16261-37070			RADIATOR HOSE, BYPASS NO.1	1	37.20	25.00	27.90	Replace	Replace ?	No
82111-47772			WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace	Replace ?	No
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.22	Replace	Replace ?	No
51107-12010			SIDE CHASSIC FRT/RH	1	173.50	25.00	130.12	Replace	Replace R	No
5702712010			MEMBER SUB-ASSY, FR RH	1	810.70	25.00	608.02	Replace	Replace ?	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace R ✓ DT X	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ NEC ✓	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace ✓	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓	No
53701-47050			FENDER APRON SUB FRT/RH	1	637.80	25.00	478.35	Replace	Replace ?	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace ✓ TN	No
53851-47040			FENDER LINER PAD, FR WHEEL. RH	1	49.30	25.00	36.97	Replace	Replace X	No
53827-47030			FENDER PROTECTOR FRT/RH SIDE	1	113.90	25.00	85.42	Replace	Replace ?	No
53825-47010			FENDER PROTECTOR FRT/RH UPPER	1	46.10	25.00	34.57	Replace	Replace ?	No
45046-49225			TIE ROD END RH	1	159.30	25.00	119.47	Replace	Replace ?	No
48068-47050			LOWER ARM FRT/RH	1	625.90	25.00	469.42	Replace	Replace ?	No
43330-49185			JOINT ASSY, LWR BALL	1	195.60	25.00	146.70	Replace	Replace ?	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace R	No
61131-47030			PILLAR, FR BODY	1	363.10	25.00	272.32	Replace	Replace R	No
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace R	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓ NEC	No
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace X	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace X	No
TOTAL MATERIALS								18,660.13	18,660.01	
TOTAL MATERIALS(Discounted)							14,928.01	14,928.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

14228-94



Tow + 2 days

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Guar. Attached Supplementary

12-4-18/12:12


12-4-18/16:12

5-4-18/16:12

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF474P
 Ref. No : TAX/04/18/2017
 Reg. Date : 30/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : KOH SEOW HEONG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 03/04/2018 03:42:00 PM
 Accident Reported Date / Time : 04/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 03/04/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095365
 Special Instruction to ARC, if any :



TOWED \$40 / SKP1761R NTUC HS
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121
 LUMPSUM REPAIR

Prepared Date : 04/04/2018 02:27:47 PM

8me

Recording Camera

☐☒

Radio Antenna

☐☒

1st witness

in

Date

5-4-18

2nd witness

Date

E 1/2 F
 KM 264997

Vehicle to Wega Date In: 6/4 Towing: Pay
 Time In: 1500 Driver:
 Wega Job No: 04/0207
 Vehicle sent to SMRT Date In: 4/04 Towing:
 Time In: 1023 Driver: Lyy
 Received by (SMRT):

04/4/18 11.05 P953

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U705751766

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,352.00	1,000.00
Total Spray Painting Charges	3,348.00	1,400.00
Total Material Charges	10,759.12	8,524.74
Other Charges	2,140.00	-1,724.74
TOTAL	17,599.12	9,200.00
Lum Sum Total	0.00	0.00
No. of Repair Days	9.00	8.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	04/04/2018 03:54:30 PM	05/04/2018 04:12:42 PM

F

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/04/2018 03:53:52 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0370

Invoice No :

Quotation Date : 17/4

Invoice Date :

Invoice Amount :

Prepared Date :

$$\begin{array}{r}
 \$8524.72 \\
 + \$1000.00 \\
 + \$1960.00 \\
 \hline
 11,484.72 \\
 - 20\% \\
 \hline
 9187.78
 \end{array}$$

45 \$9200/-

*Sebastian
23/4/18*

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,352.00	1,000.00 /
Total Labour	1,352.00	1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	100.00 /
TO REPSRAY FRONT HOOD	378.00	200.00 /
TO RESPRAY FRONT SUPPORT PANEL	180.00	50.00 /
TO RESPRAY FRONT FENDER LH	378.00	200.00 /
TO RESPRAY FRONT FENDER RH	378.00	200.00 /
TO RESPRAY FRONT DOOR RH	378.00	200.00 /
TO RESPRAY FRONT PILLAR RH	180.00	100.00 /
TO RESPRAY APRON PANEL RH	180.00	100.00 /
TO RESPRAY FRT MEMBER,RH	180.00	0.00
TO RESPRAY RH REAR DOOR	378.00	0.00 /
TO RESPRAY RIM	180.00	50.00 /
Total Spray Painting & Panel Beating	3,348.00	1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 /
TO CHECK & RESET SYSTEM FUNCTION	350.00	200.00 /
TO ALIGN CHASSIS	350.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO TOP UP A/C GAS	120.00	0.00
TO REMOVE AND REFIX UNDERCARRIAGE	250.00	200.00 /
Lump Sum Adjustment by Surveyor	0.00	-2,284.74
Total Other Costs	2,140.00	-1,724.74

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No	✓ CRK
52127-47903			COVER, FR BUMPER HOLE RH	0	18.50	25.00	0.00	Replace	Not given	No	X NW
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No	✓ N/C
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No	✓ CRK
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No	✓ BT
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Check	No	X NW
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Check	No	X NW
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No	✓ GNY
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace	No	✓ CRK
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace	No	✓ MS
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Check	No	X NW
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Check	No	X NW
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace	No	✓ SKR
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78	Replace	Replace	No	✓ Defcon
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Check	No	X NW
53301-47060		6505555	HOOD PANEL	1	748.10	100.00	0.00	Replace	Repair	No	R
53420-47070			HOOD HINGE LH	0	55.90	25.00	0.00	Replace	Not given	No	X NW
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No	✓ BT
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No	✓ BT
88710-47150			TUBE & ACCESSORY	1	631.90	25.00	473.93	Replace	Check	No	X NW
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No	✓ CRK
65319-47120			WIPER WASHER INLET	1	36.90	25.00	27.68	Replace	Replace	No	✓ Defcon
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace	No	✓ Defcon
85330-47010			MOTOR NO.1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Replace	No	✓ MS
85330-60180			MOTOR NO.2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Replace	No	✓ MS
85371 / 90099-62091			HOSE, WINDSHIELD WASHER (FROM MOTOR TO JOINT)	1	17.60	25.00	13.20	Replace	Check	No	X NW
	COMMON		COOLANT	1	12.32	0.00	12.32	Replace	Replace	No	✓ N/C
16480-28080			COOLANT RESERVE TANK	1	395.30	25.00	296.48	Replace	Replace	No	✓ Defcon
16261-37070			RADIATOR HOSE, BYPASS NO.1	1	37.20	25.00	27.90	Replace	Check	No	X NW

4509.42

8265.02

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
82111-47772			WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace	Check	No X
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.23	Replace	Check	No X
51107-12010			SIDE CHASSIS FRT/RH	1	173.50	100.00	0.00	Replace	Repair	No R
5702712010			MEMBER SUB-ASSY, FR RH	1	810.70	25.00	608.03	Replace	Check	No X
53802-47050		6505558	FENDER FRT/LH	1	723.40	100.00	0.00	Replace	Repair	No R
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53701-47050			FENDER APRON SUB FRT/RH	1	637.80	25.00	478.35	Replace	Check	No X
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace	No
53851-47040			FENDER LINER PAD, FR WHEEL, RH	0	49.30	25.00	0.00	Replace	Not given	No X
53827-47030			FENDER PROTECTOR FRT/RH SIDE	1	113.90	25.00	85.43	Replace	Check	No X
53825-47010			FENDER PROTECTOR FRT/RH UPPER	1	46.10	25.00	34.58	Replace	Check	No X
45046-49225			TIE ROD END RH	1	159.30	25.00	119.48	Replace	Check	No X
48068-47050			LOWER ARM FRT/RH	1	625.90	25.00	469.43	Replace	Replace	No S
43330-49185			JOINT ASSY, LWR BALL	1	195.60	25.00	146.70	Replace	Check	No X
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No X
42611-47140 (Frt)		6505658	WHEEL DISC, FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace	No S
61131-47030			PILLAR, FR BODY	1	363.10	100.00	0.00	Replace	Repair	No R
67001-47070		6505528	DOOR FRT/RH	1	894.40	100.00	0.00	Replace	Repair	No R
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
67003-47080		6505486	DOOR RR/RH	0	954.50	25.00	0.00	Replace	Not given	No X
			PIXEL STICKER	0	60.00	0.00	0.00	Replace	Not given	No X
43410-47030			DRIVE SHAFT RH	1	1,764.40	25.00	1,323.30	Replace	Replace	No S
TOTAL MATERIALS							16,811.17	8,524.74		
TOTAL MATERIALS(Discounted)							10,759.12	8,524.74		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
43410-47030		DRIVE SHAFT RH	1	1,764.40	25.00	1,323.30	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						1,323.30			



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006385/Srbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 03-05-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 1761R	Veh. Inspected	SHF 474P
Policy No.	5092256495	Coverage (\$)	0.00
Claim No.	MT/0988974-002	Excess (\$)	0.00
Assign From		Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U705751766	Colour	MAROON
Odometer	264997	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/04/2018	Inspection Date	05/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 474P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER FRT (DISC 25%)	CRACKED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRACKED	78.80	59.10
1	BUMPER REINFORCEMENT FRT (DISC 25%)	BENT	498.40	373.80
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CUT	311.10	233.32
1	FOG LAMP RH (DISC 10%)	CRACKED	295.20	265.68
1	BUMPER SUPPORT F/RH (DISC 25%)	MISSING	76.40	57.30
1	BUMPER FRT ABSORBER LOWER (DISC 25%)	DEFORMED	127.70	95.78
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.92
1	SUPPORT SUB-ASSY (DISC 25%)	BENT	1,460.40	1,095.30
1	WIPER WASHER INLET (DISC 25%)	DEFORMED	36.90	27.68
1	WIPER WASHER JAR (DISC 25%)	DEFORMED	180.10	135.07
1	COOLANT RESERVE TANK (DISC 25%)	DEFORMED	395.30	296.48
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	FENDER FRT/RH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	FENDER LINER FRT/RH (DISC 25%)	TORN	171.70	128.77
1	LOWER ARM FRT/RH (DISC 25%)	BENT	625.90	469.43
1	WHEEL FISC FRONT (DISC 25%)	CUT	1,484.20	1,113.15
1	DRIVE SHAFT RH (DISC 25%)	DAMAGED	1,764.40	1,323.30
1	LENS & BODY, FR TURN RH (DISC 10%)	SCRATCHED	511.80	460.62
1	HEAD LAMP RH (DISC 10%)	CRACKED	945.20	850.68
1	MOTOR NO 1, WIPER WASHER JAR (DISC 10%)	DAMAGED	239.00	215.10
1	MOTOR NO 2, WIPER WASHER JAR (DISC 10%)	DAMAGED	240.00	216.00
1	COOLANT (SN)	NECESSARY	12.32	12.32
1	STICKER DECAL SMRT (DOOR)(SN)	NECESSARY	60.00	60.00
1	COVER FR BUMPER HOLE RH	NOT NECESSARY	18.50	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	BRACKET, FR TURN LOWER RH	NOT NECESSARY	26.00	-

Report Ref No. NS/INC18006385/Srbn2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRACKET,FR TURN UPPER RH	NOT NECESSARY	24.40	-
1	WIRE ENGINE ROOM NO 3	NOT NECESSARY	242.00	-
1	HOOD HINGE LH	NOT NECESSARY	55.90	-
1	TUBE & ACCESSORY	NOT NECESSARY	631.90	-
1	HOSE,WINDSHIELD WASHER (FROM MOTOR TO JOINT)	NOT NECESSARY	17.60	-
1	RADIATOR HOSE,BYPASS NO 1	NOT NECESSARY	37.20	-
1	WIRE ENGINE ROOM	NOT NECESSARY	5,567.10	-
1	RADIATOR LOWER SUPPORT	NOT NECESSARY	876.30	-
1	MEMBER SUB-ASSY FR RH	NOT NECESSARY	810.70	-
1	FENDER LINER PAD,FR WHEEL RH	NOT NECESSARY	49.30	-
1	FENDER PROTECTOR FRT/RH SIDE	NOT NECESSARY	113.90	-
1	FENDER PROTECTOR FRT/RH UPPER	NOT NECESSARY	46.10	-
1	TIE ROD END RH	NOT NECESSARY	159.30	-
1	JOINT ASSY LWR BALL	NOT NECESSARY	195.60	-
1	TYRE	NOT NECESSARY	126.74	-
1	DOOR RR/RH	NOT NECESSARY	954.50	-
1	PIXEL STICKER	NOT NECESSARY	60.00	-
1	HOOD PANEL	TO REPAIR	748.10	-
1	SIDE CHASSIS FRT/RH	TO REPAIR	173.50	-
1	FENDER FRT/LH	TO REPAIR	723.40	-
1	PILLAR,FR BODY	TO REPAIR	363.10	-
1	DOOR FRT/RH	TO REPAIR	894.40	-
1	FENDER APRON SUB FRT/RH	NOT NECESSARY	637.80	-
			24,950.16	8,524.76
	LABOUR			
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		3,232.00	1,520.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		3,448.00	1,440.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			6,840.00	2,960.00
	GRAND TOTAL		31,790.16	11,484.76

Report Ref No. NS/INC18006385/Srbn2



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			9,200.00
--	--	--	----------

Report Ref No. NS/INC18006385/Srbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.