



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

DATE : 5/3/2018

TO : AXA INSURANCE PTE LTLD

ATTN : MOTOR CLAIMS DEPT

OFFICE / MOBILE :

EMAIL ADDRESS :

FROM : GOLDBELL ENGINEERING PTE LTD (PIONEER)

ATTN : CHUA SYASYA

MOBILE/ EMAIL : 8481 4099

FAX NO. :

WORKSHOP : Blk 3 Pioneer Road North #01-24
Singapore 628457.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

VEHICLE NO. : SDW7676K

MODEL NO. : LEXUS GS350 LUXURY AUTO

CHASSIS NO. : JTHBE1BL605008936

ENGINE NO. : 2GR8756555

REG. DATE : 25/5/2012

REF. NO. : GBP/SVC/SALES-

D.O.A. : 25/3/2018

POLICY NO. : GA035706/1

CLAIM TYPE : THIRD PARTY CLAIM

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1		REAR BUMPER	1	\$ 961 901.70
2		REAR BUMPER DIFFUSER	1	\$ 542 478.60
3		REAR BUMPER DIFFUSER GARNISH LHS	1	\$ 231 231.10
4		REAR BUMPER DIFFUSER GARNISH RHS	1	\$ 231 231.10
5		REAR BUMPER FOAM	1	\$ 120 120.70
6		REAR BUMPER REINFORCEMENT	1	\$ 492 492.30
7		REAR BUMPER BRACKET LHS	1	\$ 119 119.20
8		REAR BUMPER BRACKET RHS	1	\$ 119 119.20
9		REAR BOOT	1	\$ 922 922.60
10		REAR BOOT WEATHERSTRIP	1	\$ 211 211.60
11		REAR BOOT HINGE LHS	1	\$ 200 200.00
12		REAR BOOT HINGE RHS	1	\$ 200 200.00
13		REAR BOOT LOCK	1	\$ 982 982.60
14		REAR BOOT STRIKER PLATE	1	\$ 45 45.70
15		REAR BOOT COMPARTMENT END GARNISH	1	\$ 211 211.60
16		REAR BOOT COMPARTMENT TOP GARNISH	1	\$ 331 331.60
17		REVERSE SENSOR	1	\$ 380 380.70

200 s/a

TOTAL : \$ 6,180.30
LESS 10% : \$ 618.03
PARTS TOTAL : \$ 5,562.27

LABOUR CHARGES

1	TO PANEL BEAT & REALIGN VEHICLE REAR DAMAGED AREA.	\$ 800.00 500
2	SPRAY PAINTING ON REAR BOOT, BUMPER & AFFECTED AREA.	\$ 600.00 400

LABOUR TOTAL : \$ 1,400.00

TOTAL AMOUNT (BEFORE GST) : \$ 6,962.27



Certificate No: AJA(S)01/Q1243

Certificate No: AJA013554



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

PREPARED BY : CHUA SYASYA

DATE / TIME : 09/04/18 @ 1050

SURVEYOR : RASUL (LKK)

MOBILE NO. : 96010068

OFFICE FAX NO. :

EMAIL ADDRESS : rasul@lkkauto.com

REPAIR TYPE : PART-BY-PART / LUMPSUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 4 days

REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE
STARS



Certificate No: AJA(S)01/Q1243

Certificate No: AJA013054