



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/03/2018
Vehicle Reg. No.:	SDD5510T	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MITSUBISHI OUTLANDER, 2.4 CVT (A)	Vehicle Reg. Date:	30/01/2015
Vehicle Colour:	BLACK	Chassis No:	JMYXTGF3WZF001573
Engine No:	4B12PG7348		
Odometer:	0 KM		
Paint Type:			
Nett Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	1,732.70
Miscellaneous Items	10.00
Labour	880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,622.70
+ GST 7.00% (S\$)	183.59
Nett Amount (S\$)	2,806.29

This claim is handled by: **KEONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjim 92495745
-wp
22/5/18 1340
2 days
Resurvey after repair
sure (Merimen.com)

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2018)**Parts:** M1-SUV MITSUBISHI OUTLANDER 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SDD5510T)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	de *1,007.00 FN
2	1		*REAR BUMPER SENSOR	0	0.00	X *200.00 FS
3	1		*REAR BUMPER LOWER GARNISH	10.00	0.00	de *646.00 FN
4	10		*REAR BUMPER CLIPS	10.00	0.00	de *50.00 FN
5	1		*REAR BUMPER REINFORCEMENT - TO CHECK	10.00	0.00	-
6	1		*REAR BUMPER REFLECTOR RH - TO CHECK	10.00	0.00	-
7	1		*REAR BOOT - REPAIR	10.00	0.00	X m -
Sub Total (S\$)						1,903.00
- Nett Item Discount on N Items (S\$)						170.30
Total Parts (S\$)						1,732.70

F=Franchise part, S=SpcNett, N=NettItemDisc.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR BOOT, REAR PANEL, REMOVE AND REFIX DAMAGED PARTS. STRAIGHTEN AND REALIGN AFFECTED AREAS	New	200 350.00
2	TO SPRAY AFFECTED AREAS	New	300 500.00
3	TO INSTALL REVERSE SENSOR & CHECK FUNCTION	New	30.00
Gross Labour Cost (S\$)			880.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >