

1552/111

INS. CASE OWNER:

CC 6 / LCR180

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/4

11/4/18

11/4/18

PBC 8856-X; SLR 2201L-X

Email letter to 02

W/L

claimant & repairer same. NO ATA
is requested - BV issue. Please check w
handover.

RECEIVED 16 MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Raymond.

Email

Cal

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

40.00 (S 20 x 2 days)

Loss of Income (LOI):

S\$

(S x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

S\$

Name 1:

Ban Hock Hin Co Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
11/4/18

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: LRC6855at Workshop m/s BHPI

of _____

Insured: SLR2201L

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 800

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 1.5 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

6/4/18 Confirmed finally 27A 30120 with Raymond.Veh No: LRC6855Yr Regn: 6, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamahac.c. 124Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 70593

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LBPKC128080000180

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.75 x 8R: 3.00 - 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 28/3/18D.O.I. 6/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Left.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

(Pd. #249.12
68%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18006408/Uwa3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 06-04-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 2201L	Veh. Inspected	FBC 6865C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/03/2018	Inspection Date	06/04/2018	
Survey held at	BAN HOCK HIN CO. PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32505

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 02/04/2018
CLAIM NO. : 11127
POLICY NO. : AVFMSB0000611801
FROM : RAYMOND

VEHICLE NO. : FBC6865S
MAKE/MODEL : YAM / YBR125

*Not Allowed
1 hr
P/P \$120
2 day,
6/4/18
Take photo After repair*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	2.00	\$35.00	70.00
2	LENS SIGNAL FRONT RH P/N: 26599	REPLACE	1.00	\$12.00	12.00 X
3	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	19.00 X
4	MID WASHER WAVE 90206-06090 P/N: 22565	REPLACE	4.00	\$1.50	6.00 X
5	MIRROR RH P/N: 52701	REPLACE	1.00	\$30.00	30.00 X
6	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	\$32.00	32.00 X
7	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00 X
8	SPRAY PAINT ON CRASH BAR	Spray	1.00	\$50.00	50.00 X
9	SPRAY PAINT ON FRONT cowling fender	Spray	1.00	\$65.00	65.00
10	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00
11	WASHER, PLATE	REPLACE	4.00	\$1.50	6.00 X
12	WASHER, PLATE	REPLACE	4.00	\$1.50	6.00 X

SUB TOTAL

\$345.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 9001: 2008

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL					\$369.15

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018 Edit Reg		06 Apr 2018 00:00 Edit Adj Rpt	S\$120.00 Edit Estimates	S\$120.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	LCRF PTE LTD, Co. Reg. No.: 201604597K		
Main Claimant:	BAN HOCK HIN COMPANY PTE LTD, Co. Reg. No.: 197000288K		
Vehicle Reg. No.:	FBC6865C	Date of Loss:	28/03/2018 00:00 - :59 [117 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2749692925SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLR2201L	Policy No. (Claimant):	AVFMSB0000611700
		Excess:	
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com		
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (09/04/2018): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBC6865C (2749692925SG)
[SLR2201L]**

TP

BAN HOCK HIN COMPANY PTE LTD

Mar 28 2018 12:00AM

[LCRF PTE LTD]

Ban Hock Hin Co. Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▾

Letters/Correspondences			1 per page ▾	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Photos/Images			3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 20:14	General View		Load JPG
2	06/04/18 20:14	General View		Load JPG
3	06/04/18 20:14	General View		Load JPG
4	06/04/18 20:14	General View		Load JPG
5	06/04/18 20:15	General View		Load JPG
6	06/04/18 20:15	General View		Load JPG
7	06/04/18 20:15	General View		Load JPG
8	06/04/18 20:15	General View		Load JPG
9	06/04/18 20:15	General View		Load JPG
10	06/04/18 20:15	General View		Load JPG
11	06/04/18 20:15	General View		Load JPG
12	06/04/18 20:15	General View		Load JPG
13	06/04/18 20:15	General View		Load JPG
14	06/04/18 20:15	General View		Load JPG
15	06/04/18 20:15	General View		Load JPG
16	06/04/18 20:15	General View		Load JPG
17	06/04/18 20:15	General View		Load JPG
18	06/04/18 20:15	General View		Load JPG
19	06/04/18 20:15	General View		Load JPG
20	06/04/18 20:15	General View		Load JPG

Documentation			1 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 23:08	TP ESTIMATE - MARKED		Load PDF
2	09/04/18 23:08	TP GIA REPORT		Load PDF
3	11/04/18 15:43	Email letter to OI ACCIDENT INVOLVING SLR 2201L & FBC 6865C ON 28.03.2018		Load PDF
4	18/05/18 15:38	LETTER TO OI		Load PDF
5	18/05/18 15:38	LTA SEARCH		Load PDF
6	18/05/18 15:38	RELEASE VOUCHER		Load PDF
7	18/05/18 15:38	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/04/18 15:07	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR2201L (Insd veh)	Model:	YAMAHA YBR125 124CC (M)
	FBC6865C (TP veh)		
Date of Accident:	28/03/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	369.15
Final Repair Cost	:	\$	128.40
Loss of Use	:	\$	40.00
Rental (if any)	:	\$	2.00 days at \$20.00 per day
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	175.85

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown

1)	Ban Hock Hin Co. Pte Ltd	:	\$	175.85
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

18 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18006408/UWA3S2
Date: 18/05/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	FBC6865C	Insured Vehicle No :	SLR2201L
Date of Loss:	28/03/2018	Nature of Claim:	TP
		Claim No:	2749692925SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC6865C	Engine No:	E3D6E000414
Make & Model:	YAMAHA YBR125, 124cc (M)	Chassis No:	LBPKE128080000180
Reg. Date:	05/06/2008 (Man. Year: 2008)	Odometer:	70593 km
Colour:	White		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	3.00-18
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	125.00	0.00	125.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	220.00	120.00	100.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	345.00	120.00	225.00	65.22
+ GST 7.00/7.00% (S\$)	24.15	8.40	15.75	65.22
Nett Amount (S\$)	369.15	128.40	240.75	65.22
+ Loss of Use (2.0 x S\$20.00/day) (S\$)		40.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		175.85		

INSPECTION

Date of Assignment:	06/04/2018		Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	06/04/2018	Inspected At:	No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LENS SIGNAL FRONT RH (CRACKED)	Not Consistent With The Impact	12.00 F	*- F
2	1		*LEVER BRAKE (SCRATCHED)	Not Consistent With The Impact	19.00 F	*- F
3	4		*MID WASHER WAVE	Not Necessary	6.00 F	*- F
4	1		*MIRROR RH (CUT)	Not Consistent With The Impact	30.00 F	*- F
5	1		*PROTECTOR MUFFLER (REAR)	Not Necessary	32.00 F	*- F
6	1		*RUBBER FOOTREST FRONT	Not Necessary	14.00 F	*- F
7	4		*WASHER, PLATE	Not Necessary	6.00 F	*- F
8	4		*WASHER, PLATE	Not Necessary	6.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	125.00	0.00
--------------------	--------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR - FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED.	New	70.00	50.00
2	SPRAY PAINT ON CRASH BAR.	New	50.00	0.00
3	SPRAY PAINT ON FRONT FENDER.	New	65.00	35.00
4	TRANSPORT CHARGES (MOTORCYCLE / SCOOTER) STD.	New	35.00	35.00
Gross Labour Cost (S\$)			220.00	120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >