

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg
Our Ref: EST104/18/TP
Your Ref: TP claim against GBF5972G

6-Apr-18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Honda Vezel Hybrid no: SLT7762R

Date of accident: 03-04-2018

Parts supply:

1 pc Tailgate	lets do
1 pc Tailgate inner lock	tw
1 pc Tailgate emblem - VEZEL	new
1 pc Tailgate emblem - HYBRID	new
1 pc Tailgate emblem - H	new
2 pcs Tailgate absorbers @\$223.50	11
2 pcs Tailgate stoppers @\$15.00	11
1 pc Tailgate inner board	re/cor
2 pcs Tailgate hinges @\$75.50	11
1 pc Tailgate centre garnish	new
2 pcs Tailgate rear no. plate lamps @\$38.50	11
1 pc Tailgate outer handle & sensor	
2 pcs Tailgate lamps @\$413.25	u/s new
1 pc Tailgate weatherstrip	tw
1 pc Rear windscreen moulding	new
1 pc Rear reverse camera	shhd
2 pcs Taillamps @\$504.60	o/s new
2 pcs Tailgate clips @\$10.00	11
1 pc Rear bumper	new
1 pc Rear bumper reinforcement	new
2 pcs Rear bumper brackets @\$113.50	11
2 pcs Rear bumper retainers @\$25.90	11
8 pcs Rear bumper clips @\$3.50	new
2 pcs Rear bumper reflectors @\$148.35	11
2 pcs Rear bumper side @\$195.00	new
2 pcs Rear arch garnish @\$189.50	new
1 pc Rear end panel	new
1 pc Rear end panel garnish	tw

S/Nett Items

1 pc Rear no. plate & cover (S/Nett)	new
1 pc Rear windscreen gum (S/Nett)	new
1 set Rear reverse sensor (S/Nett)	shhd

ESTIMATE

Not Authorized
L. K. L.

To be photo taken party.
6/4/18

4 day.
4/5 \$4600

SS	1,100.90	—
	76.60	—
	32.90	—
	75.50	—
	28.50	—
	447.00	X
	30.00	X
	298.50	2
	151.00	+
	189.95	2
	77.00	X
	175.50	X
	826.50	7pc
	135.80	—
	73.80	—
	597.35	3005. Net
	1,009.20	1pc
	20.00	X
	762.70	—
	253.50	X
	227.00	X
	51.80	X
	28.00	✓
	296.70	X
	390.00	X
	379.00	7pc
	415.60	—
	122.30	—
	8,272.60	—
Less 20%:	(1,654.52)	—
	4448.4	—
	3558.72	—
	45.00	40
	40.00	✓
	250.00	200
	6,953.08	—

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Honda Vezel Hybrid no: SLT7762R

Date of accident: 03-04-2018

Parts supply:

Balance b/f:

S\$ 6,953.08

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove and refit rear windscreen

To remove and refit rear reverse sensor

To remove and refit rear reverse camera

To apply underseal

To check wirings.

1,000.00 600

1,100.00 800

120.00 ✓

60.00

60.00 50

80.00 30

30.00 20

S\$ 9,403.08

575872
4606

Let Auto Consultants hence notify

the insurer of the following:

- To resurvey to include after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: