

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5979H**AAD1804-043***Not Notified*
L1Pm @ 3950

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5979H

VF1ABL15AUC281167

RENAULT

LATITUDE

3.4.2018

*Alh***PART****LIST**

1	HEADLAMP LH	\$	<i>Sh</i> 1,184.43 <i>X</i>
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 <i>X</i>
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>D</i> 278.84 ✓
1	FENDER BRACKET LOWER LH	\$	<i>Sh</i> 15.79 <i>X</i>
1	FENDER INSULATOR LH	\$	<i>Sh</i> 130.84 <i>X</i>
1	DOOR PANEL FRT LH	\$	<i>B</i> 2,844.66 ✓
1	DOOR HINGE UPPER LH L70Y	\$	<i>R</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>Sh</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>R</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sh</i> <i>R</i> 477.76 <i>X</i>
1	DOOR HANDLE COVER FRT LH	\$	<i>Sh</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sh</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>R</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sh</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sh</i> 120.97
1	DOOR MIRROR ASSY LH	\$	<i>Sh</i> 1,483.40

\$ 10,717.7310% **\$ 1,071.77****\$ 9,645.96****Specical Nett**

1SET	BUMPER CLIP FRT	\$	<i>Sh</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT LH	\$	<i>Sh</i> 12.00 <i>X</i>
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>Sh</i> 10.50 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1804-043**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5979H

1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60.00
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	15.00

TOTAL	\$	438.00
--------------	-----------	---------------

TOTAL PARTS	\$	10,083.96
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,450.00	500
Putty and spray painting of the affected portion.	\$	2,200.00	660
To rust-proofing of the affected areas.	\$	170.00	80
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD1804-043

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5979HTo vacuum, replace, refix and recharge Air Intercooler \$ ~~170.00~~ X**TOTAL** \$ 6,860.00**Over All Total** \$ 16,943.96**PART BY PART (REPAIR DAY)**~~2~~ DAYS

3 days