

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 1508 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, lhs headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 ✓ 1000. ✓	
3	To respray front bumper and bonnet.	\$ 1,500.00 ✓ 1100 ✓	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓ ✓	
TOTAL LABOUR CHARGES		: \$ 4,152.00	