

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0413/2018/CCS
Date : 04-Apr-18

Vehicle NOT IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tey Su Min, June
Address : 30 Eastwood Rd
#04-05
Singapore 486365
Telephone : HP +65 90468240
Type of Claim : Own Damage Claims
Policy No. : 2100301745-05000
Vehicle No : **SKB 1508 E**
Model Code : Audi A1 SB 1.4 TFSI
Model / Year : May-12
Engine No : CAX A93994
Chassis No : WAUZZZ8X4CB225485
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 04-Apr-18
Place of Accident : Bayshore exit towards ECP

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 1508 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, lhs headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1000.	
3	To respray front bumper and bonnet.	\$ 1,500.00 1100	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>4,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 1508 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repld.</i>	\$ 1,336.00	✓
2	FRONT BUMPER SPOILER <i>Repld</i>	\$ 165.00	✓
3	RADIATOR GRILLE <i>Curled</i>	\$ 501.00	✓
4	FRONT BUMPER GRILLE - LH/RH <i>2 new</i>	2 \$ 368.00	+
5	FRONT BUMPER CLOSING ELEMENT	\$ 143.00	+
6	FRONT REINFORCEMENT BEAM ?	\$ 605.00	?
7	FRONT BUMPER SUPPORT - LH/RH ?	2 \$ 22.00	?
8	HEADLIGHT - LH ?	\$ 1,705.00	?
9	HEADLIGHT MOUNTING - LH ?	\$ 92.00	?
10	HEADLIGHT WASHER CYLINDER - LH <i>new</i>	\$ 123.00	+
11	BONNET <i>Dented</i>	\$ 1,943.00	✓
12	BONNET CATCH HOOK - TOP <i>new</i>	\$ 57.00	+
13	BONNET LOCK BAR <i>new</i>	2 \$ 87.00	+
14	BONNET CATCH HOOK - BOTTOM <i>new</i>	\$ 55.00	+
15	BONNET LOCK <i>new</i>	2 \$ 376.00	+
16	SIGN ' CAUTION ' STICKER <i>new</i>	\$ 12.00	✓
17	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 33.00	✓
18	FRONT NO. PLATE <i>Bent</i>	S/N \$ 25.00	✓
19	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 7,948.00	
TOTAL LABOUR CHARGES		: \$ 4,152.00	
GRAND TOTAL		: \$ 12,100.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 06/04/18
Authorised Date :
Excess Cost :
Liability :
Remarks : NP Authorised, 05 Rys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant