

REPAIR ESTIMATE*

VEHICLE NO : SHD 4223G

DATE 6/4/2018 10:47

MAKE :

Jumani

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>X repair</i>			\$ 538.80	
	Front Bumper Bracket (RH) <i>X sc</i>			\$ 20.10	
	Frt Wheel Hub Cap, RH <i>X sc</i>			\$ 145.00	
	<i>Front RH Fender X repair</i>				
	SUB TOTAL			\$ 703.90	
	LESS 20%			\$ 140.78	
	DISCOUNTED TOTAL			\$ 563.12	
	Front Fender Advertisement Logo (RH) <i>/ m</i>			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge				
	Panel Beating-Repair Frt RH Fender			\$ 250.00 <i>200</i>	
	Spray Painting Charge			\$ 500.00 <i>400</i>	
	FRT Wheel Alignment			\$ 120.00 <i>X m</i>	
	TOTAL LABOUR			\$ 870.00	
	ESTIMATE TOTAL			\$ 1,533.12	

Kali 11/11/11

6/4/18 1525hr

2 Rty

4/5

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.