

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8531P

DATE 6/4/2018 10:58

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille / on			\$ 1,480.00
	Radiator Grille H Emblem X 12			\$ 290.80
	Radiator Grille Chrome Moulding X 12			\$ 395.50
	Front Bumper Cover / Panel			\$ 1,052.20
	Front Bumper Sponge / kn			\$ 142.20
	Front Bumper Reinforcement / Bolt			\$ 526.10
	Front Bumper Bracket Top (RH) X 500			\$ 22.40
	Front Bumper Bracket (RH) X 500			\$ 24.60
	Headlamp Support Panel Assy X 500			\$ 1,067.50
	Headlamp (RH) X 500			\$ 1,388.00
	Radiator Guard, RH X 500			\$ 35.00
	SUB TOTAL			\$ 6,424.30
	LESS 20%			\$ 1,284.86
	DISCOUNTED TOTAL			\$ 5,139.44
	Labour Charge			300
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 250.00 200
	Wiring Charge			\$ 50.00 X 20
	Remove/Refix Aircon & Refill Gas			\$ 150.00 X 20
	TOTAL LABOUR			\$ 1,450.00
	ESTIMATE TOTAL			\$ 6,589.44
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

AXA

Jumani

P1

REPAIR ESTIMATE*

VEHICLE NO : SH 8531P

DATE 6/4/2018 11:00

MAKE :

MODEL : HYUNDAI i40

P2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Licence Lamp Holder <i>X</i>			\$ 100.00
	Rear Bumper <i>Return</i>			\$ 603.60
	Rear Bumper Reinforcement <i>X</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X</i>	\$	180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X</i>	\$	49.00	\$ 98.00
	Rear Bumper Clips <i>new</i>			\$ 22.00
	Rear Bumper Sponge <i>tm</i>			\$ 143.40
	Rear Bumper Under Cover <i>del</i>			\$ 225.00
	SUB TOTAL			\$ 2,056.35
	LESS 20%			\$ 411.27
	DISCOUNTED TOTAL			\$ 1,645.08
	Rear No.Plake <i>cm</i>			\$ 25.00
	Rear Bumper Reverse Sensor <i>skhd</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>ne</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>ne</i>	\$	100.00	\$ 200.00
				\$ 410.70
	Labour Charge			<i>200</i>
	Panel Beating			\$ 250.00
	Spray Painting Charge			\$ 500.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>Xm</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 920.00
	ESTIMATE TOTAL			\$ 2,975.78

Kalua (1/1/12)

6/4/18 1535h

4 Days

P/P

Before Part p4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.