

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1461K

DATE 6/4/2018 10:37

MAKE :

MODEL : HYUNDAI IONIC

LICK

A14

Qty	Parts Description/ Labour	Type	Unit Price	
	Boot Lid Hyundai Plate ✓ Boot Lid 'H' Emblem ✓ Boot Lid CRDI Plate ✓ Rear Bumper ✓ Rear Bumper Reinforcement ? Rear Bumper Clip ✓ Rear Bumper Sponge ? Rear Bumper Under Cover ✓			
	SUB TOTAL			\$ -
	LESS 20%			\$ -
	DISCOUNTED TOTAL			\$ -
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Rear No. Plate ✓			\$ 25.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
				\$ 190.70
	Labour Charge			
	Panel Beating- Repair Bootlid			\$ 500.00 ³⁰⁰
	Spray Painting Charge			\$ 500.00 ⁴⁰⁰
	Wiring Charge			\$ 50.00 ^X
	Tuff Kote			\$ 50.00 ^X
	Remove/Refix Reverse Sensor			\$ 120.00 ²⁰
	TOTAL LABOUR			\$ 1,220.00
	ESTIMATE TOTAL			\$ 1,410.70
<p> <i>Kalvin 11/11/18</i> <i>6/4/18 1130 hrs.</i> <i>2 days</i> <i>PIP</i> <i>Before part p 40</i> </p> <div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____</p> </div> <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				