

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/FWD18006452/AGA3Q2**Date:** 27/08/2020REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2017-00000429
Claimant
Vehicle No : ES933Z **Insured Vehicle No :** FBK9112U
Date of Loss: 30/03/2018 Nature of Claim: TP Claim No: 1201800004237

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **ES933Z**
Make & Model: TOYOTA ALPHARD, 2.4 S (A) Engine No: HIDDEN
Reg. Date: 01/11/2013 (Man. Year: 2013) Chassis No: ANH208301501
Colour: Black Odometer: 284766 km
Engine Capacity: 2362 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	1,444.82	1,214.82	230.00	15.92	
Miscellaneous Items	0.00	0.00	0.00		
Labour	610.00	490.00	120.00	19.67	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	2,054.82	1,704.82	350.00	17.03	
Approved Total (Overridden) (S\$)		1,350.00			
	(S\$)	2,054.82	1,350.00	704.82	34.30
	+ GST 7.00/7.00% (S\$)	143.84	94.50	49.34	34.30
	Nett Amount (S\$)	2,198.66	1,444.50	754.16	34.30
	Global Sum Settlement (S\$)		900.00		

INSPECTION

Date of Assignment: 06/04/2018
Date Inspected: 06/04/2018 Inspected At: Cruise Autocare Pte Ltd
53 UBI AVE 1 PAYA UBI IND. PARK
#03-53
Singapore 408934
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)
Parts: M1-MPV	TOYOTA ALPHARD 2.4 S (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for ES933Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	680.70 FL	*680.70 FL
2	1		*FRONT BUMPER RETAINER ,RH	Necessary	112.40 FL	*112.40 FL
3	1		*SPORT RIM	Cut	550.00 FS	*400.00 FS
4	1		*TYRE 235/50 R18	Punctured	300.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,643.10	1,413.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	198.28	198.28
Total Parts (\$\$)	1,444.82	1,214.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE	New	80.00	60.00
2	LABOUR TO REMOVE DAMAGED PARTS ,ALIGN AND REPLACE PARTS	New	200.00	150.00
3	CONDUCT FRONT WHEEL ALIGNMENT	New	80.00	80.00
4	SPRAY PAINTING ON	New	250.00	200.00
			Gross Labour Cost (\$\$)	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >