

GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BP 3645** Page No. : 1 of 2

Date Estimated : 09/04/2018

Prepared By : Wong Guo Xiang

- ESTIMATE REPAIR FOR - T Ramanan S/o M Thiruchittampalam 141 Lorong Ah Soo #10-265 Singapore 530141	- ACCOUNT - CASH - Sale service 2000
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2429C	VF3LPNHWGS259197	30/06/2017	3081.2 Allure17	0

DESCRIPTION	VALUE
SUNDRIES	36 150.00
TO REPLACE / REPAIR FRT BUMPER FRT PANEL,FRT BONNET,FRT LHS FENDER,FRT RHS FENDER	1800 3,000.00
RESPRAY FRT BUMPER,FRT BONNET, FRT LHS FENDER,FRT RHS FENDER	2400 3,000.00
WIRING CONNECTION & CHECK (NETT)	150.00
REMOVE & REPLACE RADIATOR INCLUDING BLEEDING,PRESSURE TEST & CHECK LEAKAGE (NETT)	7 600.00
REMOVE & REPLACE A/C CONDENSER INCLUDING REFILL A/C GAS, PRESSURE TEST & CHECK LEAKAGE (NETTa)	7 600.00
REMOVE & REPLACE FRT HEADLAMP SYSTEM INCLUDING REALIGN HEADLAMP BEAM LEVEL	200.00
TO REMOVE & REPLACE FRT PARKING SENSOR (NETT)	150.00
TUFF KOTE @ \$60 PER PANEL (NETT)	60 2400.00
SEALANT FOR FRT BONNET @ \$90	90.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK INCLUDING CLEAR FAULT CODE (NETT)	600.00
Total Labour 1:	8,780.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610742580	FRT BUMPER	1	700.00	10.00	DE 630.00
1610742980	RECESS DOOR FRT	1	33.00	10.00	X 29.70
1610745580	FRT BUMPER F-LAMP MOULDING	1	150.00	10.00	NE 135.00
1610745180	FRT BPR CTRL GRILLE BRACKET	1	224.00	10.00	CA 201.60
1610745680	GRILLE MOULDING	1	100.00	10.00	CA 90.00
1610745880	RADIATOR GRILLE FRAME MDLG	1	240.00	10.00	CA 216.00
1610746780	FRT BUMPER ABSORBER	1	45.00	10.00	DE 40.50
1610746880	DETECTOR SENSOR SUPPORT SET	1	91.00	10.00	NE 81.90
9800498680	FRT GUARD GRILLE	1	141.00	10.00	X 126.90
1623159580	BRACKET SET	1	60.00	10.00	X 54.00

JTOFRANCE

Division of Vantage Automotive Limited)
 Jishess Registration No. 52907220C GST Registration No. M2-0000551-1
 405 Alexandra Road
 168942, Singapore
 Tel : 6376 2288
 Fax : 6477 7373



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : BP 3645
 Date Estimated : 09/04/2018
 Prepared By : Wong Guo Xiang

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ2429C	VF3LPHNYWGS259197	30/06/2017	3081.2 Allurel7	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610745980	FRT BUMPER LWR MOULDING	1	168.00	10.00	X 151.20
1610758980	FRT BUMPER C-FINISHER	1	146.00	10.00	X 131.40
1610761380	FINISHER BUMPER	1	65.00	10.00	X 58.50
9805083080	FRT BUMPER PLUG	1	60.00	10.00	X 54.00
1610761480	SET PROXIMITY SENSOR SUPPORTS FRT	1	68.00	10.00	na 61.20
98039139XT	FRT BUMPER TOP RANGE	1	45.00	10.00	X 40.50
96773637XT	FRT BUMPER RANGE	1	68.00	10.00	ca 61.20
9677378580	FRT BPR REINFORCEMENT	1	280.00	10.00	bt 252.00
1612686380	MKT LWR FRT BPR PANEL FIXINGS	1	61.00	10.00	na 54.90
9816603980	FRT FACE TOP CROSSMEMBER	1	150.00	10.00	135.00
9802164380	FRT FENDER LH	1	321.00	10.00	R 288.90
9802164280	FRT FENDER RH	1	321.00	10.00	R 288.90
9678591980	FRT WING ACCOUSTIC SEAL LH	1	78.00	10.00	X 70.20
9678591880	FRT WING ACCOUSTIC SEAL RH	1	78.00	10.00	X 70.20
9802163180	ENGINE BONNET - ALUM	1	750.00	10.00	bt 675.00
9677784880	BONNET HINGE LH	1	40.00	10.00	bt 36.00
9677784980	BONNET HINGE RH	1	40.00	10.00	bt 36.00
1618000680	HEADLAMP ASSY LH	1	1,330.00	10.00	ca 1,197.00
1618000780	BARE HEADLAMP RH, ADD DRIVER KIT	1	1,330.00	10.00	X 1,197.00
9675747980	RADIATOR ASSY	1	605.00	10.00	7 544.50
9816746580	CONDENSER	1	690.00	10.00	7 621.00

Total Parts : 7,630.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,780.00
Parts	:	7,630.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,148.71

Customer Service Officer

Contact