

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9453B**AAD1804-059***Not Attached
11 Sep 8 3650h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9453B

KL1LA69RJBB064810

CHEVROLET

EPICA 2.0

4.4.2018

EQ**PART****LIST**

1	1	Front Shock Absorber Assy LH	\$	SH 216.17 X
2	1	Front Shock Absorber Top Mounting LH	\$	SH 48.32 X
3	1	Front Lower Arm LH	\$	SH 283.00 X
4	1	Front Knuckle Arm LH	\$	SH 230.00 X
5	1	Front Hub Unit	\$	SH 376.00 X
6	1	Front Fender LH	\$	R 837.60 ✓
7	1	Front Fender Liner LH	\$	DR 47.00 ✓
8	1	Fender Insulation LH	\$	SH 39.00 X
9	1	Front Fender RR Bracket LH	\$	R 7.10 X
10	1	Front Fender Inner Wheel House Panel LH	\$	R 1,437.00 X
11	1	Front Door LH	\$	R 1,133.00 ✓
12	1	Front Door Glass Guide LH Chrome Moulding	\$	SH 60.00 X
13	1	Front Door Outer Moulding	\$	SH 220.00 X
14	1	Front Door Outer Handle	\$	SH 125.00 X
15	1	Front Door Handle Support	\$	SH 3.00 X
16	1	Front Door outer handle inner seal	\$	SH 89.15 X
17	1	Front Door outer key lock	\$	SH 25.00 X
18	1	Front Door Hinge Upper	\$	R 65.00 X
19	1	Front Door Hinge Lower	\$	R 65.00 ✓
20	1	Front Door inner lock	\$	R 586.00 X
21	1	Front Door Inner Lock Latch LH	\$	R 206.00 X
22	1	Front Door Check / Arrestor	\$	SH 67.50 X
23	1	Front Door Weatherstrip LH	\$	SH 138.79 X
24	1	Front Door glass channel weatherstrip	\$	SH 160.00 X
25	1	Front Door inner trim board	\$	SH 455.69 X
26	1	Front Door window glass	\$	SH 456.12 X
27	1	Front Door Power Window Motor (Master) LH	\$	SH 284.97 X
28	1	Front Door power window motor switch	\$	SH 145.00 X

Trans-cab Auto Services Pte Ltd

AAD1804-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9453B

29	1	Front Door Window Regulator Gear LH	\$	Sn	84.58X
30	1	Front Door Outer Pillar Panel LH	\$	N	715.00 X
31	1	Front Door Pillar Inner Panel LH	\$	N	850.00 X
32	1	Front Door Center Pillar Panel LH	\$	N	698.15 X
33	1	Front Side View Mirror LH	\$	Sn	1,191.00 X
34	1	Rear Door LH (Panel A-RR DR LH)	\$	N	1,133.00 ✓
35	1	Rear door weatherstrip - Inner	\$	Sn	41.40
36	1	Rear door weatherstrip - 2nd Frame	\$	Sn	25.90
37	1	Rear door top hinge	\$	N	35.00
38	1	Rear door bottom hinge	\$	N	35.00
39	1	Rear door inner lock	\$	N	425.00
40	1	Rear door check / arrestor	\$	Sn	65.00 X
41	1	Rear door lock striker / latch	\$	Sn	120.00
42	1	Rear door outer weatherstrip moulding	\$	Sn	85.00
43	1	Side Rocker Panel Garnish LH	\$	N	236.40
44	1	Rear Fender LH	\$	N	1,145.00
45	1	Rear Fender Inner Trim LH	\$	Sn	418.44
46	1	Front Side Rocker Panel Outer LH	\$	N	600.00
47	1	Front Side Rocker Panel Inner LH	\$	N	519.30

TOTAL	\$	16,229.58
10%	\$	1,622.96
	\$	14,606.62

Special Nett

1 Set	Front Bumper Fastener Clip	\$	24.00	X
1 Set	Front licence plate with holder	\$	192.00	X
1 Set	Radiator Grille clip	\$	35.00	X
1 Set	Front Fender Liner clip	\$	30.00	✓
1Set	Rear Fender Inner Trim Clip LH	\$	30.00	X
TOTAL		\$	783.30	

TOTAL PARTS	\$	16,917.10
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9453B**AAD1804-059****LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	501
Putty and spray painting of the affected portion.	\$	3,200.00	801
Towing Fees.	\$	na 120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To rust-proofing of the affected areas.	\$	170.00	701
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201
To transfer of fender fittings, attachment and perform water seepage test.	\$	na 170.00	X

TOTAL \$ 8,660.00**Over All Total \$ 25,577.10****10 Days****4 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from LKK Auto Consultants

Repair Days

Acknowledged by Repairer
Signature:
Date: