

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9920U****AAD1804-057***Not Authaird  
61 Sng 83200h*

|                       |                   |
|-----------------------|-------------------|
| Vehicle No.:          | <b>SHD 9920U</b>  |
| Chassis No.:          | VF1ABL15AUC277504 |
| Vehicle Make:         | RENAULT           |
| Vehicle Model:        | LATITUDE          |
| Date of Accident :    | 4.4.2018          |
| Third Party Insurer : | <b>III</b>        |

| PART |                                 | LIST |                        |
|------|---------------------------------|------|------------------------|
| 1    | BUMPER COVER FRT                | \$   | <i>mgem</i> 1,259.42 ✓ |
| 1    | BUMPER SPOILER FRT              | \$   | <i>SL</i> 181.75 X     |
| 1    | BUMPER ABSORBER FRT             | \$   | <i>SL</i> 394.68 X     |
| 1    | BUMPER RETAINER FRT LH          | \$   | <i>SL</i> 151.41 ✓     |
| 1    | BUMPER SUPPORT FRT              | \$   | <i>SL</i> 123.88 X     |
| 1    | BUMPER RETAINER FRT RH          | \$   | <i>DIV</i> 150.77 ✓    |
| 1    | BUMPER SUPPORT FRT              | \$   | <i>SL</i> 123.88 X     |
| 1    | BUMPER UNDERTRAY FRT            | \$   | <i>SL</i> 472.83 X     |
| 1    | BUMPER GRILLE LOWER FRT         | \$   | <i>SL</i> 266.80 X     |
| 1    | BUMPER FOG LAMP GRILLE RH       | \$   | <i>SL</i> 207.21 X     |
| 1    | BUMPER BEAM FRT                 | \$   | <i>R</i> 914.08 X      |
| 1    | HEADLAMP RH                     | \$   | <i>mgem</i> 1,184.43 ✓ |
| 1    | HEADLAMP PANEL FRT RH           | \$   | <i>R</i> 152.15 X      |
| 1    | FENDER PANEL FRT RH             | \$   | <i>R</i> 783.83 ✓      |
| 1    | WHEELARCH FRT RH                | \$   | <i>SL</i> 278.84 X     |
| 1    | FENDER BRACKET LOWER RH         | \$   | <i>SL</i> 15.79 X      |
| 1    | FENDER INSULATOR RH             | \$   | <i>SL</i> 130.84 X     |
| 1    | DOOR PANEL FRT RH               | \$   | <i>R</i> 2,844.66 X    |
| 1    | RADIATOR GRILLE                 | \$   | <i>SL</i> 1,707.78 X   |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' | \$   | <i>SL</i> 225.36 X     |
| 1    | RADIATOR GRILLE FRAME           | \$   | <i>SL</i> 1,353.75 X   |
| 1    | RADAITOR FAN COWLING            | \$   | <i>SL</i> 820.54 X     |
| 1    | RADIATOR FAN MOTOR LH           | \$   | <i>SL</i> 967.36 X     |
| 1    | RADIATOR FAN MOTOR RH           | \$   | <i>SL</i> 1,479.46 X   |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>16,191.51</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,619.15</b>  |
|              | <b>\$</b> | <b>14,572.36</b> |

**Trans-cab Auto Services Pte Ltd**

AAD1804-057

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9920U

**Specical Nett**

|      |                                |    |       |     |
|------|--------------------------------|----|-------|-----|
| 1SET | BUMPER CLIP FRT                | \$ | 66.00 | ✓   |
| 1    | BUMPER BRACKET CLIP FRT RH     | \$ | 12.00 | } X |
| 1    | BUMPER SUPPORT CLIP FRT RH     | \$ | 10.50 |     |
| 1SET | BUMPER GRILLE LOWER CLIP       | \$ | 69.00 |     |
| 1SET | FRAME FULL SUPPORT PANEL CLIP  | \$ | 70.00 |     |
| 2    | FRAME FULL SUPPORT PANEL NUT   | \$ | 20.00 |     |
| 2    | FRAME FULL SUPPORT PANEL STUD  | \$ | 30.00 |     |
| 1SET | WHEELARCH CLIP FRT RH          | \$ | 30.50 |     |
| 1    | FRONT DOOR STICKER 'Trans-cab' | \$ | 80.00 |     |
| 1    | FRONT DOOR STICKER 'Chassis'   | \$ | 50.00 |     |

|              |           |               |
|--------------|-----------|---------------|
| <b>TOTAL</b> | <b>\$</b> | <b>438.00</b> |
|--------------|-----------|---------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>15,010.36</b> |
|--------------------|-----------|------------------|

**LABOUR**

|                                                                                                                           |    |          |     |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|-----|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 3,500.00 | 400 |
| Putty and spray painting of the affected portion.                                                                         | \$ | 3,000.00 | 440 |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00   | 30  |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00   | X   |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00   | X   |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | 170.00   | X   |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00   | 20  |

**Trans-cab Auto Services Pte Ltd****AAD1804-057**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9920U**

|                                                                                  |    |        |   |
|----------------------------------------------------------------------------------|----|--------|---|
| To transfer of front fender fittings, attachment and perform water seepage test. | \$ | 380.00 | X |
| To vacuum, replace, refix and recharge air condenser                             | \$ | 380.00 | X |
| To replace, refix and top up coolant for radiator                                | \$ | 170.00 | X |
| To vacuum, replace, refix and recharge Air Intercooler                           | \$ | 170.00 | X |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>8,710.00</b> |
|--------------|-----------|-----------------|

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>Over All Total</b> | <b>\$</b> | <b>23,720.36</b> |
|-----------------------|-----------|------------------|

**LUMP SUM (REPAIR DAY)**~~10 DAYS~~

2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: