

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0705/2018  
DATE : 27-MAR-2018

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
S(079120)  
TEL : 91007211  
FAX :

OWNER'S NAME : TEE KOK LIAN  
ADDRESS : APT BLK 747 WOODLANDS CIRCLE  
#11-702  
S(730747)  
TELEPHONE NO : 91270740

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 1700022097  
VEHICLE NO : SLQ2147R  
MODEL CODE : BS9BKLC  
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT  
ENGINE NO : FB25Y526090  
CHASSIS NO : JF2BS9KC2GG046434  
MILEAGE : 1 KM  
DATE IN : 27/03/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : KUAN WEI LOONG\*\*  
ACCIDENT DATE : 25/03/2018

Print Date : 27/03/2018  
Print Time : 20:15:50

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLQ2147R

| S/NO                 | JOB CODE | NATURE OF JOB                                                                         | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|----------------------|----------|---------------------------------------------------------------------------------------|----------------------|------------------------------|
| 1                    | TPCLAIM  | CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)                                           |                      |                              |
| 2                    | ZZ/001   | CONDUCT TP CLAIM AIG LOCATION:301 UPPER THOMSON<br>ROAD DATE:25/03/2018 TIME:1255 HRS |                      |                              |
| 3                    | ZZ/002   | REPAIR/REPLACE FRONT BUMPER AND FRONT PANEL                                           | 750.00               | 240                          |
| 4                    | ZZ/003   | RESPRAY FRONT BUMPER AND FRONT PANEL                                                  | 600.00               | 400                          |
| 5                    | ZZ/004   | TO CONDUCT FRONT LIGHTING TEST                                                        | 28.00                | ✓                            |
| 6                    | ZZ/005   | TO CONDUCT FRONT PROTECTANT COATING                                                   | 250.00               | 150                          |
| 7                    | ZZ/006   | REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING                                           | 125.00               | 30                           |
| 8                    | ZZ/007   | SUNDRIES                                                                              | nn 100.00            | 7                            |
| TOTAL LABOUR CHARGES |          |                                                                                       | 1853.00              |                              |

MOTORIMAGE ENTERPRISES PTE. LTD.  
 19 LORONG 8, TOA PAYOH  
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ2147R

| DAMAGED PARTS & PRICES        |                               |              |         |      |                      |                |
|-------------------------------|-------------------------------|--------------|---------|------|----------------------|----------------|
| S/NO                          | PARTS DESCRIPTION             | PARTS NUMBER | NETT    | LIST | S/NETT               | S/LIST REMARKS |
| 1                             | RAD PNL COMPL RPR             | 53029AL1219P |         |      | <i>R</i> 601.20      | <i>X</i>       |
| 2                             | FENDER F LH                   | 57120AL0709P |         |      | <i>R</i> 270.00      | <i>X</i>       |
| 3                             | BUMPER PUNCHING F OBK FOR H/W | 57702AL110   |         |      | <i>CM</i> 594.00     | <i>✓</i>       |
| 4                             | ENR ABSORB FOAM FEXP          | 57705AL050   |         |      | 57.60                | <i>?</i>       |
| 5                             | ENR ABSORB CTR F FHI          | 57705AL071   |         |      | 35.10                | <i>?</i>       |
| 6                             | BRKT SD F RH                  | 57707AL081   |         |      | <i>SL</i> 18.00      | <i>X</i>       |
| 7                             | BRKT SD F LH                  | 57707AL091   |         |      | <i>SL</i> 18.00      | <i>X</i>       |
| 8                             | BEAM COMPL F EU               | 57711AL0119P |         |      | 288.00               | <i>?</i>       |
| 9                             | COVER HOOK F OBK FHI          | 57731AL170   |         |      | <i>SL</i> 5.40       | <i>X</i>       |
| 10                            | LAMP ASSY HEAD RLA            | 84002AL010   |         |      | <i>mg CM</i> 1870.00 | <i>✓</i>       |
| 11                            | FOG LAMP ASSY F               | 84501AJ060   |         |      | 272.00               | <i>?</i>       |
| 12                            | NOZZLE H L WASHERLH           | 86636AL021   |         |      | 90.00                | <i>?</i>       |
| 13                            | NOZZLE COVER ASSYOBL          | 86636AL080EN |         |      | 54.00                | <i>?</i>       |
| SUB TOTAL                     |                               |              | 0.00    | 0.00 | 0.00                 | 4173.30        |
| LESS DISCOUNT ( S/LIST-30 % ) |                               |              | 0.00    | 0.00 | 0.00                 | 1251.99        |
| GRAND TOTAL                   |                               |              | 0.00    | 0.00 | 0.00                 | 2921.31        |
| OVERALL TOTAL                 |                               |              | 2921.31 |      |                      |                |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLQ2147R

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 1853.00   |
| TOTAL SPARE PARTS CHARGES | 2921.31   |
| GRAND TOTAL               | 4774.31 * |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |        |
|-----------------|--------|
| NAME            | :      |
| SURVEYED DATE   | :      |
| AUTHORIZED DATE | :      |
| EXCESS CLAUSE   | : 0.00 |
| LIABILITY       | : 0.00 |
| REMARKS         | :      |

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Authorise*  
*1.B.1*  
*Resurvey B4 paint*  
*2-3 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: