



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHEN YUANWEI EZEKIEL
BLK 226A SUMANG LANE
#17-214
SINGAPORE 821226

Estimate No: MCS1102368
Date: 06 Apr 2018
Policy No: PNPV2017-00006319
Veh Reg No: SLG3007H
Make/Model: HONDA VEZEL 1.5X
CVT A

ATTN:

Your Ref No: SLG3007H
Claim Type: Third Party
Accident Date: 05/04/2018
TP Veh Reg No: SKC2321P

*Not with claim
1.B.1
Runway B4 paint 4 days*

Estimate Repair Cost to Vehicle No :SLG3007H

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 TAILGATE	1 PC	953.30	✓
2 TAILGATE LOGO - VEZEL	1 PC	45.80	✓
3 TAILGATE RUBBER SEAL	1 PC	104.40	X
4 REAR BUMPER	1 PC	508.50	✓
5 REAR BUMPER SIDE RETAINER - LH & RH	2 PC	55.00	X
6 REAR BUMPER CLIP	10 PC	35.00	✓
7 REAR BUZZER	1 PC	110.10	?
8 REAR WINDSCREEN MOULDING	1 PC	138.60	✓
9 REAR BOOT LOCK	1 PC	76.60	X
		2,027.30	
	Less 20%	405.46	1,621.84
Special Nett			
10 REVERSE SENSOR	1 SET	220.00	200.00 ✓
11 WINDSCREEN SEALANT	1 PC	40.00	✓
		260.00	260.00
LABOUR			
12 TO CHECK WIRING AND REFOCUS HEADLAMP	1 PC	30.00	15.00 ✓
13 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	✓
14 TO REMOVE AND REINSTALL TAILGATE WIRE HARNESS AND WIPER MOTOR	1 PC	90.00	60.00 ✓
15 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR REAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	480.00 ✓
16 TO SPRAY TAILGATE, END PANEL AND EFFECTED AREAS	1 PC	500.00	400.00 ✓
		1,540.00	1,540.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : CHEN YUANWEI EZEKIEL
BLK 226A SUMANG LANE
#17-214
SINGAPORE 821226

Estimate No: MCS1102368
Date: 06 Apr 2018
Policy No: PNPV2017-00006319
Veh Reg No: SLG3007H
Make/Model: HONDA VEZEL 1.5X
CVT A

ATTN:

Your Ref No: SLG3007H
Claim Type: Third Party
Accident Date: 05/04/2018
TP Veh Reg No: SKC2321P

Estimate Repair Cost to Vehicle No :SLG3007H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 3,421.84
		Add GST @ 7%	239.53
		Total Amount Payable	<u>S\$ 3,661.37</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED SIXTY ONE AND CENTS THIRTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE