

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16, Singapore 079120

GST Ref. No: M2-0111811-5

Vehicle No: SLU 6279X
Chasis No : W0LJD7EC1HB152890
Engine No: A2170025GU7X0215

Invoice No: CGI-ASC-18IR01427G

Invoice Date: 1/11/2018

| DESCRIPTION | AMOUNT SGD |
|-------------|---------------|
|-------------|---------------|

Parts

| <u>No.</u> | <u>Qty.</u> | <u>Description</u> | <u>Price (SGD)</u> |
|------------|-------------|---------------------------------|--------------------|
| <u>1</u> | 1 | REAR BUMPER UPPER | 1250.00 |
| <u>2</u> | 1 | REAR BUMPER LOWER | 950.00 |
| <u>3</u> | 1 | REAR BUMPER SILL PLATE(SILVER) | 350.00 |
| <u>4</u> | 1 | REAR BUMPER TOWING COVER | 25.00 |
| <u>5</u> | 1 | LHR BUMPER REFLECTOR | 190.00 |
| <u>6</u> | 1 | RHR BUMPER REFLECTOR | 190.00 |
| <u>7</u> | 1 | REAR END PANEL Lower | 750.00 |
| <u>8</u> | 1 | REAR END PANEL TRIM | 168.00 |
| <u>9</u> | 1 | RHR BUMPER GUIDE, OUTER & INNER | 65.00 |
| <u>10</u> | 1 | LHR BUMPER GUIDE, OUTER & INNER | 65.00 |
| <u>11</u> | 1 | REAR BUMPER ABSORBER - RH | 60.00 |
| <u>12</u> | 1 | REAR BUMPER ABSORBER - LH | 60.00 |
| <u>13</u> | 1 | REAR BUMPER BEAM | 815.00 |
| <u>14</u> | 1 | REVERSE SENSOR SET | 450.00 |
| <u>15</u> | 1 | REAR TAILGATE | 1900.00 |
| <u>16</u> | 1 | REAR TAILGATE LATCH | 450.00 |
| <u>17</u> | 1 | REAR TAILGATE OPEL LOGO | 180.00 |
| <u>18</u> | 1 | LETTERING MOKKA X | 130.00 |
| <u>19</u> | 1 | LETTERING CDTI | 91.00 |
| <u>20</u> | 1 | LHR TAILLAMP | 550.00 |
| <u>21</u> | 1 | RHR TAILLAMP | 550.00 |

Supplementary Items

| | | | |
|-----------|---|----------------------------|---------|
| <u>22</u> | 1 | LHR FENDER INNER SHIELD | 180.00 |
| <u>23</u> | 1 | RR TAILGATE HANDLE ASSY | 2877.00 |
| <u>24</u> | 1 | RR TAILGATE INNER TRIM | 450.00 |
| <u>25</u> | 1 | RR TAILGATE RUBBER BEADING | 230.00 |

Total: 12976.00
Less 10%: 1297.60
Parts Total : 11678.40

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Labour

| <u>No.</u> | <u>Description</u> | <u>Price (SGD)</u> |
|------------|--|--------------------|
| <u>1</u> | To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts | 2,400.00 |
| <u>2</u> | Carry out spray painting on affect area frt portion (Rear bumper) | 1,650.00 |
| <u>3</u> | To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair | 30.00 |
| <u>4</u> | Remove and refit reverse sensor (Labour) | 60.00 |
| <u>5</u> | To conduct transfer of parts from old tailgate to new tailgate | 80.00 |
| <u>6</u> | To remove and refit rear windscreen | 120.00 |

Labour Total : 4340.00

Other

| <u>No.</u> | <u>Other Description</u> | <u>Price (SGD)</u> |
|------------|--------------------------|--------------------|
| 1 | Rear Bumper Clip Set | 40.00 |

Other Total : 40.00

Total : 16058.40
GST (7%) 1124.09
Grand Total: 17182.49

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.