

Hybrid & Electric Vehicle Service Center
 600 SIN MING AVE, LEVEL 3, SINGAPORE 575733
 Tel No. : 63529268 Fax No. : 63529508
 E-Mail : admin@hevshop.com
 Website : http://appleheveinternational.com
 Tax Reg. No. : 201718701K

NG CHEN LENG
 9 Sin Min Walk #17-06
 Singapore 575578

Estimate : ES000032

Date : 06/04/2018
 Vehicle Num. : SGK8268B
 Make/Model : Vezei Hybrid 1.5Z-2016
 Chassis/Eng# : RU31129837/LEB5079858
 Accident Date : 05/04/2018
 Claim No. :
 Reference :
 Policy No. : (13/05/2026)

Attention : Motor Claim Department
 Contact : 8338 6433

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	Tailgate ASSY		1,100.00
2.	1	Tailgate Weather Strip		151.70
3.	2	Tailgate Stopper	21.00	42.00
4.	1	Tailgate Lock ASSY		145.70
5.	1	Tailgate Striker		85.00
6.	1	Rear Bumper		980.00
7.	2	Rear Bumper Side Spacer (LH / RH)	28.80	57.60
8.	1	Rear Panel		476.00
9.	1	Rear Panel Top Garnish		130.00
10.	1	Rear Wheel Arch Protector		268.20
11.	1	Rear Windscreen Moulding		220.20
12.	1	Rear Windscreen Sealant Kit		132.10
13.	1	Rear Floor Cover		257.00
14.	1	Trunk Floor Box		240.00
15.	1	SMART Buzzer ASSY		220.00
16.	1	Antenna ASSY		145.00
17.	1	Reverse Sensor Set		220.00
18.	1	'H' Emblem		25.00
19.	1	'VEZEL' Emblem		58.00
20.	1	'HYBRID' Emblem		85.00
List Totals\$:				5,038.50
20.00% Discount S\$:				1,007.70
				4,030.80

LIST ITEMS :

1. Tailgate ASSY / *Paint*

2. Tailgate Weather Strip X

3. Tailgate Stopper X *2*

4. Tailgate Lock ASSY X *2* / *dmg*

5. Tailgate Striker X

6. Rear Bumper / *pe*

7. Rear Bumper Side Spacer (LH / RH) / *850.70*

8. Rear Panel / *repair* X

9. Rear Panel Top Garnish X

10. Rear Wheel Arch Protector X *2* / *OR*

11. Rear Windscreen Moulding -

12. Rear Windscreen Sealant Kit -

13. Rear Floor Cover X

14. Trunk Floor Box X *2* / *dmg*

15. SMART Buzzer ASSY X *2* / *no damage*

16. Antenna ASSY X

17. Reverse Sensor Set X

18. 'H' Emblem / *NEC*

19. 'VEZEL' Emblem /

20. 'HYBRID' Emblem /

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CONTINUE / ...

APPLE HEV INTERNATIONAL PTE LTD

Hybrid & Electric Vehicle Service Center
600 SIN MING AVE, LEVEL 3, SINGAPORE 575733
Tel No. : 63529268 Fax No. : 63529508
E-Mail : admin@hevshop.com
Website : http://applehevinternational.com
Tax Reg. No. : 201718701K

NG CHEN LENG
9 Sin Min Walk #17-06
Singapore 575578

Attention : Motor Claim Department
Contact : 8338 6433

Estimate : ES0000032

Date : 06/04/2018
Vehicle Num. : SGK8268B
Maker/Model : Vezei Hybrid 1.5Z-2016
Chassis/Eng# : RU31129837/LEB5079858
Accident Date : 05/04/2018
Claim No. :
Reference :
Policy No. : (13/05/2026)

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	10	SPECIAL NETT ITEMS : Rear Bumper Clip ✓	7.00	70.00
		Special Nett Total S\$:		70.00
		LABOUR : Panel Beating Spray Painting To remove, refix hybrid battery ASSY to facilitate rear panel epair work To remove, refix rear windscreen To conduct water test for rear car body		1,100.00 850.00 X 300.00 X 100.00 X 100.00 2,450.00

*SPays.
part by part.
before paint photos. / After paint photos.*

SingDollars : Six Thousand Five Hundred Fifty & Cents Eighty Only

Guo Qiang - 82880282
Total S\$: 6,550.80

Guo Qiang @ HKauto. Com.

12/4/18.

APPLE HEV INTERNATIONAL PTE LTD

*NAZ
LKC
13/4/18 1715*