

REF: CS / LAW18006544 / Avb02

Special Instruction:

US: \$ 10900.00

From (Person): Jusbeer of Tan Kok Wan Date/Time: 24/08/2017
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: PAR Automotive & Formteam

Workshop: Twinear Automotive

OD(TP Re-inspection) / Evaluation

To Inspect Vehicle No: SJ3 149L Insured: F88 4033J

at Workshop m/s Twincor Automotive Tel: 01-17
of 2 Kaki Bukit Ave 2

Policy No: AY/C2105/16 Claim No: TWK/DN/0936/16

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20-10-2015

11-04-2018 (Wednesday) @ 2.30pm

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 11/12/2018 11:12 Confirmed with 11/12/2018 11:12 Final Fig 11/12/2018 11:12, 11/12/2018 11:12 days (Red S 11/12/2018 11:12 / 11/12/2018 11:12 %; Original 11/12/2018 11:12 days)

Date/Time: 30/7/18 Submit Final Fig LS \$6700, 7 days (Red \$ 4200 / 39 %; Original days)

[illegible]

Para(1) : Parts found not replaced	(To highlight R or UB , LR , Etc)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

RECEIVED 30 JUL 2018

\$ 500.00

Para(3) : Nett Value

Market Value : _____

Salvage Value :

Nett Value

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time 30/7-19 pxt File Pass to

2) Date/Time File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 24 August, 2017 3:25 PM
To: assignments
Subject: FW: YRef: To be advised : ORef: TWK/DN/0936/16

Importance: High

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jasbeer Kaur on behalf of Daniel Cheong [mailto:jasbeerkaur@tkqp.com.sg]
Sent: Thursday, 24 August, 2017 2:43 PM
To: SUR <sur@lkkauto.com>
Cc: Daniel Cheong Yong Liang <danielcheong@tkqp.com.sg>; andy@yoga-legal.com
Subject: FW: YRef: To be advised : ORef: TWK/DN/0936/16
Importance: High

Dear Sirs,

MC SUIT NO. 9030 of 2016

ACCIDENT INVOLVING SJS 149L, FBB 4233J AND SKV 5829Y ON 20.10.2015 ALONG BKE TOWARDS WOODLANDS BEFORE BUKIT PANJANG EXIT ABOUT 1820 HRS

We refer to the above matter.

M/s C Yogarajah LLC acts for the Plaintiff and M/s Tan Kok Quan Partnership acts for the Defendant, whose vehicle No. is FBB 4233J.

Please be informed that the Court has appointed, Mr Adrian Ling you as the Single Joint Expert for this action to provide an independent assessment in respect of cost of repairs to motor car No. SJS 149L. We forward herewith copies of 2 survey reports and accident reports for your perusal.

Kindly note that as Single Joint Expert appointed by the Court, your primary duty is to the Court and you are required to give a fair and reasonable assessment of cost of repairs for SJS 149L.

Your report to be released within 4 weeks from today.

Based on our previous record, Mr Adrian Ling's fees for SJE report is \$500.00.

Kindly liaise with M/s C Yogarajah LLC on when you can conduct the re-survey of the Plaintiff's vehicle. Their contact no. is 62925838 and their reference No. AY/C2105/16

All the documents have been placed under this link

Link as below:

https://tkqp.sharepoint.com/insurancelitigation/_layouts/15/guestaccess.aspx?docid=1f8696722f37f43828c241895cda1c0d8&authkey=AZbmAy9FBpOZ1O9K7HYLvTk

Regards,
Daniel Cheong
Associate

TKQP

Tan Kok Quan Partnership
Advocates & Solicitors, Singapore
1 Wallich Street #07-02 Guoco Tower Singapore 078881
T (65) 6225 9333
D (65) 6496 9590
F (65) 6227 6116
E danielcheong@tkqp.com.sg
W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

TKQP

Tan Kok Quan Partnership
Advocates & Solicitors, Singapore
1 Wallich Street #07-02 Guoco Tower Singapore 078881
T (65) 6225 9333
D (65) 6496 9588
F (65) 6227 6116
E jasbeerkaur@tkqp.com.sg
W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

Catherine Chong (LKK Auto)

From: Keline <keline@yoga-legal.com>
Sent: Monday, 9 April, 2018 11:02 AM
To: 'Catherine Chong (LKK Auto)'
Cc: 'assignments'; jasbaer.kaur@tkqp.com.sg
Subject: RE: YRef: AYC2105.16.kt : ORef: TWK/DN/0936/16 - SJS 149L

Importance: High

Dear Catherine,

Refer to our earlier telephone conversation.

We write to confirm the re-inspection of our client's vehicle **SJS 149L** as follows:-

Date : **11 April 2018 (Wednesday)**
Time : **3.00 pm**
Venue : **Twincar Automotive Pte Ltd**
2 Kaki Bukit Avenue 2
#01-17 Kaki Bukit Auto Hub
Singapore 417921
Contact: Ms. Emily
Tel: 6-842-0051

Kindly let us have your SJE report within the next four weeks from the date of re-inspection.

Thank you.

Regards

Keline Tung (Ms)
M/s C. YOGARAJAH LLC
883 North Bridge Road
#19-05 Southbank
Singapore 198785
(UEN No. 201333127N)
(GST Reg No. 201333127N)
Tel : (65) 6292 5838
Fax : (65) 6292 5938
Email : keline@yoga-legal.com

Important Note: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 9 April, 2018 10:42 AM
To: keline@yoga-legal.com
Cc: 'assignments'
Subject: RE: YRef: To be advised : ORef: TWK/DN/0936/16

Dear Ms Keline,

Kindly arrange RI appointment for this SJE.

Our Ref : AY/C2105/16

Your Ref : SJS 149L

26 February 2018

M/S LKK AUTO CONSULTANTS PTE LTD
51 Ubi Avenue 1
#01-25 Paya Ubi Industrial Park
Singapore 408933

BY FAX: 6-741-4108 & BY POST
(Enclosures by post only)

Dear Sirs

MC/MC 9030/2016

Accident Involving SJS 149L, FBB 4233J & SKV 5829Y On 20.10.2015 Along BKE Towards Woodlands Before Bukit Panjang Exit At About 1820 Hrs.

We refer to the above matter.

We write to inform you that your Mr. Adrian Ling of M/s LKK Auto Consultants Pte Ltd has been appointed by the Court to be the "SJE" in this matter.

We are acting for the Plaintiff, whose vehicle is SJS 149L and M/s Tan Quan Kuan Partnership is acting for the Defendant, whose vehicle is FBB 4233J.

Kindly find enclosed herewith copies of the following for your perusal:-

- 1) Accident report and police report of the Plaintiff (SJS 149L);
- 2) Survey report of the Plaintiff's vehicle SJS 149L by M/s PAR Automotive Consultancy;
- 3) Colored photographs of the Plaintiff's vehicle SJS 149L by M/s PAR Automotive Consultancy;
- 4) Accident report and police report of the Defendant (FBB 4233J); &
- 5) Re-inspection report and colored photographs of the Plaintiff's vehicle SJS 149L by M/s Formteam Consultancy Pte Ltd.

Kindly let us have a copy of the "SJE report" soonest.

Kindly contact our office should you still require a physical re-inspection to be arranged.

Kindly revert.

Yours faithfully,


C. YOGARAJAH LLC
Enc.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2015 14:59
Date Of Accident	20/10/2015 18:20
Exact Location Of Accident	BKE TOWARD WOODLANDS BEFORE BUKIT PANJANG EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS149L
Insured/Policyholder	
Name Of Registered Owner	MOHAMED NUR MUBBIN BIN ABDUL KADIR
NRIC No	S7341792I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92763402
Alternative Phone No	Others-92763402
Vehicle Particulars	
Manufacturer	PROTON
Model	EXORA 1.6L AT (M-LINE) ABS D/AB 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	GOING BACK HOME
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5072690357
Cover Note Number	-
Driver	
Name of Driver	MOHAMED NUR MUBBIN BIN ABDUL KADIR
NRIC No	S7341792I
Date Of Birth	16/11/1973
Occupation	Indoor
Date Of Driving Pass	29/05/2009
Driving Experience	6 Years And 4 Months
Gender	Male
Mobile Number	(Local) +65-92763402
Fax Number	
Contact Number	Others-92763402
Email Address	NOEMAIL

Address	BLK 343 WOODLANDS AVENUE 1 #03-625
Postcode	730343
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head to Rear (TP Hit Insured)
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Woodlands East N.p.c
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: Singapore
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED POLICE REPORT NO.T/20151021/2026.

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBB4233J
Vehicle Make/Model/Colour	YAMAHA T135
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC Income Insurance Co-operative Ltd
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKV5829Y
Vehicle Make/Model/Colour	MERCEDES BENZ S400L (R19 LED)
Details Of Properties	

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims.


(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan BKE TOWARD WOODLANDS BEFORE BKE17 PANJIANI, EXIT



WOODLANDS

A-SJS 149 L
B-FAB 4233 J
C-SKV 5829 Y

Describe Circumstances of the Accident

As per POLICE REPORT NO. 7/20151021/2026.

A - STS 149 L

B - FBG 4233 J


C - SKV 5829 Y

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

POLICE REPORT

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20151021/2026

1 of 3

Report No: T/20151021/2026

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/10/2015 10:00		Vide Report No.: J/20151020/0168		Station Diary No.: 38	
Informant's Particulars					
Name of Informant: Mohamed Nur Mubbin Bin Abdul Kadir			Address: APT BLK 343 Woodlands Avenue 1 #03-625 SINGAPORE		
ID Type / ID No.: NRIC NO / S73417921			Contact No.: Home/Office: Mobile: 92763402		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 41	Date of Birth: 16/11/1973	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: MANAGEMENT SUPPORT OFFICER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 20/10/2015 18:20	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB4233J	Motorcycle				Seriously Damaged	0
SJS149L	Car	PROTON	EXORA 1.6L AT (M-LINE) ABS D/AB 2WD 5DR	Silver	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date
SJS149L	NTUC Income Insurance Co-Operative Limited	5072690357	27/07/2015	26/07/2016

POLICE REPORT

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20151021/2026

2 of 3

Report No. T/20151021/2026

CONTINUATION OF REPORT


Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Mohamed Nur Mubbin Bin Abdul Kadir	ID No.	S73417921
Related Vehicle	NIL	Contact No.	92763402
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL
Rider			
Name	Adil Bin Selamat	ID No.	S1257954C
Related Vehicle	NIL	Contact No.	96747470
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details.

On the 20/10/2015 at about 1810hrs I was driving, SJS149L, after exiting Dairy Farm Road to enter Bukit Timah Expressway towards Woodlands. Due to the heavy traffic, my vehicle was not moving as I was waiting for the traffic in front to move. As I was waiting along the 3rd lane of the expressway when about 1820hrs, I heard a loud thud to the back of my vehicle. I discovered that a motorcyclist riding FBB4233J had crashed into the back of my vehicle. Subsequently the rider informed me that he had called up the ambulance and soon afterwards the police and the ambulance had arrived. The police then advised me to lodge a police report, vide J/20151020/0168.

POLICE REPORT

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20151021/2026

3 of 3

Report No. T/20151021/2026

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / KHAIRUL ANWAR BIN SHARIFUDDIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/10/2015 10:00
Officer In Charge Of Case: TP / GIT / Yeo Kia Huan Contact No.: 65476325	Classification Of Case:

Authentication Stamp
NP168

POLICE REPORT



T/20151021/2062

1 of 3

Report No. T/20151021/2062

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No. T/20151021/2026

Report Number T/20151021/2062

Vide Report Number T/20151021/2026

Date/Time of Report Made 21/10/2015 12:53

Place Report Lodged Traffic Police Division HQ

Type of Informant Driver

Name of Informant MOHAMED NUR MUBBIN BIN ABDUL KADIR

ID Type / ID No. NRIC NO. S73417921

Home Office

Mobile 92763402

Email

Type of Accident Injury - Conveyed By Ambulance

Drink Drive No

Anyone conveyed by ambulance Yes

Date/Time of Accident 20/10/2015 18:20

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB4233J	Motorcycle	YAMAHA	T135	Black		0
SJS149L	Car	PROTON	EXORA 1.6L AT (M-LINE) ABS D/AB- 2WD 5DR	Silver		0
SKV5829Y	Car	MERCEDES BENZ	S400L (R19 LED)	Black		0

POLICE REPORT



T:20151021/5062

2 of 3

Report No. T:20151021/2062

Continuation of CSF For NP168


Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOHAMED NUR MUBBIN BIN ABDUL KADIR	ID No.	S73417921
Related Vehicle	NIL	Contact No.	92763402
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL
Driver			
Name	Adil Bin Selamat	ID No.	S1257954C
Related Vehicle	NIL	Contact No.	96747470
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Facts.

On the 20/10/2015 at about 1810hrs I was driving, SJS149L, after exiting Dairy Farm Road to enter Bukit Timah Expressway towards Woodlands. Due to the heavy traffic, my vehicle was not moving as I was waiting for the traffic in front to move. As I was waiting along the 3rd lane of the expressway when about 1820hrs, I heard a loud thud to the back of my vehicle. I discovered that a motorcyclist riding FBB4233J had crashed into the back of my vehicle. Subsequently the rider informed me that he had called up the ambulance and soon afterwards the police and the ambulance had arrived. The police then advised me to lodge a police report, vide T:20151020/0168.

The driver of SKV5829Y inform me that the motorcycle had hit his car. There is a slight scratch on the rear right backlight.

POLICE REPORT



T/20151021/2062

3 of 3

Report No. T/20151021/2062

Continuation of CSF For NP168

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity	No
Officer-In-Charge of Case	TP GIT / Yeo Kia Huat
Classification of Case	1) INJURY CONVEYED BY AMBULANCE

Healman

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo






Accident Photo







PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0017-16-TCA

18 January 2016

Mohamed Nur Mubbin Bin Abdul Kadir
Blk 343 Woodlands Ave 1 #03-625
Singapore 730343

INVOICE No. 0017-16-TCA

Vehicle No. SJS149L

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$645.00
Total amount payable		<u>\$645.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0017-16-TCA

18 January 2016

ACCIDENT VEHICLE SURVEY REPORT

Mohamed Nur Mubbin Bin Abdul Kadir
Blk 343 Woodlands Ave 1 #03-625
Singapore 730343

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJS149L	<i>Odometer:</i>	91711km
<i>Make & Model:</i>	Proton Exora 1.6L AT	<i>Colour:</i>	Silver
<i>Chassis number:</i>	PL1FZ6YRR9F008371	<i>Date of accident:</i>	20/10/2015
<i>Year of Regn.:</i>	27/07/2009	<i>Date inspected:</i>	22/10/2015
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921		

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	5mm/Goodyear	5mm/Goodyear	195/65R15
<i>Rear:</i>	5mm/Goodyear	5mm/Goodyear	195/65R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BUMPER	1	squashed	1,136.03	1,136.03
REAR BUMPER INNER SIDE SHIELD CLIPS L/R <i>not Replaced</i>	10	necessary	65.00	65.00 x
REAR BUMPER INNER SIDE SHIELD L/R	2	reuse	123.00	0.00 x
REAR BUMPER INNER SPONGE	1	deformed	89.22	89.22 ✓
REAR BUMPER REFLECTOR L/R <i>not Replaced</i>	2	deformed	181.04	181.04 x
REAR BUMPER REINFORCEMENT	1	bent	268.06	268.06 ✓
REAR BUMPER SIDE RETAINER L/R	2	necessary	71.46	71.46 ✓
REAR BUMPER TOP BEAM	1	bent	142.63	142.63 ✓
REAR BUMPER TOW HOOK COVER	1	reuse	34.82	0.00 x
REAR END PANEL 'INNER'	1	repair	251.31	0.00 x
REAR END PANEL 'OUTER'	1	buckled	268.57	268.57 ✓
REAR END PANEL INNER TOP GARNISH	1	warped	197.81	197.81 ✓
REAR END PANEL INNER TOP GARNISH CLIPS	6	necessary	39.00	39.00 10
REAR END PANEL LOCK STRIKER	1	bent	22.59	22.59 x
REAR EXHAUST GASKET <i>not Replaced</i>	1	necessary	18.91	18.91 x
REAR EXHAUST RUBBER MOUNTING	3	distorted	154.26	154.26 x
REAR EXHAUST SILENCER BOX	1	repair	1,999.14	0.00 x
REAR FLOOR PANEL INNER TOP UPHOLSTERY BOARD	1	deformed	463.14	463.14 ✓
REAR TAILGATE	1	buckled	1,707.39	1,707.39
REAR TAILGATE 'CPS' EMBLEM	1	necessary	22.96	22.96 ✓
REAR TAILGATE 'EXORA' EMBLEM	1	necessary	27.13	27.13 ✓
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	35.83	35.83 ✓
REAR TAILGATE 3RD BRAKE LAMP	1	reuse	117.62	0.00 x
REAR TAILGATE 3RD BRAKE LAMP GARNISH	1	reuse	32.14	0.00 x
REAR TAILGATE DAMPER L/R <i>not Replaced</i>	2	bent	303.82	303.82 x
REAR TAILGATE HINGES L/R	2	bent	76.28	76.28 x
REAR TAILGATE INNER HANDLE	1	warped	19.86	19.86 x
REAR TAILGATE INNER UPHOLSTERY CARDBOARD	1	fractured	223.44	223.44 ✓
REAR TAILGATE MECHANISM LOCK	1	bent	314.14	314.14 ✓
REAR TAILGATE NUMBER PLATE LAMP L/R	2	fractured	51.20	51.20 ✓
REAR TAILGATE OUTER GARNISH	1	warped	104.28	104.28 ✓
REAR TAILGATE OUTER GARNISH CLIPS	10	necessary	65.00	65.00 20
REAR TAILGATE OUTER LOCK HANDLE <i>not Replaced</i>	1	distorted	139.30	139.30 x
REAR TAILGATE RUBBER GUIDE STOPPER L/R	4	deformed	112.56	112.56 x
REAR TAILGATE SPOILER	1	reuse	411.65	0.00 x
REAR TAILGATE WEATHERSTRIP	1	deformed	162.58	162.58 ✓
REAR TAILGATE WINDSCREEN	1	shattered	590.69	590.69 ✓
REAR TAILGATE WINDSCREEN MOULDING	1	necessary	112.10	112.10 ✓
REAR TAILGATE WIPER ARM	1	bent	87.27	87.27 x
REAR TAILGATE WIPER ARM COVER <i>not Replaced</i>	1	fractured	17.91	17.91 x
REAR TAILGATE WIPER ARM RUBBER SEAL	1	necessary	14.44	14.44 x
REAR TAILGATE WIPER BLADE	1	abraded	32.46	32.46 x

PAR Automotive Consultancy

Report No: 0017-16-TCA-SJS149L

REAR TAILGATE WIPER MOTOR	1	shorted	321.47	321.47	X
REAR TAILGATE WIPER NOZZLE	1	reuse	19.50	0.00	X
REAR TAILGATE WIRE HARNESS - SET	1	reuse	334.66	0.00	X
REAR TAILLAMP APRON PANEL CLIPS L/R	4	necessary	26.00	26.00	✓
REAR TAILLAMP APRON PANEL L/R	2	reuse	244.68	0.00	X
REAR TAILLAMP CLIPS L/R	10	necessary	65.00	65.00	20
REAR TAILLAMP INNER PANEL L/R	2	repair	778.82	0.00	X
REAR TAILLAMP L/R	2	fractured	778.78	778.78	389.39
SPARE TYRE BRACKET	1	bent	184.95	184.95	X
SPARE TYRE SCREW LOCK - SET	1	bent	84.62	84.62	X

Subtotal before discount SS 13,146.52 SS 8,799.18

Percentage discount 10% and 10% SS 1,314.65 SS 879.92

Sub-total 1 SS 11,831.87 SS 7,919.26

REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00	✓
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00	200
REAR FLOOR PANEL INSULATOR MAT	1	necessary	350.00	350.00	X
REAR TAILGATE INNER UPHOLSTERY CARDBOARD CLIPS - SET	1	necessary	30.00	30.00	✓
REAR TAILGATE NUMBER PLATE	1	bent	25.00	25.00	✓
REAR TAILGATE NUMBER PLATE HOLDER	1	bent	50.00	50.00	30
REAR TAILGATE REVERSE CAMERA	1	shorted	800.00	800.00	400
REAR TAILGATE WINDSCREEN 3M SOLAR FILM	1	necessary	380.00	380.00	250
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00	60
SPARE TYRE	1	reuse	280.00	0.00	X

Subtotal before discount SS 2,395.00 SS 2,115.00

Sub-total 2 SS 2,395.00 SS 2,115.00

Parts-total SS 14,226.87 SS 10,034.26

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	150.00	80.00	✓
To remove, reinstall tailgate windscreen	150.00	120.00	✓
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00	✓
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,500.00	1,200.00	600
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	160.00	120.00	X
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	1,100.00	700
To apply anti-rust chemical on repaired and replaced panel.	120.00	60.00	40

Labour Total SS 3,720.00 SS 2,740.00

Parts & Labour Total SS 17,946.87 SS 12,774.26

total 89334
h/s 6.7K

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 10,900.00
and the recommended number of working days for the repairs is within 8 day(s).**



B J Loi (I Eng., MIML, AIRTE)

Automotive Appraiser

Report No: 0017-16-TCA

18 January 2016

ACCIDENT VEHICLE SURVEY REPORT

Mohamed Nur Mubbin Bin Abdul Kadir
Blk 343 Woodlands Ave 1 #03-625
Singapore 730343

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJS149L	<i>Odometer:</i>	91711km
<i>Make & Model:</i>	Proton Exora 1.6L AT	<i>Colour:</i>	Silver
<i>Chassis number:</i>	PL1FZ6YRR9F008371	<i>Date of accident:</i>	20/10/2015
<i>Year of Regn.:</i>	27/07/2009	<i>Date inspected:</i>	22/10/2015
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "**Without Prejudice**" basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2015 13:12
Date Of Accident	20/10/2015 18:20
Exact Location Of Accident	BKE (WOODLANDS) EXIT FROM DAIRY FARM ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBB4233J
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD RAZIF BIN ADIL
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96747470
Alternative Phone No	Office-96747470

Vehicle Particulars

Manufacturer	YAMAHA
Model	T135
Vehicle Category	Motorcycle

Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	5041252747-05 TP
Cover Note Number	

Driver

Name of Driver	ADIL BIN SELAMAT
NRIC No	S1257954C
Address	BLK 873 WOODLANDS ST 81 #01-258

General Information of the Accident

Type Of Accident	Collision- Head to Rear (Insured Hit TP)
Weather Conditions	Clear

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	1

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED. ATTENDED BY AINI

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS149L
Vehicle Make/Model/Colour	
Name of Driver	
Insurance Company Name	

DETAILS OF INJURED PERSON 1

Name	ADIL BIN SELAMAT
Injured person in which vehicle?	FBB4233J

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

IOAC BUKIT BATOK (VAC)

511 Bukit Batok St 23

Singapore 654515

Tel: 6567 9427 / 6567 3312

Fax: 6564 0722

Email: vachb@singnet.com.sg

22 OCT 2013


Am

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

Declaration

We declare the foregoing particulars are true in every respect.

IDAC BUKIT BATOK (VAC)
511 Bukit Batok St 23
Singapore 659545
Tel: 6567 9427 / 6560 3312
Fax: 6569 0722
Email: vacbb@singnet.com.sg

22 OCT 73

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Individual Statement Pg.1

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20151021/2030

1 of 3

Report No. T/20151021/2030

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/10/2015 10:27		Vide Report No.:		Station Diary No.: 46	
Informant's Particulars					
Name of Informant: ADIL BIN SELAMAT			Address: APT BLK 873 WOODLANDS STREET 81 #01-258 SINGAPORE 730873		
ID Type / ID No.: NRIC NO / S1257954C			Contact No.: Home/Office: Mobile: 96747470		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 57	Date of Birth: 25/10/1957	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: Customer service manager			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 20/10/2015 18:20	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB4233J	Motorcycle				Seriously Damaged	0
SJS149L	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Individual Statement Pg.1

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20151021/2030

2 of 3

Report No. T/20151021/2030

CONTINUATION OF REPORT

Rider			
Name	ADIL BIN SELAMAT	ID No.	S1257954C
Related Vehicle	NIL	Contact No.	96747470
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details.

On 20/10/2015 at about 1815hrs I was riding FBB4233J after exiting Dairy Farm Road entering Bukit Timah Expressway towards Woodlands. The traffic was very heavy so I was riding slowly. In front of me was a black Mercedes who suddenly came to a stop and forced me to overtake him abruptly. Subsequently, after doing so I did not realize the vehicle SJS149L was very close in front and I couldn't stop in time which caused my vehicle to crash into the back of SJS149L. After crashing, I was in a daze when I was told that the ambulance had been called. Minutes later the Ambulance and the Police arrived to the scene. The Police officer at the scene advised me to lodge a Police report. I was then assessed by the paramedic and was conveyed to Ng Teng Fong General Hospital.

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20151021/2030

3 of 3

Report No. T/20151021/2030

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

SN 130

KHAIRUE ANWAR BIN SHARIFUDDEEN

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

21/10/2015 10:27

Officer In Charge Of Case:

TP / GIT /

Yeo Kia Hunt

Contact No.: 65476325

Classification Of Case:

Authentication Stamp

NP168

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408568

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: monesurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : RRN16-020367-RI/FP/cg

Your Reference: MT/CA/TP/009/0879024-001/RD/LC

Date : 16-Apr-2016

Motor Claims Department
NTUC Income Co-Operative Limited
1 Maritime Square
#10-01 Harbourfront Centre
Singapore 099253

Attention : Ms Rajeswary

Dear Sir/Mdm,

RE-INSPECTION OF VEHICLE NO . SJS 149L

Pursuant to your instructions on 16 Feb 2016 , we have conducted a reinspection of the above vehicle at 2 Kaki Bukit Ave 2 #01-17/18 Kaki Bukit Autohub S'417921 on 12 Apr 2016.

We recommend a repair cost of **\$6,450.00** (see report) based on lump sum repair and the estimated duration of repairs would take **06 days**.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPAC1, MSAAA
Licensed Appraiser

(Email : frankie@fta.com.sg)

Encl. Re-inspection Report

FormTeam Consultancy Pte Ltd

PAGE : 2

Our Reference : RRN16-020367-RI/FP/cg

Your Reference : MT/CA/TP/009/0879024-001/RD/LC

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
3	Rear Exhaust Rubber Mounting	Not Necessary		154.26	-
1	Rear Exhaust Silencer Box	Repair		-	-
1	Rear Floor Panel Inner Top Upholstery Board	Not Replaced		463.14	-
1	Rear Tailgate	Buckled		1,707.39	1,707.39
1	Rear Tailgate 'CPS' Emblem	Necessary		22.96	22.96
1	Rear Tailgate 'Exora' Emblem	Necessary		27.13	27.13
1	Rear Tailgate 'Logo' Emblem	Necessary		35.83	35.83
1	Rear Tailgate 3RD Brake Lamp	Reuse		-	-
1	Rear Tailgate 3RD Brake Lamp Garnish	Reuse		-	-
2	Rear Tailgate Damper L/R	Not Replaced		303.82	-
2	Rear Tailgate Hinges L/R	Not Replaced		76.28	-
1	Rear Tailgate Inner Handle	Warped		19.86	19.86
1	Rear Tailgate Inner Upholstery Cardboard	Fractured		223.44	223.44
1	Rear Tailgate Mechanism Lock	Bent		314.14	314.14
2	Rear Tailgate No. Plate Lamp L/R	Fractured		51.20	51.20
1	Rear Tailgate Outer Garnish	Warped		104.28	104.28
10	Rear Tailgate Outer Garnish Clips	Necessary		65.00	65.00
1	Rear Tailgate Outer Lock Handle	Distorted		139.30	139.30
4	Rear Tailgate Rubber Guide Stopper L/R	Reuse		112.56	-
1	Rear Tailgate Spoiler	Reuse		-	-
1	Rear Tailgate Weatherstrip	Deformed		162.58	162.58
1	Rear Tailgate Windscreen	Shattered		590.69	590.69
1	Rear Tailgate Windscreen Moulding	Necessary		112.10	112.10
1	Rear Tailgate Wiper Arm	Reuse /		87.27	-
1	Rear Tailgate Wiper Arm Cover	Not Necessary /		17.91	-
1	Rear Tailgate Wiper Arm Rubber Seal	Wear And		14.44	-
1	Rear Tailgate Wiper Blade	Tear		32.46	-
1	Rear Tailgate Wiper Motor	Not Consistent		321.47	-
1	Rear Tailgate Wiper Nozzle	Reuse		-	-

FormTeam Consultancy Pte Ltd

PAGE : 4

Our Reference : RRN16-020367-RI/FP/cg

Your Reference: MT/CA/TP/009/0879024-001/RD/LC

QTY	DESCRIPTION	SUBMITTED	REVISED
	LABOUR & MISC		
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00	20.00
2	To remove, reinstall tailgate windscreen.	120.00	120.00
3	To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60.00	60.00
4	To re-spray painting on the rear boot lid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,200.00	600.00
5	To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	120.00	-
6	To provide labour, workmanship to change the above damaged body parts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. (including all repair parts)	1,100.00	600.00
7	To apply anti-rust chemical on repaired and replaced panel.	60.00	60.00
	Total Labour Amount	2,740.00	1,460.00
	Total Parts and Labour	12,774.26	8,087.22



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TAN KOK QUAN PARTNERSHIP		Ref : CS/LAW18006544/Avbe2	
1 WALLICH STREET #07-02 GUOCO TOWERS SINGAPORE 078881		Date : 30-07-2018	
		Code : L021	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
	Insured Veh.	FBB 4233J	Veh. Inspected
			SJS 149L
	Policy No.	AY/C2105/16	Coverage (\$)
			0.00
	Claim No.	TWK/DN/0936/16	Excess (\$)
			0.00
	Assign From	JASBEER	Assign Date
			24/08/2017
2. Vehicle Particulars & Condition			
	Make & Model	PROTON EXORA	c.c
			1597
	Engine No.	HIDDEN	Year of Reg.
			2009
	Chassis No.	PL1FZ6YRR9F008371	Colour
			SILVER
	Odometer	141842	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			STANDARD ALLOY RIM
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	195/65 R15	HANKOOK
			6 mm
	L/H Front Tyre	195/65 R15	HANKOOK
			6 mm
	R/H Rear Tyre	195/65 R15	HANKOOK
			6 mm
	L/H Rear Tyre	195/65 R15	HANKOOK
			6 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
	Accident Date	20/10/2015	Inspection Date
			11/04/2018
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921	
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 149L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	REPLACED	1,136.03	1,136.03
10	REAR BUMPER INNER SIDE SHIELD CLIPS L/R	NOT CHANGED	65.00	-
2	REAR BUMPER INNER SIDE SHIELD L/R	REUSE	123.00	-
1	REAR BUMPER INNER SPONGE	REPLACED	89.22	89.22
2	REAR BUMPER REFLECTOR L/R	NOT CHANGED	181.04	-
1	REAR BUMPER REINFORCEMENT	REPLACED	268.06	268.06
2	REAR BUMPER SIDE RETAINER L/R	REPLACED	71.46	71.46
1	REAR BUMPER TOP BEAM	REPLACED	142.63	142.63
1	REAR BUMPER TOW HOOK COVER	REUSE	34.82	-
1	REAR END PANEL 'INNER'	REPAIRED SEE LABOUR	251.31	-
1	REAR END PANEL 'OUTER'	REPLACED	268.57	268.57
1	REAR END PANEL INNER TOP GARNISH	REPLACED	197.81	197.81
6	REAR END PANEL INNER TOP GARNISH CLIPS	REPLACED	39.00	10.00
1	REAR END PANEL LOCK STRIKER	NOT CHANGED	22.59	-
1	REAR EXHAUST GASKET	NOT CHANGED	18.91	-
3	REAR EXHAUST RUBBER MOUNTING	NOT CHANGED	154.26	-
1	REAR EXHAUST SILENCER BOX	REPAIRED SEE LABOUR	1,999.14	-
1	REAR FLOOR PANEL INNER TOP UPHOLSTERY BOARD	REPLACED	463.14	463.14
1	REAR TAILGATE	REPLACED	1,707.39	1,707.39
1	REAR TAILGATE 'CPS' EMBLEM	REPLACED	22.96	22.96
1	REAR TAILGATE 'EXORA' EMBLEM	REPLACED	27.13	27.13
1	REAR TAILGATE 'LOGO' EMBLEM	REPLACED	35.83	35.83
1	REAR TAILGATE 3RD BRAKE LAMP	REUSE	117.62	-
1	REAR TAILGATE 3RD BRAKE LAMP GARNISH	REUSE	32.14	-
2	REAR TAILGATE DAMPER L/R	NOT CHANGED	303.82	-
2	REAR TAILGATE HINGES L/R	NOT CHANGED	76.28	-
1	REAR TAILGATE INNER HANDLE	NOT CHANGED	19.86	-
1	REAR TAILGATE INNER UPHOLSTERY CARDBOARD	REPLACED	223.44	223.44
1	REAR TAILGATE MECHANISM LOCK	REPLACED	314.14	314.14

Report Ref No. CS/LAW18006544/Avbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILGATE NUMBER PLATE LAMP L/R	REPLACED	51.20	51.20
1	REAR TAILGATE OUTER GARNISH	REPLACED	104.28	104.28
10	REAR TAILGATE OUTER GARNISH CLIPS	REPLACED	65.00	20.00
1	REAR TAILGATE OUTER LOCK HANDLE	NOT CHANGED	139.30	-
4	REAR TAILGATE RUBBER GUIDE STOPPER L/R	NOT CHANGED	112.58	-
1	REAR TAILGATE SPOILER	REUSE	411.65	-
1	REAR TAILGATE WEATHERSTRIP	REPLACED	162.58	162.58
1	REAR TAILGATE WINDSCREEN	REPLACED	590.69	590.69
1	REAR TAILGATE WINDSCREEN MOULDING	REPLACED	112.10	112.10
1	REAR TAILGATE WIPER ARM	NOT CHANGED	87.27	-
1	REAR TAILGATE WIPER ARM COVER	NOT CHANGED	17.91	-
1	REAR TAILGATE WIPER ARM RUBBER SEAL	NOT CHANGED	14.44	-
1	REAR TAILGATE WIPER BLADE	NOT CHANGED	32.46	-
1	REAR TAILGATE WIPER MOTOR	NOT CHANGED	321.47	-
1	REAR TAILGATE WIPER NOZZLE	REUSE	19.50	-
1	SET REAR TAILGATE WIRE HARNESS	REUSE	334.66	-
4	REAR TAILLAMP APRON PANEL CLIPS L/R	REPLACED	26.00	26.00
2	REAR TAILLAMP APRON PANEL L/R	REUSE	244.68	-
10	REAR TAILLAMP CLIPS L/R	REPLACED	65.00	20.00
2	REAR TAILLAMP INNER PANEL L/R	REPAIRED SEE LABOUR	778.82	-
2	REAR TAILLAMP L/R	O/S REPLACED / N/S NOT CHANGED	778.78	389.39
1	SPARE TYRE BRACKET	NOT CHANGED	184.95	-
1	SET SPARE TYRE SCREW LOCK	NOT CHANGED	84.62	-
	LESS 10% DISCOUNT		-1,314.65	-645.41
			11,831.87	5,808.64
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	REPLACED	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	REPLACED	350.00	200.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT CHANGED	350.00	-
1	SET REAR TAILGATE INNER UPHOLSTERY CARDBOARD CLIPS (SN)	REPLACED	30.00	30.00
1	REAR TAILGATE NUMBER PLATE (SN)	REPLACED	25.00	25.00

Report Ref No. CS/LAW18006544/Avbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	REPLACED	50.00	30.00
1	REAR TAILGATE REVERSE CAMERA (SN)	REPLACED	800.00	400.00
1	REAR TAILGATE WINDSCREEN 3M SOLAR FILM (SN)	REPLACED	380.00	250.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	REPLACED	100.00	60.00
1	SPARE TYRE (SN)	REUSE	280.00	-
			2,395.00	1,025.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		150.00	80.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR).		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,500.00	600.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	160.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT, INCLUSIVE OF THE REPAIR OF REAR END PANEL 'INNER', REAR EXHAUST SILENCER BOX AND REAR TAILLAMP INNER PANEL L/R.		1,500.00	700.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			3,720.00	1,600.00
GRAND TOTAL			17,946.87	8,433.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,700.00

Report Ref No. CS/LAW18006544/Avbe2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.