

ASS. REC. BY:

REF: CS/AIG18006559/Tlqd327 Special Instruction:

Survivor:  
Member

ASSIGNMENT (Office)

From (Person): Leo Tong Shing of AIG Date/Time: 9/10/18 @ 3:27pm

Estimated Cost:

Bill to:

 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 3223 P Insured:

at Workshop in/s: Goldbell Engineering (pioneer) Tel: 8816 2798 / 8481 4099

of 29, Tanjung Penjunu, 609026

Policy No: 2106392147-03

Claim No: 7489944572SG

Sum Insured:

Excess:

\$ IBA 1300/-

Make of Veh:

D.O.A. 10/03/2018

(Client's Record)

11/4/2018 @ 2pm

CA /  REP / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:27pm @ 9/10/18

Person Contacted:

Sasha

Vehicle IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 3223P - CC11AIG17019649 / Spb3g? D.O.A: 9/10/17
17/4/18 @ 4:05pm	Informed Sya Sya C/ir \$ ex = \$ 1300 by email.
24/5/18 @ 2:21pm	Confirmed with Sya Sya LS \$ 540, 8 days. (Red \$ 5132.50, 492)



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Mar 2018 <a href="#">Sendback Est</a>	09 Apr 2018 15:27 <b>S\$10,532.50</b>	09 Apr 2018 15:27 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>A&amp;A CONSTRUCTION &amp; ENGINEERING PTE LTD</b> , Co. Reg. No.: 200713458Z, Tel: +6598222145		
Vehicle Reg. No.:	<b>GBC3223P</b>	Date of Loss:	10/03/2018 12:00 - :59 [75 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD / 7439944572SG</b>	Policy/Cover Note No.:	2100392147-03 (Comprehensive)
		Excess:	
Repairer:	<b>Goldbell Engineering Pte Ltd (Tuas)</b> 29, Tanjong Penjuru, 609026 West Coast - Tel: 6864 0695		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loo, Tong Shing</b> ] TongShing.Loo@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt due 18/04/2018</b> ]		
Driver/Custodian:	LAU JASON (31 / Male), NRIC: S8620436C, Tel: +6598222145		
Adj Asg. Remarks:	Auto-assignment		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 24 May 2018 2:26 PM  
**To:** 'Chua Syahirul Syazwani Binte Irwan'; Admin-D (LKKAuto)  
**Cc:** 'Ramesh S/O Somasundrem'; 'Derek Chow Zhi Da'; assignments; SUR  
**Subject:** RE: Survey for GBC3223P- Own Damage

Dear Syasya,

Confirm Lump Sum \$5,400.00 before excess \$1,300.00 & GST and 8 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 24 May 2018 2:21 PM  
**To:** Chua Syahirul Syazwani Binte Irwan <[ChuaSyaSya@goldbell.com.sg](mailto:ChuaSyaSya@goldbell.com.sg)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** Ramesh S/O Somasundrem <[Ramesh@goldbell.com.sg](mailto:Ramesh@goldbell.com.sg)>; Derek Chow Zhi Da <[DerekChowZD@goldbell.com.sg](mailto:DerekChowZD@goldbell.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: Survey for GBC3223P- Own Damage

Dear Syasya,

Confirm Lump Sum \$5,400.00 before GST and 8 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chua Syahirul Syazwani Binte Irwan [<mailto:ChuaSyaSya@goldbell.com.sg>]  
**Sent:** Tuesday, 22 May 2018 11:29 AM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** Ramesh S/O Somasundrem <[Ramesh@goldbell.com.sg](mailto:Ramesh@goldbell.com.sg)>; Derek Chow Zhi Da <[DerekChowZD@goldbell.com.sg](mailto:DerekChowZD@goldbell.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: Survey for GBC3223P- Own Damage

Dear Shiau Chan,

Is there any updates on the finalisation?

Thank you.

Regards,  
Syasya

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 12 April 2018 4:05 PM  
**To:** Chua Syahirul Syazwani Binte Irwan; Admin-D (LKKAuto)  
**Cc:** Ramesh S/O Somasundrem; Derek Chow Zhi Da; SUR  
**Subject:** RE: Survey for GBC3223P- Own Damage

Dear Sya Sya,

Please proceed to repair the insured vehicle **GBC 3223P (Excess \$1,300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chua Syahirul Syazwani Binte Irwan [mailto:[ChuaSyaSya@goldbell.com.sg](mailto:ChuaSyaSya@goldbell.com.sg)]  
**Sent:** Tuesday, 10 April 2018 9:53 AM  
**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** Ramesh S/O Somasundrem <[Ramesh@goldbell.com.sg](mailto:Ramesh@goldbell.com.sg)>; Derek Chow Zhi Da <[DerekChowZD@goldbell.com.sg](mailto:DerekChowZD@goldbell.com.sg)>  
**Subject:** Survey for GBC3223P- Own Damage

Dear Navitha,

As spoken over the phone earlier on,  
Tomorrow Survey at 2pm is confirmed.

Thank you.

**Chua Syahirul Syazwani Binte Irwan | Goldbell Engineering Pte Ltd**  
Customer Service Advisor, Motor Claims

DID: +65 8481 4099 | Tel: +65 6458 9596 | Fax: +65 6458 7172 |

Mobile: | Web: <http://www.goldbell.com.sg>

Address: Goldbell Engineering Pte Ltd (Ang Mo Kio)

Blk 5035 Ang Mo Kio Industrial Park 2, #01-345

Singapore 569538

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3458Z
<b>Vehicle Details</b>	
Vehicle No.:	GBC3223P
Vehicle to be Exported:	No
Intended De-registration Date:	12 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	1KD2135388
Chassis No.:	JTFAT35Y00K201811
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	14 Nov 2011
First Registration Date:	14 Nov 2011
Transfer Count:	1
Actual ARF Paid:	\$1,249.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Nov 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,803.00
COE Rebate Amount:	\$14,632.00
<b>Total Rebate Amount:</b>	<b>\$14,632.00</b>

The information contained herein is correct as at 12 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/03/2018 14:24
Date Of Accident	10/03/2018 12:00
Exact Location Of Accident	ALONG PIE TOWARDS TUAS EXITING TO BKE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC3223P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	A&A CONSTRUCTION & ENGINEERING PTE LTD
Co Reg No	200713458Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98222145
Alternative Phone No	OFFICE-95668086

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 MANUAL 3SEATER-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100392147-03
Cover Note Number	

### Driver

Name of Driver	LAU JASON
NRIC No	S8620436C
Date Of Birth	15/07/1988
Occupation	OUTDOOR
Date Of Driving Pass	25/08/2006
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	+65-98222145
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 791 CHOA CHU KANG NORTH 6 #05-254
Postcode	680791
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP7281D
Vehicle Make/Model/Colour	HINO
Details Of Properties	FRONT & SIDE
Vehicle Category	
Name of Driver	MUNIYAN ELAVARASU
NRIC/Passport Number	G8418878L
Contact Number	98945099
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### **IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, contesting or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
  
Reporting Centre Personnel's Signature  
Name:  
NRIC/IDN No.:



## Individual Statement



**SINGAPORE  
POLICE FORCE**



T/201803102139

Police Station Of Origin  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689295  
Tel No: 1800-7659999

1 of 3

Report No. T/201803102139

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 10/03/2018 17:38		Vide Report No. J/20180310/0138	Station Diary No. 100
<b>Informant's Particulars</b>			
Name of Informant: LAU JASON		Address: APT BLK 791 CHOA CHU KANG NORTH B #05-254 SINGAPORE 680791	
ID Type / ID No. NRIC NO / S8620436C		Contact No.	Mobile: 98222145
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 31	Date of Birth: 15/07/1986	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: ASSISTANT PROJECT MANAGER		Driving Licence Information Class: 3,4,5	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 10/03/2018 12:00	Type of Location: slip road
Location: Along Road 1 Traveling Toward Road 2 PAN ISLAND EXPRESSWAY BUKIT TIMAH EXPRESSWAY PIE (Tuas), slip road of BKE towards Woodlands				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC3223P	Lorry				Slightly Damaged	0
YP7281D	Lorry				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Individual Statement



**SINGAPORE  
POLICE FORCE**



T/20180310/2139

2 of 3

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 659286  
Tel No: 1800-7659999

Report No. T/20180310/2139

CONTINUATION OF REPORT

Driver			
Name	LAU JASON	ID No.	S8620436C
Related Vehicle	GBC3223P (Lorry)	Contact No.	88222145
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MUNIYAN ELAVARASU	ID No.	G8418878L
Related Vehicle	YP7281D (Lorry)	Contact No.	88945099
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 10/3/2018 at about 1200hrs. I was driving along PIE (Tuas), slip road of BKE towards Woodlands when my lorry skidded and due to that I collided onto another lorry (YP7281D) and subsequently both our vehicles collided onto the barrier. Both the driver and I then went out of our vehicles to check on one another. Both the driver and I were unhurt due to the incident. The traffic police came to the scene not long after. Both the driver and I then left the scene after we were told we could leave by the traffic police. My vehicle sustained slight damages to the front portion of the lorry whereas the other lorry sustained slight damages to the center right portion and the front bumper. I am now lodging this report for insurance claims

Individual Statement



SINGAPORE  
POLICE FORCE



T/20180310/2139

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689288  
Tel No: 1800-7659999

3 of 3

Report No. T/20180310/2139

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 85474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sgt 2 YAO MING YANG, CASIMIR
Signature Of Interpreter: Not applicable
Officer in Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMAD ABDILLAH BIN PALIL Contact No: 65476246

Signature Of Informant: 
Date/Time: 10/03/2018 17:38
Classification Of Case:

Authentication Stamp  
NP168

SINGAPORE POLICE FORCE

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
 6 Raffles Quay #04-01A SINGAPORE 048582  
 Tel: (65) 6224 2222 Fax: (65) 6224 2222  
 Operating Hours: Monday to Friday, 10:00am - 12:00pm  
 and 1:00pm to 5:00pm. Reg. No. V08021728

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with which you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: 190518004018 Vehicle Registration No: SR652237  
 Name of Insured: Ms E. Indira Angaranj NRIC/IN/Passport No: 2017181583  
 [\*Vehicle Driver / Vehicle Owner] [\*] Please delete as appropriate  
 Address: 7030 Bukit Kechil Road #2-192 Singapore (09515)  
 Contact (Tel): \_\_\_\_\_ Mobile No: \_\_\_\_\_  
 Email Address: ms18brngan@com.sg  
 Date of Accident: 12/1/18 Time of Accident: 1:00pm  
 Place of Accident: 170, Tanjong Pagar Working Rd.  
 Insurance Company: MSA Insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Attached form report

\_\_\_\_\_  
 Policyholder / Driver's Signature  
 Date: \_\_\_\_\_

\_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name: \_\_\_\_\_  
 NRIC/IN No: \_\_\_\_\_  
 Date: \_\_\_\_\_



# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

INSURER: **AIG Asia Pacific Insurance Pte. Ltd. (SG)**

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	2100392147-03	Date of Loss:	10/03/2018
Vehicle Reg. No.:	GBC3223P	Driveable?	
Driver Age/Info:	31 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	A&A CONSTRUCTION & ENGINEERING PTE LTD	Contact No:	+6598222145
Driver:	LAU JASON		

Make/Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Vehicle Reg. Date:	14/11/2011
Vehicle Colour:	WHITE	Chassis No:	JTFAT35Y00K201811
Engine No:	1KD2135388		
Odometer:	0 KM		

Paint Type:	
List Item Discount:	25.00 %
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	8

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Date:

Description of Accident/Loss	REFER TO POLICE REPORT
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)

Tanpin 97495249  
Ex: to be advise  
Revert, Not Authorise  
11/4/18 @ 2:15pm  
8 days  
sur@lkkauto.com  
Resurvey after paint  
humpun.

## COST OF CLAIMS

	Amount
Parts	5,902.50
Miscellaneous Items	620.00
Labour	4,010.00
Paintwork Labour	0.00
Towing	0.00
<b>Calculated Gross Total (\$\$)</b>	<b>10,532.50</b>
<b>- Excess (\$\$)</b>	<b>1,300.00</b>
<b>Nett Amount (\$\$)</b>	<b>9,232.50</b>

This claim is handled by: **CHUA SYAHIRUL SYAZWANI BINTE IRWAN**



**REPAIR DETAILS**

## Reference

**Part Source:** (Last Synchronised: 09 Apr 2018)**Parts:** N/A TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBC3223P)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	25.00	0.00	Rx 400.00 FL
2	1		*FRONT DOOR ASSY	25.00	0.00	ht 1,685.00 FL ✓
3	1		*FRONT DOOT INNER TRIM BOARD LHS	25.00	0.00	? *550.00 FL X n
4	1		*FRONT DOOR WEATHER STRIP	25.00	0.00	nd *195.00 FL ✓
5	1		*FRONT DOOR HINGE BOTTOM LHS	25.00	0.00	ht 100.00 FL ✓
6	1		*FRONT DOOR HINGE TOP LHS	25.00	0.00	? *100.00 FL X n
7	1		*HEADLAMP LHS	25.00	0.00	cre *620.00 FL ✓
8	1		*HEADLAMP RHS	25.00	0.00	X *620.00 FL n
9	1		*FRONT DOOR STEP INNER PANEL LHS	25.00	0.00	Rx *420.00 FL
10	1		*FRONT DOOR STEP GARNISH LHS	25.00	0.00	X *365.00 FL n
11	1		*FRONT CORNER PANEL LHS	25.00	0.00	bt 325.00 FL ✓
12	1		*FRONT CORNER GARNISH LHS	25.00	0.00	mt 150.00 FL ✓
13	1		*FRONT GRILLE	25.00	0.00	cr 500.00 FL ✓
14	1		*FRONT GRILLE LOGO	25.00	0.00	nd *95.00 FL ✓
15	1		*FRONT WINDSCREEN GLASS	25.00	0.00	ht 1,400.00 FL ✓
16	1		*FRONT WINDSCREEN GLASS RUBBER	25.00	0.00	nd *295.00 FL ✓
17	1		*WIPER BLADE	25.00	0.00	X n *50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,870.00
- List Item Discount on L Items (S\$)	1,967.50
<b>Total Parts (S\$)</b>	<b>5,902.50</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	COMPANY REGISTRATION STICKER	nc 25.00
2	1	IU BRACKET	nc 20.00
3	1	REAR MUDFLAP LHS	h 100.00
4	1	REAR MUDGUARD LHS	bt 250.00
5	1	REAR NUMBER PLATE	nn X 20.00
6	1	REAR TAIL GATE L-BRACKET LHS	bt 130.00
7	1	REAR TAIL GATE STOPPER LHS	nc 75.00
Sub Total (S\$)			<b>620.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO PANEL BEAT & REALIGN VEHICLE DAMAGED AREA	New	1000 1,800.00
2	TO CHECK FOR & RECTIFY WIRING FAULTS	New	30. 150.00
3	TO REMOVE & REFIX WINDSCREEN	New	nc ✓ 120.00
4	TO REMOVE & TRANSFER FRONT DOOR COMPARTMENTS	New	60 180.00
5	TO CARRY OUT WHEEL ALIGNMENT TEST	New	nn X 180.00
6	TO CARRY OUT SPRAY PAINTING ON REPAIR AREA	New	1000 1,500.00
7	SUNDRIES	New	30. 80.00
Gross Labour Cost (S\$)			<b>4,010.00</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >





# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

INSURER: **AIG Asia Pacific Insurance Pte. Ltd. (SG)**

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	2100392147-03	Date of Loss:	10/03/2018
Vehicle Reg. No.:	<b>GBC3223P</b>	Driveable?	
Driver Age/Info:	31 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	A&A CONSTRUCTION & ENGINEERING PTE LTD	Contact No:	+6598222145
river:	LAU JASON		
Make/Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Vehicle Reg. Date:	14/11/2011
Vehicle Colour:	WHITE		
Engine No:	1KD2135388	Chassis No:	JTFAT35Y00K201811
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO POLICE REPORT		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

Tanpin 97495749  
Ex: to be advise  
Revert, Not Authoris  
11/4/18 @ 2:15pm  
8 days  
Sur @ 11/4/18 to com.  
Resumy after paint  
being done.

## COST OF CLAIMS

	Amount
Parts	5,902.50
Miscellaneous Items	620.00
Labour	4,010.00
Paintwork Labour	0.00
Towing	0.00
<b>Calculated Gross Total (S\$)</b>	<b>10,532.50</b>
- Excess (S\$)	1,300.00
<b>Nett Amount (S\$)</b>	<b>9,232.50</b>

This claim is handled by: **CHUA SYAHIRUL SYAZWANI BINTE IRWAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** (Last Synchronised: 09 Apr 2018)  
**Parts:** N/A TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for GBC3223P)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	25.00	0.00	Rx 400.00 FL
2	1		*FRONT DOOR ASSY	25.00	0.00	bt 2,685.00 FL
3	1		*FRONT DOOR INNER TRIM BOARD LHS	25.00	0.00	X *550.00 FL
	1		*FRONT DOOR WEATHER STRIP	25.00	0.00	rt 195.00 FL
5	1		*FRONT DOOR HINGE BOTTOM LHS	25.00	0.00	bt 100.00 FL
6	1		*FRONT DOOR HINGE TOP LHS	25.00	0.00	X *100.00 FL
7	1		*HEADLAMP LHS	25.00	0.00	cr 620.00 FL
8	1		*HEADLAMP RHS	25.00	0.00	X *620.00 FL
9	1		*FRONT DOOR STEP INNER PANEL LHS	25.00	0.00	Ry *420.00 FL
10	1		*FRONT DOOR STEP GARNISH LHS	25.00	0.00	X *365.00 FL
11	1		*FRONT CORNER PANEL LHS	25.00	0.00	bt 325.00 FL
12	1		*FRONT CORNER GARNISH LHS	25.00	0.00	out 150.00 FL
13	1		*FRONT GRILLE	25.00	0.00	inv 500.00 FL
14	1		*FRONT GRILLE LOGO	25.00	0.00	net 95.00 FL
15	1		*FRONT WINDSCREEN GLASS	25.00	0.00	net 1,400.00 FL
16	1		*FRONT WINDSCREEN GLASS RUBBER	25.00	0.00	net 295.00 FL
17	1		*WIPER BLADE	25.00	0.00	Y *50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,870.00
- List Item Discount on L Items (S\$)	1,967.50
<b>Total Parts (S\$)</b>	<b>5,902.50</b>

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

Parts : \$5365 - 25%  
 = \$4023.75  
 s/n \$600  
 Labour : \$2120  
 Total : \$4023.75 + \$600 + \$2120  
 = \$6743.75  
 L/S% = \$6743.75 - 20%  
 = \$5395

Resurvey  
 by  
 24/4/18  
 R Nam

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	COMPANY REGISTRATION STICKER	new 25.00
2	1	IU BRACKET	new 20.00
3	1	REAR MUDFLAP LHS	100.00
4	1	REAR MUDGUARD LHS	250.00
5	1	REAR NUMBER PLATE	20.00
6	1	REAR TAIL GATE L-BRACKET LHS	130.00
7	1	REAR TAIL GATE STOPPER LHS	new 75.00
<b>Sub Total (S\$)</b>			<b>620.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO PANEL BEAT & REALIGN VEHICLE DAMAGED AREA	New	1000 1,800.00
2	TO CHECK FOR & RECTIFY WIRING FAULTS	New	30. 150.00
3	TO REMOVE & REFIX WINDSCREEN	New	120.00
4	TO REMOVE & TRANSFER FRONT DOOR COMPARTMENTS	New	60 180.00
5	TO CARRY OUT WHEEL ALIGNMENT TEST	New	8. 180.00
6	TO CARRY OUT SPRAY PAINTING ON REPAIR AREA	New	1000. 1,500.00
7	SUNDRIES	New	30. 80.00
<b>Gross Labour Cost (S\$)</b>			<b>4,010.00</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Mar 2018 <a href="#">Sendback Est</a>	09 Apr 2018 15:27 <b>S\$10,532.50</b>	09 Apr 2018 15:27 <a href="#">Edit Adj Rpt</a>	<b>S\$5,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

  

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

  

CLAIM SUBFOLDER DETAILS	
Insured:	<b>ABA CONSTRUCTION &amp; ENGINEERING PTE LTD</b> , Co. Reg. No.: 200713458Z, Tel: +6598222145
Vehicle Reg. No.:	<b>GBC3223P</b>
Claim Type:	<b>OD / 7439944572SG</b>
Date of Loss:	10/03/2018 12:00 - :59 [75 Months and 24 Days From LTA Reg Date (Man Yr)]
Policy/Cover Note No.:	2100392147 (Comprehensive)
Excess:	S\$1,300.00
Repairer:	<b>Goldbell Engineering Pte Ltd (Tuas)</b> 29, Tanjong Penjuru, 609026 West Coast - Tel: 6864 0695
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tr, Tinesh</b> ] Tinesh.Tr@aig.com
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 18/04/2018]
Driver/Custodian:	LAU JASON (31 / Male), NRIC: S8620436C, Tel: +6598222145
Adj. Remarks:	Auto-assignment

  

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

  

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

GBC3223P (74399445725G)

OD

Mar 10 2018 12:00PM

[A&A CONSTRUCTION & ENGINEERING PTE LTD]

Goldbell Engineering Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			View	View in Browser <input type="checkbox"/>
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
1	09/04/18 15:27	Repairer Estimates	 Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 14:20	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	24/05/18 14:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
36	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/05/18 14:20	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 15:59	ESTIMATE	 Load PDF	

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
1	12/03/18 15:37	Accident Statement	 Load HTM	
2	13/03/18 15:19	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	13/03/18 15:20	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
1	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	12/03/18 15:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
1	12/03/18 15:37	<b>Sketch Plan</b>	 Load JPG	<input checked="" type="checkbox"/>
2	12/03/18 15:37	<b>Sketch Plan #2</b>	 Load JPG	<input checked="" type="checkbox"/>
3	13/03/18 15:19	<b>Individual Statement</b> Police report	 Load JPG	<input checked="" type="checkbox"/>
4	13/03/18 15:20	<b>Individual Statement</b> Police report	 Load JPG	<input checked="" type="checkbox"/>
5	13/03/18 15:20	<b>Individual Statement</b> Police report	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG18006559/T1QD3E2

**Date:** 25/05/2018

#### REFERENCE

Insured/Claimant: A&A CONSTRUCTION & ENGINEERING PTE LTD Policy No: 2100392147

Date of Loss: 10/03/2018

Nature of Claim: OD

Claim No: 7439944572SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBC3223P</b>	Engine No:	1KD2135388
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Chassis No:	JTFAT35Y00K201811
Reg. Date:	14/11/2011 (Man. Year: 2011)	Odometer:	217991 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$36,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R17 (D)
Front Left Side:	Condor 6 mm	Rear Left Side:	Condor 6/6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Condor 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,902.50	4,023.75	1,878.75	31.83
Miscellaneous Items	620.00	610.00	10.00	1.61
Labour	4,010.00	2,240.00	1,770.00	44.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,532.50</b>	<b>6,873.75</b>	<b>3,658.75</b>	<b>34.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>- Excess (S\$)</b>	1,300.00	1,300.00	0.00	0.00
<b>(S\$)</b>	9,232.50	4,100.00	5,132.50	55.59
<b>+ GST 0.00/7.00% (S\$)</b>	0.00	287.00	-287.00	
<b>Nett Amount (S\$)</b>	<b>9,232.50</b>	<b>4,387.00</b>	<b>4,845.50</b>	<b>52.48</b>

#### INSPECTION

Date of Assignment:	09/04/2018	Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	11/04/2018	Inspected At:	29, Tanjong Penjuru Singapore 609026
Estimated Period of Repair:	8.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	400.00 FL	*- FL
2	1		*FRONT DOOR ASSY	Bent	1,685.00 FL	*1,685.00 FL
3	1		*FRONT DOOR INNER TRIM BOARD LHS	Not Necessary	550.00 FL	*- FL
4	1		*FRONT DOOR WEATHER STRIP	Necessary	195.00 FL	*195.00 FL
5	1		*FRONT DOOR HINGE BOTTOM LHS	Bent	100.00 FL	*100.00 FL
6	1		*FRONT DOOR HINGE TOP LHS	Not Necessary	100.00 FL	*- FL
7	1		*HEADLAMP LHS	Cracked	620.00 FL	*620.00 FL
8	1		*HEADLAMP RHS	Not Necessary	620.00 FL	*- FL
9	1		*FRONT DOOR STEP INNER PANEL LHS	Repair	420.00 FL	*- FL
10	1		*FRONT DOOR STEP GARNISH LHS	Not Necessary	365.00 FL	*- FL
11	1		*FRONT CORNER PANEL LHS	Bent	325.00 FL	*325.00 FL
12	1		*FRONT CORNER GARNISH LHS	Cut	150.00 FL	*150.00 FL
13	1		*FRONT GRILLE	Cracked	500.00 FL	*500.00 FL
14	1		*FRONT GRILLE LOGO	Necessary	95.00 FL	*95.00 FL
15	1		*FRONT WINDSCREEN GLASS	Cracked	1,400.00 FL	*1,400.00 FL
16	1		*FRONT WINDSCREEN GLASS RUBBER	Necessary	295.00 FL	*295.00 FL
17	1		*WIPER BLADE	Not Necessary	50.00 FL	*- FL

F=Franchise part, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,870.00</b>	<b>5,365.00</b>
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,967.50	1,341.25
<b>Total Parts (\$\$)</b>	<b>5,902.50</b>	<b>4,023.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	COMPANY REGISTRATION STICKER (NECESSARY)	25.00	25.00
2	1	IU BRACKET (NECESSARY)	20.00	20.00
3	1	REAR MUDFLAP LHS (TORN)	100.00	100.00
4	1	REAR MUDGUARD LHS (BENT)	250.00	250.00
5	1	REAR NUMBER PLATE (NOT NECESSARY)	20.00	0.00
6	1	REAR TAIL GATE L-BRACKET LHS (BENT)	130.00	130.00
7	1	REAR TAIL GATE STOPPER LHS (MISSING)	75.00	75.00
8	1	OD/TP Case (Insurer)	-	10.00
<b>Sub Total (S\$)</b>			<b>620.00</b>	<b>610.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT & REALIGN VEHICLE DAMAGED AREA	New	1,800.00	1,000.00
2	TO CHECK FOR & RECTIFY WIRING FAULTS	New	150.00	30.00
3	TO REMOVE & REFIX WINDSCREEN	New	120.00	120.00
4	TO REMOVE & TRANSFER FRONT DOOR COMPARTMENTS	New	180.00	60.00
5	TO CARRY OUT WHEEL ALIGNMENT TEST	New	180.00	0.00
6	TO CARRY OUT SPRAY PAINTING ON REPAIR AREA	New	1,500.00	1,000.00
7	SUNDRIES	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>4,010.00</b>	<b>2,240.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;