

7/03/2003

ASS. REC. BY:

REF: es/FCI 18 006660 / Agd37

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

CWS

From (Person):

Sithara

of

FCI

Date/Time: 09/04/18 @ 5:13pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 8982B

Insured:

SHA 0241X

at Workshop m/s

Hui Huing Hong Bao

Tel:

97322 326

of

2kaki Blk Ave 2 #02-11

Policy No:

Claim No:

D18002746MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/04/2018

11/04/2018 @ Morning

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

'wp'

Date/Time:

9:02am @ 10/04/18

Person Contacted:

Alison

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLR 8982B -X

SHA 0241X -X.

12/4/18 @

5:03pm informed Sithara, we are pending estimate from repairer.

24/4/18 @

10:30am revised to Sithara by email.

Total est \$350, 2 days (Red \$750, 47%).

REF: FCI

ASSIGNMENT

From:

Date: 11/4/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLR 8982B

at Workshop m/s Hui Huang Hong Bao
of 2 Kaki Bkt Ave 2 # 02-11

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR 8982B

Yr Regn: 30 Aug, 17

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle

c.c. 1496

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 28796

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 6P71114691

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

205/50R16

R:

205/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal.

d

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

11/04/18

Survey held at

Hui Huang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 APR 2018

Date/Time. File Pass to?

☐

Preli. Report

11/24/4 lwp

Final Report

Date/Time. File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS) SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 7P 350

90
50
15
155



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002746MFSH

Date: 24 April 2018

Our Ref: CS/FCI18006560/Aqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 8982B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/04/2018 at the premises of M/s HUI HUANG HONG BAO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>600.00</u>
Revised Estimate Amount	: S\$ <u>350.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng. AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	06-04-2018	Our Ref No. D18002746MFSH
Accident Date	04-04-2018	Claim Type. Third Party
Insured Vehicle	SHA0241X	Third Party Vehicle. SLR8982B
Survey Location	2KAKI BULKIT AVENUE 2 #02-11 KAKI BULKIT @AUTOHUB	
Contact Person.	ALISON	
Contact No.	0/ 97322326	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI HUANG HONG BAO MOTORS	Attention. NIL
Cc : TP Solicitor	M NEDUMARAN & CO	TP Solicitor Fax No. 65098482
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236732)



PRI Documents



Close



PRI Header Details

Claim No	D18002746MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & M NEDUM
Workshop Name	HUI HUANG HONG BAO MOTORS (Contact Person : ALISON)	Survey Location & Contact Details	2KAKI BULKIT AVENUE 2 #02-11 KAKI BULKIT @AUTO- Mobile: 97322326 , Phone: 0 , Fax: 0 EmailId: IGENE.LIM@MNEDUCO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0241X	TP Vehicle No	SLR8982B
PRI Recieved Date	06-04-2018 08:24:32 PM	Surveyor Appointed Date	09-04-2018 05:12:10 PM	Surveyor Accept Date	10-04-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	10-04-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 24 April 2018 10:30 AM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002746MFSH/1
Attachments: CSFCI18006560Aqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLR 8982B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 12 April 2018 5:03 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002746MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SLR 8982B on 11/04/2018.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 10 April 2018 9:06 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002746MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 12 April 2018 5:03 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002746MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SLR 8982B on 11/04/2018.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 10 April 2018 9:06 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002746MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 9 April 2018 5:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002746MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

➡ **Branch Office:** 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/H2/1812327/st
Your Reference : SHA 241X

Date : 6th April 2018

BY EMAIL: motor_claims@first-insurance.com.sg ONLY

FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road,
#16-01, City House
Singapore 068877

Dear Sirs,

1. **NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**
2. **ACCIDENT ON 4/4/2018 INVOLVING VEHICLE NOS. SLR 8982B AND SHA 241X ALONG PHILIP STREET.**

We are instructed by POPULAR RENT A CAR PTE LTD (owners of motor vehicle no. SLR 8982B) and/or HUI HUANG HONG BAO MOTORS (the motor workshop for SLR 8982B) to notify you of a road traffic accident on 4/4/2018 at about 1530 hours along PHILIPS STREET involving our client's vehicle registration number [SLR 8982B] and [SHA 241X] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO
(Branch Office)
c.c. 1) CITYCAB PTE LTD

(Vehicle : SHA 241X)

- 2) **NAME OF WORKSHOP :**
HUI HUANG HONG BAO MOTORS
2 Kaki Bukit Avenue 2
#02-11 Kaki Bukit @ AutoHub
Singapore 417921
Telephone : 9732 2326/ 8102 5571

(Vehicle : SLR 8982B)

(Attention : Alison)

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhhhb@gmail.com

M/s Popular Rent A Car Pte Ltd
501 Guillemard Road
Singapore 399840

TP 1st Cap.

Xiao Chen.

9th April 2018

Estimate cost of repairs to Honda Shuttle - SLR 8982 B

Labour charges to remove, repair and refit rear bumper

\$ ~~300.00~~ 150

Spray painting

\$ ~~300.00~~ 200

\$ 600.00

Dollars : Six hundred only.

total : 350 (P/P)
02 Aug

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006560/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 241X	Veh. Inspected	SLR 8982B	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18002746MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	09/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GP71114691	Colour	BLACK	
Odometer	28796	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	FALKEN	6 mm	
L/H Front Tyre	205/50 R16	FALKEN	6 mm	
R/H Rear Tyre	205/50 R16	FALKEN	6 mm	
L/H Rear Tyre	205/50 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2018	Inspection Date	11/04/2018	
Survey held at	HUI HUANG HONG BAO MOTORS 2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8982B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES TO REMOVE,REPAIR AND REFIT REAR BUMPER.		300.00	150.00
	SPRAY PAINTING.		300.00	200.00
			600.00	350.00
	GRAND TOTAL		600.00	350.00
RECOMMENDED COST OF REPAIRS				350.00

Report Ref No. CS/FCI18006560/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.