

REF:

NS/TNC18006569 / Sgdn2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: Fm 6777M

Policy No. 50 75388 265-02 02.11.17 - 01.11.18

Claims No. MT/0989884-02

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No.

SHB5952P

Yr Regn:

19/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius 4

C.C.

1798

Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: 35476

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTOKB3154203517916

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU4 PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 6/4/18

D.O.I. 9/4/18

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 5152P - 03/LCR/1005276 / Klnb3

DUN 130317

TAX/04/18/2033

FM 6777M - X

LEK

NTUC

Klnal sig 5 32/18.51 (Red 8 22/29, Fr 6/2)

FM 6777M

RECEIVED 5 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

11/4/2018

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

Transportation.

) S + RS SI

) Photos

) Other

/

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 3278.51

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

160

35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006569/Sqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-04-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FM 6777M	Veh. Inspected	SHB 5952P
Policy No.	5075388265-02	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/04/2018	Inspection Date	09/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0989874-002	SMRT TAXIS PTE LTD	SHB 5952P	FM 6777M	06/04/2018
2	MT/0988647-002	SMRT TAXIS PTE LTD	SHB 1892E	SKE 5210X	30/03/2018
3	MT/0986581-002	SMRT BUSES LTD	SG 1713H	SKQ 9751L	17/03/2018

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident:

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5075388265-02	SARAVANAN S/O NADARAJAN	S8403575J	GMC	Third Party	FM6777M	FM6777M	02/11/2017	01/11/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2018 11:15
Date Of Accident	06/04/2018 08:30
Exact Location Of Accident	CTE TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5952P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	GOH KOK SIONG
NRIC No	S1150234B
Date Of Birth	04/03/1956
Occupation	OUTDOOR
Date Of Driving Pass	18/05/1974
Driving Experience	43 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	22
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180406/2071 I am a taxi driver, my vehicle plate number is SHB5952P. On 06/04/18 at about 0830hrs, I was travelling on CTE towards AYE on the first lane going to send my passenger to Indonesian Embassy. There was a motorcycle cycling behind me. As there was a heavy jam in front, my vehicle came to a stop. Suddenly, I felt something hit onto the rear of my car. I came down to see what happened immediately and I saw the motorcyclist who was travelling behind me lying on the floor. He was unable to move and was bleeding. Someone else called for the police and ambulance. When the ambulance reached, the motorcyclist was conveyed to the hospital. I did not managed to get the particulars of the motorcyclist. My rear bumper of my vehicle suffered some damages. The rear left portion of my vehicle suffered several dents and scratches. My passenger was not injured. I felt pain in my neck and went to see a doctor at a clinic. There is a in car camera in my vehicle and it managed to captured down the entire process of the accident. I was then told by the Traffic Police to lodge a Traffic Accident report at a police center.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FM6777M
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

UNKNOWN RIDER

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FM6777M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

6/4/20

SKETCH PLAN



A - SHB5952P

R - FM 6777M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 7/20180406/2171

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

6/4/2018



**SINGAPORE
POLICE FORCE**



T/20180406/2071

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

1 of 3

Report No. T/20180406/2071

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/04/2018 13:38		Vide Report No.: E/20180406/0055		Station Diary No.: 78	
Name of Informant: GOH KOK SIONG			Address: APT BLK 22 HAVELOCK ROAD #06-707 SINGAPORE 160022		
ID Type / ID No.: NRIC NO / S1150234B			Contact No.: Home/Office: Mobile: 96876749		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 04/03/1956	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 06/04/2018 08:30	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY Towards AYE, after Ang Mo Kio Avenue 5				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FM6777M	Motorcycle				Seriously Damaged	0
SHB5952P	Car	TOYOTA	PRIUS	Maroon	Slightly Damaged	1

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Scanned with CamScanner



**SINGAPORE
POLICE FORCE**



T/20180406/2071

2 of 3

Report No. T/20180406/2071

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

CONTINUATION OF REPORT

Name	GOH KOK SIONG /	ID No.	S1150234B
Related Vehicle	SHB5952P (Car)	Contact No.	96876749
Hospital/Clinic	CENTRAL 24-HR CLINIC (WOODLANDS)	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	06/04/2018	Date Discharge	06/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

I am a taxi driver, my vehicle plate number is SHB5952P.

On 06/04/18 at about 0830hrs, I was travelling on CTE towards AYE, on the first lane, going to send my passenger to Indonesian Embassy. There was a motorcycle cycling behind me. As there was a heavy jam in front, my vehicle came to a stop. Suddenly, I felt something hit onto the rear of my car. I came down to see what happened immediately and I saw the motorcyclist who was travelling behind me lying on the floor. He was unable to move and was bleeding. Someone else called for the police and ambulance. When the ambulance reached, the motorcyclist was conveyed to the hospital. I did not managed to get the particulars of the motorcyclist.

My rear bumper of my vehicle suffered some damages. The rear left portion of my vehicle suffered several dents and scratches. My passenger was not injured. I felt pain in my neck and went to see a doctor at a clinic. There is a in car camera in my vehicle and it managed to captured down the entire process of the accident. I was then told by the Traffic Police to lodge a Traffic Accident report at a police center.

Scanned with CamScanner



**SINGAPORE
POLICE FORCE**



T/20180406/2071

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

3 of 3

Report No. T/20180406/2071

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: 130

J /

CHEN



Signature :

Signature Of Interpreter:

Not applicable

Singapore Police Force

Signature Of Informant:

Date/Time:

06/04/2018 13:38

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED SUFIAN BIN SUDIN

Contact No.: 65476367

Classification Of Case:

Authentication Stamp

NP158

Scanned with CamScanner

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5952P
Vehicle to be Exported:	No
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8267236
Chassis No.:	JTDKB3FU203577416
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$32,827.00
Total Rebate Amount:	\$36,577.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Apr 2018

OK

SMRT Accident Vehicle Repair Estimates

NTUC

C-117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5952P
 Ref. No : TAX/04/18/2033
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : GOH KOK SIONG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 06/04/2018 08:30:00 AM
 Accident Reported Date / Time : 06/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095420
 Special Instruction to ARC, if any :
 FM6777M
 Prepared Date : 06/04/2018 11:54:25 AM



Sebastian
9/4/18

- Part by part repair.
- Question mark Item Photo.
- Photo ~~After~~ Paint Before

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU203577416

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 2,034.00	0.00
Total Material Charges	: 5,766.56	5,766.56
Other Charges	: 1,260.00	0.00
TOTAL	: 10,074.56	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sign Off Date	: 06/04/2018 05:00:08 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/04/2018 04:58:45 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 4/6/2018 5:00:42 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	0.00 500
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 7
TO RESPRAY TAIL GATE	378.00	0.00 X
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 7
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 7
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 50
TO RESPRAY REAR FENDER LH	378.00	0.00 X
Total Spray Painting & Panel Beating	2,034.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,260.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
52462470 30			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace	No
52462470 20			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace	No
52462470 10			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52592470 40			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace	No
90467170 26A0			CLIP, FLOOR UNDER COVER, NO.1	10	2.60	25.00	19.50	Replace	Replace	No
90467170 27C0			CLIP, FLOOR UNDER COVER, NO.2	10	3.20	25.00	24.00	Replace	Replace	No
52566479 00			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace	No
58399470 30			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.72	Replace	Replace	No
66259470 10			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No
81591470 10			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No
67005474 40			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
56117501 40			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace	No
75571470 10			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No
75575470 51			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77	Replace	Replace	No
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
75441470 90			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
5831647010			EXTENSION, REAR FLOOR SIDE PANEL, LH	1	76.20	25.00	57.15	Replace	Replace	No
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No
6563847060			LINER, REAR FENDER, LH	1	135.80	25.00	101.85	Replace	Replace	No
TOTAL MATERIALS								5,766.61	5,766.56	
TOTAL MATERIALS(Discounted)								5,766.56	5,766.56	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5952P
 Ref. No : TAX/04/18/2033
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : GOH KOK SIONG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 06/04/2018 08:30:00 AM
 Accident Reported Date / Time : 06/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095420
 Special Instruction to ARC, if any :
 FM6777M NTUC PIP
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
 & Email : sebastianyeang @lkkauto.com HP: 90036121
 Prepared Date : 06/04/2018 11:54:25 AM



QC 13/4/18 11.25 reject Sensor Reverse Faulty
 15.56 pass

Recording Camera ☐ ☒
 Radio Antenna ☐ ☒
 1st witness _____ Date 11-4-18
 2nd witness _____ Date _____

E 1/2 F
 KM 35476

Vehicle to Wega Date In: 9/4	Towing: _____
Time In: 7:18	Driver: Hwa
Wega Job No: 04 0228	
Vehicle sent to SMRT Date In: 13/4/18	Towing: _____
Time to: 1005	Driver: N
Received by (SMRT): _____	

Supplymetry Rear Reverse Sensor 13/4/18

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU203577416

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,014.00	500.00
Total Spray Painting Charges	2,034.00	350.00
Total Material Charges	3,407.00	2,288.50
Other Charges	1,260.00	140.00
TOTAL	7,715.00	3,278.50
Lum Sum Total	0.00	0.00
No. of Repair Days	6.00	4.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	06/04/2018 05:00:08 PM	09/04/2018 03:48:58 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/04/2018 04:58:45 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0341

Quotation Date : 16/4

Invoice Amount : 0.00

Invoice No :

Invoice Date :

Prepared Date : 4/6/2018 5:00:42 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	500.00 /
Total Labour	1,014.00	500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY FILLER RR BUMPER LH	180.00	50.00 /
TO RESPRAY REAR FENDER LH	378.00	0.00
Total Spray Painting & Panel Beating	2,034.00	350.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,260.00	140.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No	✓
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No	✓
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Check	No	X
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Check	No	X
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Check	No	X
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Check	No	X
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace S	No	✓
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No	✓
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Check	No	X
9046717026A0			CLIP, FLOOR UNDER COVER, NO.1	10	2.60	25.00	19.50	Replace	Check	No	X
9046717027C0			CLIP, FLOOR UNDER COVER, NO.2	10	3.20	25.00	24.00	Replace	Check	No	X
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace	No	✓
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.73	Replace	Replace S	No	✓
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Check	No	X
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Check	No	X
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No	✓
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Check	No	X
8159147010			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No	✓
5257647040			RETAINER, RR BUMPER, LH	0	111.50	25.00	0.00	Replace	Not given	No	X
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	0	929.60	25.00	0.00	Replace	Not given	No	X
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	100.00	0.00	Replace	Repair	No	✓
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	0	27.90	25.00	0.00	Replace	Not given	No	X
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	0	29.70	25.00	0.00	Replace	Not given	No	X
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	0	19.70	25.00	0.00	Replace	Not given	No	X
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No	✓
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No	✓

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No ✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
5831647010			EXTENSION, REAR FLOOR SIDE PANEL , LH	1	76.20	25.00	57.15	Replace	Check	No X
8156147151			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	10.00	394.29	Replace	Replace	No ✓
6160247160			PANEL SUB-ASSY, FENDER REAR LH	0	824.80	25.00	0.00	Replace	Not given	No X
6563847060			LINER, REAR FENDER , LH	0	135.80	25.00	0.00	Replace	Not given	No X
TOTAL MATERIALS							3,407.04	2,288.51		
TOTAL MATERIALS(Discounted)							3,407.00	2,288.51		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2288.51 /
 + 500.00 /
 + 490.00 /

 3278.51 /

11550.80

Sebastian
 23/4/18



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006569/Sqbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 02-05-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FM 6777M	Veh. Inspected	SHB 5952P
Policy No.	5075388265-02	Coverage (\$)	0.00
Claim No.	MT/0989874-002	Excess (\$)	0.00
Assign From		Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS 4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU203577416	Colour	MAROON
Odometer	35476	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/04/2018	Inspection Date	09/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5952P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER RR BUMPER ASSY (DISC 25%)	CRACKED	423.90	317.92
10	CLIPS PIECE,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	FILLER RR BUMPER LH (DISC 25%)	MISSING	119.90	89.92
1	COVER REAR FLOOR UNDER,LH (DISC 25%)	DEFORMED	234.30	175.73
1	GUARD RR BUMPER LOWER (DISC 25%)	PUNCTURE	558.30	418.72
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	LENS & BODY ASSY,RR BUMPER LH (DISC 10%)	SCRATCHED	486.80	438.12
1	LENS & BODY REAR COMBINATION LAMP LH (DISC 10%)	SCRATCHED	438.10	394.29
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
2	PAD,RR BUMPER RH & LH,1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER RH & LH,2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER RH & LH,3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL,RR BUMPER ARM RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	SEAL,RR BUMPER LH	NOT NECESSARY	85.20	-
10	CLIP,FLOOR UNDER COVER NO 1 @\$2.60	NOT NECESSARY	26.00	-
10	CLIP,FLOOR UNDER COVER NO 2 @\$3.20	NOT NECESSARY	32.00	-
1	COVER REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
3	PAD,RR BUMPER CTR @\$2.20	NOT NECESSARY	6.60	-
1	RETAINER,RR BUMPER,LH	NOT NECESSARY	111.50	-
1	TAIL GATE PANEL SUB-ASSY,BACK DOOR	NOT NECESSARY	929.60	-
1	TAIL GATE DAM,BACK DOOR GLASS UPPER ADHESIVE	NOT NECESSARY	27.90	-
1	TAIL GATE MOULDING GLASS,BACK DOOR	NOT NECESSARY	29.70	-
1	TAIL GATE MOULDING LOWER GLASS,BACK DOOR	NOT NECESSARY	19.70	-

Report Ref No. NS/INC18006569/Sqbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	END PANEL SUB-ASSY,BODY LOWER BACK	NOT NECESSARY	629.80	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	EXTENSION REAR FLOOR SIDE PANEL,LH	NOT NECESSARY	76.20	-
1	PANEL SUB-ASSY,FENDER REAR LH	NOT NECESSARY	824.80	-
1	LINER,REAR FENDER,LH	NOT NECESSARY	135.80	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR	891.20	-
			7,242.80	2,288.51
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		2,014.00	610.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		2,134.00	380.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			4,308.00	990.00
	GRAND TOTAL		11,550.80	3,278.51
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,278.51

Report Ref No. NS/INC18006569/Sqbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.