

ASS. REC. BY:

REF: CS/FCI18006575/ Kvd3ⁿ² Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Serene Ter

of

FCI

Date/Time: 10/4/18 @ 8:57am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 658U

Insured:

SH 7039B

at Workshop m/s

Ah Lim Motor

Tel:

64563637

of

176 Sin Ming Drive #05-12

Policy No:

Claim No:

D18002242 MPFH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/03/18

13/04/18 @ 10am

CA / REV / REP. / REV 24 HRS

hwp

H.O.D. Endorsement:

Date/Time:

11:58am @ 10/4/18

Person Contacted:

Jane

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLV 658U - x

SH 7039B - CS/FCI16009011 / H/vbd1

D.O.A: 14/5/16

16/4/18

Email preli revised to FCI

24/5/18

LS \$850 confirmed (Red 492.55, 37b)

REF: FCI

ASSIGNMENT

From:

Date: 13/4/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 6584

at Workshop m/s

Ah Lim Motor

of 176 Sin Ming Drive # 05-12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

10am @ owner waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLV 6584 Yr Regn: 02 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru A) XV c.c. 1600

Colour:

M. P. White A/C: Insured / Std / NI / NA

Sp. Reading:

92595 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF1GP3KG5D G031921

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/55ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

8 mm

R/Bal.

7 mm

L/Bal.

8 mm

L/Bal.

7 mm

D.O.A.

17/3/18

D.O.I.

13/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/4 Rk pass to Customer

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 24/5- typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

CWS

Lump Sum / I.B.I. (\$

850/2

100
50
30
11
211



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006575/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7039B	Veh. Inspected	SLV 658U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002242MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	10/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/03/2018	Inspection Date		
Survey held at	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002242MFSH

Our ref: CS/FCI18006575/Kvd3

Date : 16/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 658U


We thank for your instruction on 10/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/4/2018 at the premises of M/s AH LIM MOTOR COMPANY and have the following to report:-

Workshop Estimate Amount	: S\$1,342.55
Revised Estimate Amount	: S\$1,069.35
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	19-03-2018	Our Ref No. D18002242MFSH
Accident Date	17-03-2018	Claim Type. Third Party
Insured Vehicle	SH7039B	Third Party Vehicle. SLV658U
Survey Location	176 SIN MING DRIVE #05-12 SIN MING AUTOCARE	
Contact Person.	JANE	
Contact No.	64563637/ 0	Fax No. 64563686
Survey Type	WITHOUT PREJUDICE: EST. COR - \$1,436.53	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236100)



PRI Documents



Close



PRI Header Details

Claim No	D18002242MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & AH LIM M
Workshop Name	AH LIM MOTOR COMPANY (Contact Person : JANE)	Survey Location & Contact Details	176 SIN MING DRIVE #05-12 SIN MING AUTOCARE Mobile: 0 , Phone: 64563637 , Fax: 64563686 EmailId: JANETEH@ALMSM.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: EST. COR - \$1,436.53		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7039B	TP Vehicle No	SLV658U
PRI Recieved Date	06-04-2018 08:48:37 PM	Surveyor Appointed Date	10-04-2018 08:55:57 AM	Surveyor Accept Date	10-04-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	10-04-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 16 April 2018 2:18 PM
To: 'Claim Workflow System'
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002242MFSH/1, SLV 658U
Attachments: SLV 658U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLV 658U
Date of survey: 13/4/2018
Number of days:2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 10 April 2018 12:01 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002242MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 10 April 2018 8:56 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002242MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7212Z

Vehicle Details

Vehicle No.: SLV658U
Vehicle to be Exported: No
Intended De-registration Date: 04 Apr 2018
Vehicle Make: SUBARU
Vehicle Model: XV 1.6I AWD CVT
Primary Colour: White
Manufacturing Year: 2013
Engine No.: FB16R734028
Chassis No.: JF1GP3KC5DG031921
Maximum Power Output: 84.0 kW (112 bhp)
Open Market Value: \$17,512.00
Original Registration Date: 27 Feb 2014
First Registration Date: 27 Feb 2014
Transfer Count: 1
Actual ARF Paid: \$12,512.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Feb 2024
PARF Rebate Amount: \$9,384.00

Intended COE Rebate Details

COE Expiry Date: 26 Feb 2024
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$71,564.00
COE Rebate Amount: \$42,198.00
Total Rebate Amount: \$51,582.00

The information contained herein is correct as at 03 Apr 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7137212Z**
 Name: **MOHD BASHIR BIN MOHAMAD**

Birth Date: **27 Sep 1971**
 Issue Date: **30 Sep 2003**

000877696C




REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S7137212Z**

MOHD BASHIR BIN MOHAMAD

Race: **INDIAN**
 Date of Birth: **27-09-1971**
 Country of Birth: **SINGAPORE**

Sex: **M**

S7137212Z





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class 3 **W**

he weight of **2500 kilograms**

PASS DATE: **05 Nov 1996**

NP 428A

Licence No: **S7137212Z**



S7137212Z

S7137212Z

Blood Group: **B+** Date of Issue: **26-07-1993**

APT BLK 543 JURONG WEST STREET 42 #07-51
 SINGAPORE 640543

NRIC No: **S7137212Z** Date: **13/06/2011** No: **6828755**







CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00002122 (Comprehensive - Classic Plan)

Car plate number: SLV658U

Chassis No.: JF1GP3KC5DG031921

Engine No.: FB16R734028

Your name (As the policyholder): Mohd Bashir Bin Mohamad

Coverage start date: 01/02/2018

Coverage end date: 31/01/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

- (a) You; and
- (b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: DBS Bank Ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 06/02/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : MOHD BASHIR BIN MOHAMAD
BLK 543 JURONG WEST ST 42
#07-51
SINGAPORE 640543

Estimate No: MCS1102362
Date: 06 Apr 2018
Policy No: PNPV2018-00002122
Veh Reg No: SLV658U
Make/Model: SUBARU XV 1.6A

ATTN:

Your Ref No: SLV658U
Claim Type: Third Party
Accident Date: 17/03/2018
TP Veh Reg No: SH7039B

Not Authorised
1. B. I
Resurvey B & paint
2 days

Estimate Repair Cost to Vehicle No :SLV658U

Description	Quantity	List Price	Amount
		SS	SS
Nett			
1 FRONT BUMPER	<i>Bulldozer</i> 1 PC	660.00	✓
2 FRONT BUMPER SIDE RETAINER - LH & RH	2 PC	48.00	✗
3 FRONT BUMPER CLIP	15 PC	61.50	✓
		769.50	
	Less 10%	76.95	692.55
LABOUR			
4 TO ALIGN AND REPLACE FRONT BUMPER	1 PC	400.00	<i>200</i>
5 TO SPRAY FRONT BHUMPER	1 PC	250.00	<i>220</i>
		650.00	650.00
		Total	SS 1,342.55
		Add GST @ 7%	93.98
		Total Amount Payable	SS 1,436.53

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FOUR HUNDRED THIRTY SIX AND CENTS FIFTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: MOHD BASHIR BIN MOHAMAD
BLK 543 JURONG WEST ST 42
#07-51
SINGAPORE 640543

Estimate No: MCS1102362
Date: 06 Apr 2018
Policy No: PNPV2018-00002122
Veh Reg No: SLV658U
Make/Model: SUBARU XV 1.6A

ATTN:

Your Ref No: SLV658U
Claim Type: Third Party
Accident Date: 17/03/2018
TP Veh Reg No: SH7039B

Not Authorised
1.2.1
Running By claim

2 days

Estimate Repair Cost to Vehicle No :SLV658U

Description	Quantity	List Price	Amount
		SS	SS
Nett			
1 FRONT BUMPER	<i>Bumper</i> 1 PC	660.00	✓
2 FRONT BUMPER SIDE RETAINER - LH & RH	2 PC	48.00	✓
3 FRONT BUMPER CLIP	15 PC	61.50	✓
		769.50	
	Less 10%	76.95	692.55
LABOUR			
4 TO ALIGN AND REPLACE FRONT BUMPER	1 PC	400.00	<i>200</i>
5 TO SPRAY FRONT BHUMPER	1 PC	250.00	<i>220</i>
		650.00	650.00
Total			SS 1,342.55
Add GST @ 7%			93.98
Total Amount Payable			SS 1,436.53

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FOUR HUNDRED THIRTY SIX AND CENTS FIFTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721

TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg

GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : MOHD BASHIR BIN MOHAMAD
BLK 543 JURONG WEST ST 42
#07-51
SINGAPORE 640543

Claim No: MCS1102362
No: MFS1102084
Date: 17 May 2018
Policy No: PNPV2018-00002122
Veh Reg No: SLV658U
Make/Model: SUBARU XV 1.6A

ATTN:

Your Ref No: SLV658U
Claim Type: Third Party
Accident Date: 17/03/2018
TP Veh Reg No: SH7039B

Repair Cost to Vehicle No (For Finalization):SLV658U

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Nett			
1 FRONT BUMPER	1 PC	660.00	
2 FRONT BUMPER CLIP	15 PC	61.50	
		721.50	
	Less 10%	72.15	649.35
LABOUR			
3 TO ALIGN AND REPLACE FRONT BUMPER	1 PC	200.00	
4 TO SPRAY FRONT BHUMPER	1 PC	220.00	
		420.00	420.00
Total			S\$ 1,069.35
Lump Sum Less 20%			-213.87
Sub Total			S\$ 855.48
Less Rounding			-5.48
Lum Sum Repair			S\$ 850.00
Less Excess			S\$ 0.00
Amount Before GST			S\$ 850.00
Add GST @ 7%			59.50
Total Amount Payable			<u>S\$ 909.50</u>

TOTAL: SINGAPORE DOLLAR NINE HUNDRED AND NINE AND CENTS FIFTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 13/04/2018

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore
AUTHORISED SIGNATURE

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006575/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7039B	Veh. Inspected	SLV 658U	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002242MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	10/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU XV (A)	c.c	1600	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JF1GP3KC5DG031921	Colour	METALLIC PEARL WHITE	
Odometer	92595	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 ZR17	KUMHO	8 mm	
L/H Front Tyre	225/55 ZR17	KUMHO	8 mm	
R/H Rear Tyre	225/55 ZR17	KUMHO	7 mm	
L/H Rear Tyre	225/55 ZR17	KUMHO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/03/2018	Inspection Date	13/04/2018	
Survey held at	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 658U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (N)	BUCKLED / DENTED SERVICEABLE NECESSARY	660.00	660.00
2	FRONT BUMPER SIDE RETAINER-LH & RH (N)		48.00	-
15	FRONT BUMPER CLIP (N)		61.50	61.50
	LESS 10% DISCOUNT		-76.95	-72.15
			692.55	649.35
	<u>LABOUR</u>			
	TO ALIGN AND REPLACE FRONT BUMPER.		400.00	200.00
	TO SPRAY FRONT BUMPER.		250.00	220.00
			650.00	420.00
GRAND TOTAL			1,342.55	1,069.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				850.00

Report Ref No. CS/FC118006575/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.