

ASS. REC. BY:

REP: CS/FCT 18006576/Klvd3n7

Date/Time:

Surveyor: Calvin

ASSIGNMENT (Office)

From (Person): Aung Yin Min

of FCI

Date/Time: 10/4/18 @ 12:33pm

Estimated Cost: Bill to:

OD / WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1859S

Insured: SHA 0456T

at Workshop m/s Premier Automotive

Tel: 65446682

of 23 Changi South Ave 2 # 03-02

Policy No: Claim No: D18002785MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 6/4/2018

CA / REV / REP / REV 24 HRS ^{lwp}

H.O.D. Endorsement:

Date/Time: 12:38pm @ 10/4/18 Person Contacted: Goh wee Dek Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHD 1859S - CC3 / PC17016821 / Klhb3q2	DOA: 26/8/17
	SHA0456T - CS/FCT15009246 / Tlgbd1	DOA: 31/5/15
11/4/18	Email preli revised to FCI	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006576/K1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 456T	Veh. Inspected	SHD 1859S
Policy No.		Coverage (\$)	0.00
Claim No.	D18002785MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MING)	Assign Date	10/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/04/2018	Inspection Date	10/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002785MFSH

Our ref: CS/FCI18006576/K1vd3

DATE: 11/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1859S


We thank you for your instruction on 10/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/4/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$2,374.40
Revised Estimate Amount	: S\$1,504.40
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kalvin Ang

Technical Investigator

Technical Investigation & Reconstructionist (SAE-A)

MOTOR SURVEY ASSIGNMENT

Date	09-04-2018	Our Ref No. D18002785MFSH
Accident Date	06-04-2018	Claim Type. Third Party
Insured Vehicle	SHA0456T	Third Party Vehicle. SHD1859S
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236785)



PRI Documents



Close



PRI Header Details

Claim No	D18002785MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GOH WEE DEK)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446682 , Phone: 62148880 , Fax: 62141511 EmailId: WEEDEK.GOH@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0456T	TP Vehicle No	SHD1859S
PRI Recieved Date	09-04-2018 07:47:51 PM	Surveyor Appointed Date	10-04-2018 12:32:09 PM	Surveyor Accept Date	10-04-2018 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	10-04-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 11 April 2018 2:56 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002785MFSH/1, SHD 1859S
Attachments: SHD 1859S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 1859S
Date of survey: 10/4/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 10 April 2018 12:42 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002785MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 10 April 2018 12:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002785MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time: 16 Dec 2014 / 08:37:52 Receipt No.: AACCK001-AX239-141216-000002

Asset Type: Vehicle Transaction Amount: \$65,101.00

Asset ID: SHD1859S Channel: AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type: 01.02 Register New Vehicle (AA)

Business Transaction Reference No.: 20141216083752715726

Vehicle No.: SHD1859S

Vehicle Type: H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Scheme: Taxi (Company)

First Registration Date: 16 Dec 2014

Original Registration Date: 16 Dec 2014

Vehicle Make: KIA

Vehicle Model: OPTIMA 1.7(A) DIESEL

Chassis No.: KNAGM414MF5561706

Engine No.: D4FDEH311919

Motor No.: -

Trailer Chassis No.: -

Propellant: Diesel

Passenger Capacity: 4

Engine Capacity: 1685

Power Rating: -

Unladen Weight: 1584

Maximum Laden Weight: 2050

Primary Color: Silver

Secondary Color: -

Manufacturing Year: 2014

Open Market Value: \$20,566.00

Minimum PARF Benefit: \$7,975.00

PARF Eligibility: Y

No. of Transfer: 0

Effective Ownership Date/Time: 16 Dec 2014 08:37:52


COE No.: 2014121601001520E

COE Expiry Date: 15 Dec 2022

COE Bid Category: -

Actual QP/PQP Paid Amount: \$51,668.00

Lifespan Expiry Date: 15 Dec 2022



Sketch Plan Pg. 4

PREMIER TAXIS	HIRE / RELIEF / SUPER RELIEF
VEHICLE NO.	SHD 1859S
CONTACT NO.	9027 2520
NEW MAILING ADDRESS (if any)	✓

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0161071F



Name
LIM KAH CHYE
林家財

Race
CHINESE

Date of Birth
03-11-1952 M

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S0161071F**
Name: **LIM KAH CHYE**

Birth Date: **03 Nov 1952**
Issue Date: **05 Apr 2003**




0706041



NRIC No. **S0161071F**



Blood Group: **O+** Date of Issue: **02-01-1993**

6A SAM LEONG ROAD
SINGAPORE 207898
NRIC No: **S0161071F** Date: **26/03/2015**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	29 Mar 1976

Licence No: **S0161071F**

NP 428A

Land Transport Authority

VOCATIONAL LICENCE

Licence No: **S0161071F**
Name: **LIM KAH CHYE**
Issue Date: **18/8/2014**

Please visit www.lta.gov.sg to check the status of this vocational licence



PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

9-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

1 pc	o/s wheel cover <i>hazard</i>	\$	116.00
		Less 10%	\$ 11.60
			<u>\$ 104.40</u>
S/NETT			
1 pc	rear o/s fender sticker <i>net</i>	\$	60.00
1 pc	o/s door sticker <i>net</i>	\$	100.00
	<i>Bumper by powder metal - net \$50</i>		
	Sundry <i>net</i>	\$	50.00 20
	To check wheel alignment	\$	80.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of rear o/s fender, rear o/s door, rear bumper	\$	800.00 400
	To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, os/ rocker panel garnish	\$	800.00 720
	To apply rustproofing on the repaired and replaced panels.	\$	150.00 20
		\$	<u>2,324.40</u>
			2374.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin UAY
10/4/18 1540hrs
3 Days
4s
After Repair please

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4/5/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006576/K1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 456T	Veh. Inspected	SHD 1859S
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18002785MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	10/04/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414MF5561706	Colour	SILVER
Odometer	308573	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/04/2018	Inspection Date	10/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1859S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S WHEEL COVER	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-11.60	-11.60
			104.40	104.40
SPECIAL NETT ITEMS				
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	BUMPER TOP PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			260.00	230.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF REAR O/S FENDER, REAR O/S DOOR, REAR BUMPER.		800.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR O/S FENDER, REAR O/S DOOR, O/S ROCKER PANEL GARNISH.		800.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			2,010.00	1,170.00
GRAND TOTAL			2,374.40	1,504.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FC18006576/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.