

22/07/2002

ASS. REC. BY:

REF: CS / AXA18006579 / Right Special Instruction:

Survivor

Rasul

ASSIGNMENT (Office)

From (Person): Dino Khan

of AXA

Date/Time: 09/04/2018 4:58pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STR 6662J

Insured:

Public Liability

at Workshop m/s

Cycle & Carriage

Tel:

9181 7717

of

188 Pandan Loop

Policy No:

Claim No:

8219914

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

19.04.2018 @ 9am owner writing

H.O.D. Endorsement:

Date/Time:

10/04/2018 1039am

Person Contacted:

Eric

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	STR 6662J - X
	Public Liability X
23/4/18 @ 3:41pm	revised to zero by email.
	Final fig to 6755.17, 5 days (Red \$1979.75, 24%)
	* Send the Wksp's LOD with our report to AXA's officer.

Pass


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SFR 666 2J
 at Workshop m/s CRC
 of Pandan LUP
 Insured: AXA / up
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFR 666 2J Yr Regn: 28/05/15
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: MERCEDES Benz A180 c.c. 1595
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 40621 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD1760422J372260
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45 R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 19/04/18
 Survey held at CRC (PL)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S REAR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repairer didn't provide GIA report.

Date/Time, File Pass to?

1) 06/8/18 huan

Date/Time, File Return to?

2)

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

7P
6755.17

250

250

Catherine Chong (LKK Auto)

From: KHAN Dino <dino.khan@axa.com.sg>
Sent: Monday, 9 April, 2018 4:58 PM
To: Eric Lee Ming Hui; SUR; assignments
Cc: Dickson Property; chester@my-best-insurance.com; edwin@my-best-insurance.com; amelia@my-best-insurance.com; blanca@my-best-insurance.com
Subject: NEW SURVEY FOR LKK - Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914
Attachments: img-409161734-0001.pdf

>> Dear Eric,

Thanks for your mail. We have appointed LKK to assess the damage claim.

>> Dear LKK team,

Please liaise with Mr. Eric to fix an appointment to survey this damage and let us have your recommendations.

Best Regards

Dino Khan

Assistant manager – P&C Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: dino.khan@axa.com.sg

DID: (65) 6880 3366



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Eric Lee Ming Hui [mailto:eric.lee@cyclecarriage.com.sg]
Sent: Monday, 9 April, 2018 4:20 PM
To: KHAN Dino <dino.khan@axa.com.sg>
Cc: Dickson Property <dickson@dickson-property.com.sg>; chester@my-best-insurance.com; edwin@my-best-insurance.com; amelia@my-best-insurance.com; blanca@my-best-insurance.com
Subject: RE: RE: Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914

Dear Dino,

Have attached the repair quotation for your perusal.

Please assist to clear the liability status by this week hopefully.

Thank you.

Your Sincerely,

Eric Lee Ming Hui

Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 9181 7717 | DID: 6771 4336 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

From: KHAN Dino [<mailto:dino.khan@axa.com.sg>]

Sent: Monday, 9 April, 2018 4:04 PM

To: Eric Lee Ming Hui

Cc: Dickson Property; chester@my-best-insurance.com; edwin@my-best-insurance.com; amelia@my-best-insurance.com; blanca@my-best-insurance.com

Subject: FW: RE: Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914

'WITHOUT PREJUDICE'

Hi Eric,

Please note my email. I was provided with the wrong one the first time round.

Best Regards

Dino Khan

Assistant manager – P&C Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: dino.khan@axa.com.sg

DID: (65) 6880 3366



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: KHAN Dino

Sent: Thursday, 5 April, 2018 1:20 PM

To: 'eric.lee@cycle.carriage.com.sg' <eric.lee@cycle.carriage.com.sg>

Cc: 'Dickson Property' <dickson@dickson-property.com.sg>; chester@my-best-insurance.com; edwin@my-best-insurance.com; amelia@my-best-insurance.com; blanca@my-best-insurance.com

Subject: RE: Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914

'WITHOUT PREJUDICE'

Hi Eric,

We understand that you are representing the owner of vehicle SFR6662J in seeking claim against the MCST no. 2071, our insured.

We would appreciate your patience while we conduct our investigations. In the meantime, please let us have the following for review:

1. Letter of authorization from the vehicle owner.
2. Repair quotation and claims summary.

We await your reply.

For avoidance of doubt, our involvement should not be construed as an admission of liability.

Best Regards

Dino Khan

Assistant manager – P&C Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: dino.khan@axa.com.sg

DID: (65) 6880 3366



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 23 April 2018 3:41 PM
To: KHAN Dino; Admin-D (LKKAUTO)
Cc: SUR
Subject: RE: NEW SURVEY FOR LKK - Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914
Attachments: CSAXA18006579R1qb.pdf

Dear Dino,

Enclosed herewith preliminary advice of SFR 6662J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KHAN Dino [<mailto:dino.khan@axa.com.sg>]

Sent: Friday, 20 April 2018 1:25 PM

To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>

Subject: RE: NEW SURVEY FOR LKK - Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914

Dear Catherine,

Understand that the Third Party vehicle was surveyed yesterday. We look forward to receiving your advice on the repair estimate and loss of use.

Best Regards

Dino Khan

Assistant manager – P&C Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: dino.khan@axa.com.sg

DID: (65) 6880 3366



Please consider the environment before printing this message
This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited.
If you are not the intended recipient of the message, please notify the sender immediately.

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Thursday, 19 April, 2018 9:10 AM

To: 'Eric Lee Ming Hui' <eric.lee@cyclecarriage.com.sg>; KHAN Dino <dino.khan@axa.com.sg>; 'SUR' <sur@lkkauto.com>; 'assignments' <assignments@lkkauto.com>

Cc: 'Dickson Property' <dickson@dickson-property.com.sg>; chester@my-best-insurance.com; edwin@my-best-



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 8219914

Date: 23th April 2018

Our Ref: CS/AXA18006579/R1qb

The Motor Claims Department
AXA Insurance Singapore Pte Ltd

Attn: Dino

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFR 6662J


We thank you for the instruction on 09/04/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/04/2018 (9am) at the premises of M/s CYCLE & CARRIAGE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,205.64</u>
Revised Estimate Amount	: S\$ <u>6,226.39</u>
"Check" Items Amount	: S\$ <u>285.84</u>
Total	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages consistent.

Recommend days of repair: 5 days.

We have not authorised the repairs.

Yours faithfully

Rasul
Automobile Assessor



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFR6662J

Mdm Or Hoon Ai

730 Upper Changi Road East
#01-02
Singapore 486858

Vehicle & Document Information
WIP No 22461
Reg No/Reg Date SFR6662J / 28/05/2015
Date In/Mileage / 0
Chassis No WDD1760422J372260
Engine No 27091030649951
Make/Model MB/A 180 BlueEFFICIENCY (W17
Colour/Trim 026 650 Calcit Whit/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator			
CSI00001	Cash	09/04/2018/ 16:15	EL	350 / Eric Lee Ming Hui			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

A BPILAB	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.				1920 2880.00
A BPIRES	RESPRAY LH/ REAR DOOR, LH/ REAR FENDER & LH/ REAR 'C' PILLAR.				1200 1800.00
M BPNSUN	POLICY NO/ACC DATE : DRIVE IN/EXCESS : DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB	REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT				480.00
M LEFT REAR DOOR		1.00	1595.79	00.00	1595.79
M LH/ REAR DOOR WEATHERSTRIP		1.00	280.72	00.00	280.72
M LH/ REAR ABSORBING DOOR		1.00	62.05	00.00	62.05
M LH/ REAR DOOR HANDLE		1.00	133.41	00.00	133.41
M REAR LEFT DOOR LOCK		1.00	285.84	00.00	285.84
M LEFT ROOF WATER DEFLECTOR MOULDING		1.00	307.83	00.00	307.83

Rasul
Hp 90010068
5 days
19/04/18 0900

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Nett 8,205.64
7% GST on 8205.64 574.39
Total Payable 8,780.03

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFR6662J

Mdm Or Hoon Ai

730 Upper Changi Road East
#01-02
Singapore 486858

Vehicle & Document Information

WIP No 22461
Reg No/Reg Date SFR6662J / 28/05/2015
Date In/Mileage 08/05/2018 / 41362
Chassis No WDD1760422J372260
Engine No 27091030649951
Make/Model MB/A 180 BlueEFFICIENCY (W17
Colour/Trim 026 650 Calcit Whit/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	19/07/2018/ 18:01	EL	350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.				1920.00
A BPIRES RESpray LH/ REAR DOOR, LH/ REAR FENDER & LH/ REAR 'C' PILLAR.				1200.00
M BPNSUN DATE IN/DATE SURVEY: 19-7-18 // 0900 // RASUL - LKK DIRECT SETTLEMENT : DINO KHAN - AXA // 2-5-2018				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR. NETT				480.00
X LEFT REAR DOOR	1.00	1595.79	00.00	1595.79
X LH/ REAR DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
X LH/ REAR ABSORBING DOOR	1.00	62.05	00.00	62.05
X WATER DEFLECTOR	1.00	307.83	00.00	307.83
X BLIND RIVET WITH PAN HEAD	10.00	2.29	00.00	22.90
X WATER DEFLECTOR MOLDING CLIP	1.00	5.88	00.00	5.88

Finalization

Confirmed & accepted by

Nett 6,255.17
7% GST on 6255.17 437.86
Total Payable 6,693.03

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFR6662J

Mdm Or Hoon Ai

730 Upper Changi Road East
#01-02
Singapore 486858

Vehicle & Document Information

WIP No **22461**
Reg No/Reg Date **SFR6662J / 28/05/2015**
Date In/Mileage **08/05/2018 / 41362**
Chassis No **WDD1760422J372260**
Engine No **27091030649951**
Make/Model **MB/A 180 BlueEFFICIENCY (W17**
Colour/Trim **026 650 Calcit Whit/ 044 Anthracite**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	19/07/2018/ 18:01	EL	350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BLIND RIVET WITH PAN HEAD	10.00	2.29	00.00	22.90
X WATER DEFLECTOR MOLDING CLIP	1.00	5.88	00.00	5.88

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 28.78** **28.78**
2.01
Total Payable 30.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Our ref: SFR 6662 J
Your ref: _____

Direct Settlement

Date: 27 JUL 2018

To: AXA Insurance

Singapore _____

Attn: Motor Claims Department

Re: Accident Involving Motor Vehicle Nos. SFR 6662 J & _____
At/Along Cascade Carpark On 30-7-18 @ _____

I am the owner of vehicle no. SFR 6662 J that was involved in an accident with your insured vehicle no. _____ of the above accident.

As the accident was caused by your insured negligent/inconsiderate driving, thus I am claiming from you for the following: -

1. Cost of Repairs	\$ <u>6693.03</u>
2. Loss of Use / Rental (<u>10</u> days @ \$ <u>100</u> per day)	\$ <u>1000</u>
3. LTA/GIA Search Fee	\$ <u>-</u>
4. GIA Report Fee	\$ <u>-</u>
5. Others	\$ <u>-</u>
Total:	\$ <u>7,693.03</u>

I hereby give you fourteen (14) days to comply with the above, failing which, I shall instruct my solicitor to commence legal action against you. If you have any queries, please contact the representative of **CYCLE & CARRIAGE INDUSTRIES PTE LTD** at Telephone No: **67714336 (Mr Eric Lee) / 67714304 (Ms Amanda Ang)**.

I hereby give full authority to CYCLE & CARRIAGE INDUSTRIES PTE LTD and their representative to negotiate/comprise settlement of the above claim on my behalf.

Your co-operation and immediate attention to the above is greatly appreciated. I hereby look forward to hearing from you soon.

Yours faithfully



Name & Signature

Address: C/o. 188 Pandan Loop Singapore 128378
Cc: Mr Eric Lee/ Ms Amanda Ang
E-mail: eric.lee@cyclecarriage.com.sg / amanda.ang@cyclecarriage.com.sg
Fax No. 67795383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
AXA INSURANCE PTE LTD	Cust No/Name WCV19385/AXA INSURANCE PTE LTD
	Reg No/Reg Date SFR6662J / 28/05/2015
	Date In/Mileage 08/05/2018/ 41362
MOTOR CLAIM DEPARTMENT	Chassis No WDD1760422J372260
8 SHENTON WAY #24-01	Engine No 27091030649951
SINGAPORE 068811	Make/Model MB/A 180 BlueEFFICIENCY (W17
Contact No	Colour/Trim 026 650 Calcit Whit/ 044 Anthracite



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSI00001	Cash	19/07/2018/ 18:06	EL	350 / Eric Lee Ming Hui	22461	28144475

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
A BPILAB			1920.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.			
A BPIRES			1200.00
RESPRAY LH/ REAR DOOR, LH/ REAR FENDER & LH/ REAR 'C' PILLAR.			
M BPNSUN			F.O.C.
DATE IN/DATE SURVEY: 19-7-18 // 0900 // RASUL - LKK			
DIRECT SETTLEMENT : DINO KHAN - AXA // 2-5-2018			
A BPILAB		0.10	380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			
A BPILAB			480.00
REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT			
X LEFT REAR DOOR	1.00	1595.79	1595.79
X LH/ REAR DOOR WEATHERSTRIP	1.00	280.72	280.72
X LH/ REAR ABSORBING DOOR	1.00	62.05	62.05
X WATER DEFLECTOR	1.00	307.83	307.83
X BLIND RIVET WITH PAN HEAD	10.00	2.29	22.90
X WATER DEFLECTOR MOLDING CLIP	1.00	5.88	5.88

Parts	2,275.17		Nett	6,255.17
Labour	3,980.00	7% GST on	6255.17	437.86
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	6,693.03
Diagnostics Job	0.00		Paid	0.00
Sundry/Others	0.00		Total Due	6,693.03
Total(w/o GST)	6,255.17			

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

CHAN'S & SONS ENTERPRISE

363 Sembawang Road
Singapore 758379
Tel 67532536 Fax:67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

TAX INVOICE

MDM OR HOON AI

INVOICE : AR1805-0257
DATE : 18/05/2018
TERMS : C.O.D
STAFF ID : ELAINE
AGREEMENT NO. : HA201805-0063

ATTN : ACCOUNTS PAYABLE

DESCRIPTION	AMOUNT (SGD)
-------------	--------------

934.58

Vehicle Reg No : SKU4312H
Make / Model : TOYOTA ALTIS 1.6 AUTO
Rental Dates : Rental Billing From 08/05/2018 To 17/05/2018
Period : 10 days
Rental Rate : S\$ 100.00 Per Day (Including GST)
Reference No : SFR6662J

AMOUNT : S\$
ONE THOUSAND DOLLARS ONLY

NON-TAXABLE VALUE : 0.00
TAXABLE VALUE : 934.58
GST 7% : 65.42

TOTAL S\$: 1,000.00

Please make your cheques payable to : **CHAN'S & SONS ENTERPRISE**



For Official Use Only

Payment Date :	F / Amt
CS / CC / CH :	
CS / CC / CH :	

RENTAL AGREEMENT

201805-0063

Hirer's Name MDM OR HAN AI		Date of Birth	Passport/ Nric No.	Nationality
Address 730 UPPER CHANGI RD		Occupation	Driving Licence No	Date of Expiry
Postal Code LAST #01-02	Postal Code 486558	Contact No	Mobile Phone No. 96172722	
Joint Hirer's / Guarantor's Name JUKH MUI HUAT		Date of Birth 12.11.1957	Passport/ Nric No. S2168478C	Nationality
Address		Occupation	Driving Licence No	Date of Expiry
Postal Code		Contact No	Mobile Phone No. 96172722	

CHECK OUT

Date 8.5.18	Time 10.35am	Mileage KM	E 1/4 1/2 3/4 F
Date 17.5.18	Time 2.30pm	Mileage KM	Remarks APA

IMPORTANT NOTES:-

- Car is restricted to SINGAPORE use. See clause 1(f) for non-compliance.
- No refund will be given for vehicle that returns early.
- Own Damage Liability - First \$1500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability - First \$2000 for any Third Party Accident Claim.
- Additional Excess of \$3000 for drivers under 24yrs old or above 70yrs and/or less than 2yrs driving experience.
- Hirer is responsible for all parking fines & traffic summons.
- Extension:- One day's advance notice is required otherwise no extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension is charged at 1/5 of the daily rate.
- As preventive maintenance, please check water & engine oil daily.
- Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings after the vehicle is returned.
- For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge of \$200 will be imposed for smoky, smelly or dirty vehicle.
- Carrying of PASSENGERS in commercial vehicle is strictly prohibited. Only WORKERS covered under hirer's workmen compensation are allowed.

	UNIT		RATE (\$)	TOTAL (\$)
RATE	10	@	100	934.58
DISCOUNT				
GST @ 7%				65.42
TOTAL				1000.00
EXTENSION				
heide				
Rel. str. 14c25				
DEPOSIT (refundable) SS				AM
CHANGED OVER FROM VEH.				DATE

I/We have read and agree to the terms and conditions of the rental agreement above and as set overleaf.
I/We declare that all information given on this form is true and accurate.

[Signature]

Hirer's Signature

Joint Hirer's/ Guarantor's Signature

[Signature]
for CHAN'S & SONS ENTERPRISE

VEHICLE NO. SK4 4324	MODEL Toyota A110 1.6 AT
FROM	RETURN

*Estimate Date. For actual return see CHECK IN

Eric Lee Ming Hui

Callus.

8 - May.
1030 am.

From: KHAN Dino <dino.khan@axa.com.sg>
Sent: Wednesday, 2 May, 2018 12:11 PM
To: Eric Lee Ming Hui; SUR; assignments
Cc: Dickson Property; chester@my-best-insurance.com; edwin@my-best-insurance.com; amelia@my-best-insurance.com; blanca@my-best-insurance.com
Subject: RE: Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914

'Without prejudice'

Chan's 1.6L.

Dear Eric,

LKK adjusted the repair cost to S\$ 6,226.39. They will need to check further on parts costing S\$ 285.84. They also adjusted the days of repair to 5 days. On a 'without prejudice' basis, we have no objections for you to proceed with the repairs. LKK will assist to verify the final repair cost after the repairs are completed. We will then issue a Discharge Voucher for the owner to sign before we make payment.

Hope this clarifies. If you have any questions, please feel free to contact me. Thank you.

Best Regards

Dino Khan

Assistant manager - P&C Claims
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: dino.khan@axa.com.sg
DID: (65) 6880 3366



Please consider the environment before printing this message
This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited.
If you are not the intended recipient of the message, please notify the sender immediately.

From: Eric Lee Ming Hui [mailto:eric.lee@cyclecarriage.com.sg]
Sent: Wednesday, 2 May, 2018 9:20 AM
To: KHAN Dino <dino.khan@axa.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Dickson Property <dickson@dickson-property.com.sg>; chester@my-best-insurance.com; edwin@my-best-insurance.com; amelia@my-best-insurance.com; blanca@my-best-insurance.com
Subject: RE: Cascadale #2071 - SFR6662J damaged by a fallen lamp post - 30/03/2018, AXA REF: 8219914

Dear Dino,

Any update?

Thank you,

Your Sincerely,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA18006579/R1qbe2

8 SHENTON WAY #24-01

AXA TOWERSINGAPORE 068811

Date : 17-08-2018

ATTN : DINO KHAN

Code : AXA2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SFR 6662J
Policy No.		Coverage (\$)	0.00
Claim No.	8219914	Excess (\$)	0.00
Assign From	DINO KHAN	Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ A180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD1760422J372260	Colour	WHITE
Odometer	40621	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/03/2018	Inspection Date	19/04/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFR 6662J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LEFT REAR DOOR (SN)	BENT	1,595.79	1,595.79
1	LH/ REAR DOOR WEATHERSTRIP (SN)	NECESSARY	280.72	280.72
1	LH/ REAR ABSORBING DOOR (SN)	NECESSARY	62.05	62.05
1	LH/ REAR DOOR HANDLE (SN)	TO REPAIR SEE LABOUR	133.41	-
1	REAR LEFT DOOR LOCK (SN)	SERVICEABLE	285.84	-
1	LEFT ROOF WATER DEFLECTOR MOULDING (SN)	CUT	307.83	307.83
10	BLIND RIVET WITH PAN HEAD (SN) (ADDITIONAL) @\$2.29	NECESSARY	22.90	22.90
1	WATER DEFLECTOR MOLDING CLIP (SN) (ADDITIONAL)	NECESSARY	5.88	5.88
			2,694.42	2,275.17
LABOUR				
	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH. INCLUSIVE OF THE REPAIR OF LH/ REAR DOOR HANDLE.		2,880.00	1,920.00
	RESPRAY LH/ REAR DOOR, LH/ REAR FENDER & LH/ REAR 'C' PILLAR.		1,800.00	1,200.00
	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.		480.00	480.00
			5,540.00	3,980.00
GRAND TOTAL			8,234.42	6,255.17
RECOMMENDED COST OF REPAIRS				6,255.17

Report Ref No. CS/AXA18006579/R1qbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.