


014/18

SJB 3726R



SLE 6987u



5/13/2018 = 4

DATE / PIC

Others	
<i>C = 6</i>	

confirm accident details. inform TP claim.
agree to settle. letter send out

25/5/18

File pass to typist type report

23/7/18

geet mandati van marinen

26 | 7 | 18

email from LT2 approve mandate.

RECEIVED 16 OCT 2018

RECEIVED 25 MAY 2018

~~Don~~

Confirm by:

Email

Email Call

If NO or B 28, Ass. Lia :

000000

1997

0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99
---	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Global Sum SS:

Confirm with:

Nome:	Mateus Lucas Botelho de Pádua
-------	-------------------------------

Name:	
Matr. No.:	

Name 2: _____

ASS. REC. BY:

REF: CTZ /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 07/6/10 days

Res.: Yes or No

Lum Sum:

1.2.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

10/4 File pass to Catherine

25/5/10

Confirm I.R. -> #4842.88 with 7 working days.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

SC E 68874 Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suban Pesta c.c. 1995

Colour:

M.P. white A/C: Insured / Std / NI / NA

Sp. Reading

20588 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J1-1955K0546 072194

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

19/3/18

D.O.I.

9/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18006583/Kwb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 10-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 3726R	Veh. Inspected	SLE 6987U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/03/2018	Inspection Date	09/04/2018	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18006583/Kwb3

Date: 10.04.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLE6987U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.04.2018 at the premises of M/s Motor Image Enterprises Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,889.72
Revised Estimate Amount	: S\$	4,702.88
"Check" Items Amount	: S\$	1,952.56
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6-10 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Shu Pei (LKKAuto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Thursday, 12 April 2018 10:45 AM
To: Daniel Lim; Kuan Wei Loong; Sayedinah Bin Ali
Cc: fchong@stengg.com; shlow@stengg.com; assignments; Irene Tay; Alfred Toh; Admin A; Chee So Chow; Lucas Lee
Subject: SLE6987U-3RD PARTY CLAIM-AIG; CHINA TAIPING REF:SNM18D01460C02/6(SJB3726R)
Attachments: SLE6987U MARKED ESTIMATE.PDF

Importance: High

Without Prejudice

Your Ref: SLE6987U
Our Ref: SNM18D01460C02/6 (SJB3726R)

Dear Sirs

We refer to your email pertaining to the above matter.

Please be advised that mandate has been obtained to accept M/s LKK Auto Consultants Pte Ltd's report/findings for this claim as exceptional case.

You may quantify your client's claim, with supporting documents.

Aside to M/s STA Inspection Pte Ltd., please treat the assignment as cancelled.

Aside to M/s LKK Auto Consultants Pte Ltd, please let have your report and bill for the services rendered.

Aside to Irene, please keep track on the matter.

Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID : +65 6389 6183
FAX: +65 6224 7175/6224 7478
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Sayedinah Ali [mailto:sayedinah@motorimage.net]
Sent: Wednesday, April 11, 2018 5:55 PM
To: Alfred Toh <alfred.toh@sg.cntaiping.com>
Cc: Daniel Lim <daniellim@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>
Subject: SLE6987U-3RD PARTY CLAIM-AIG TP(SJB3726R)CHINA TAIPING REF:SNM18D01460C02/6(SJB3726R)
Importance: High

Hi Mr Alfred,

Apology. Vehicle was supposed to be surveyed by STA however we made an error in asking LKK Kenneth Kong to survey it instead.

We have started the repair based on surveyor markings. Appreciate it if we can close the case based on LKK's report. Your kind understanding and approval is greatly appreciated. Attached is the surveyor's marking.

Regards

Sayedinah Ali

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP:92992693 DID:67038109 FAX:+65-62535535

Email:sayedinah@motorimage.net

Website:www.tanchong.com :: www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 12 April 2018 2:05 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJB3726R (OI : CTI - SNM18D01460C02) and SLE6987U (TP : LKK REF - CC3/CTI18006583/Kwb3) on 19.03.2018
Attachments: leeSZ_SNM18D01460C02-SJB3726R-LKKDirectSettlementAccidentLtr_CLCR95.040.pdf; MCHM18036818-SJB3726R.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 10 April, 2018 5:46 PM
To: Claims Dept of CTI
Cc: Irene Tay; Lucas Lee; Vivian Lau (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJB3726R (OI : CTI - TBA) and SLE6987U (TP : LKK REF - CC3/CTI18006583/Kwb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Irene,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLE 6987U at M/s Motor Image Enterprises Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.ctaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D01460/C02/7**

Date: **12 APRIL 2018**

via Ordinary & Registered Mail

**TAY MEI HUI (ZHENG MEIHUI)
BLK 38C BENDEMEER ROAD
#19-852 THE RIVER VISTA @ KALLANG
SINGAPORE 333038**

Dear Sir / Madam

**ACCIDENT INVOLVING SJB3726R AND SLE6987U ON 19 MARCH 2018
ALONG PIE NEAR ADAM ROAD EXIT**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLE6987U**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIVIAN

Ref : CC3/CTI18006583/KWB3

Contact No : 68418625

via Email : VIVIAN@LKKAUTO.COM

CC : Agent - (AN0214A) - SC ALLIANCE PTE LTD

F01/LKKDS-2013

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0700/2018
DATE : 19-MAR-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#15-00 SPRINGLEAF TOWER

SINGAPORE S(079909)

TEL : 6389 6111

FAX : 6222 1033

OWNER'S NAME : KOH HUAN CHEW (XU HUANZHOU)
ADDRESS : APT BLK 138A LORONG 1A TOA PAYOH
#05-06
S(311138)
TELEPHONE NO : 9761 6737

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100476788
VEHICLE NO : SLE6987U
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y286983
CHASSIS NO : JF1BJ5KC5GG072194
MILEAGE : 1 KM
DATE IN : 19/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 19/03/2018

Print Date : 24/03/2018

Print Time : 12:05:20

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE6987U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM CHINA TAIPIG LACATION:PIE SLIP ROAD DATE:19/03/2018 TIME:0830 HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND REAR PANEL	1120.00	1680 ✓
4	ZZ/003	RESPRAY REAR BUMPER AND REAR PANEL	840.00	1260 ✓
5	ZZ/004	REMOVE/REFIX REAR RIGHT, REAR LEFT, REAR CENTER TO FACILITATE REPAIR	900.00	nn 840 X
6	ZZ/005	REMOVE/REFIX EXHAUST	150.00	nn X
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	50 ✓
8	ZZ/007	TRANSFER TAILGATE MACHANISM	150.00	nn X
9	ZZ/008	WHEEL ALIGNMENT	200.00	nn X
10	ZZ/009	REMOVE/INSTALL REAR WINDSCREEN	300.00	nn X
11	ZZ/011	TO CONDUCT REAR LIGHTING TEST	50.00	30 ✓
12	ZZ/012	TO CONDUCT REAR PROTECTANT COATING	500.00	280 ✓
13	ZZ/013	TO CONDUCT REAR ANTI-RUST COATING	580.00	290 ✓
14	ZZ/014	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	short ✓
15	ZZ/015	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	nn X
16	ZZ/016	SUNDRIES	100.00	50 ✓
17	ZZ/10	TO REMOVE/REFIX FUEL TANK	200.00	nn X
TOTAL LABOUR CHARGES			5635.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE6987U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1	EXH PIPE ASSY R (SUPP) 600C7N	44200SG011	R 720.00	X			
2	MUFFLER ASSY RH NA (SUPP)	44300SG010	R 601.20	X			
3	R EXH CUTTER RH/LH GE2/SH	44370FG002	R 72.00	X			
4	FLOOR PAN R R CP	52129SG0019P	R 432.00	X			
5	SKIRT COMPL R USE SG0009P (SUPP)	52401SG0109P	R 288.00				
6	BUMPER FACE R (IPC-BTM-USE)	57704SG012	R 540.00				
7	BRKT CORNER R RH	57707SG060	R 54.00	X			
8	BRKT CORNER R LH	57707SG070	R 18.00	X			
9	BRKT SD R RH	57707SG080	R 14.40	X			
10	BRKT SD R LH	57707SG090	R 14.40	X			
11	BEAM COMPL R EU	57711SG0219P	R 288.00				
12	COVER HOOK R	57731SG010NN	R 12.60				
13	PANEL CPL R/G NA	60809SG0109P	R 1072.80	X			
14	GLASS R/G (SUPP)	63019SG000	R 799.20	X			
15	RUBBER DAM GLS	63232SG000	R 7.20	X			
16	RUBBER R/G	63232SG010	R 12.60				
17	WSTR DR R G	63516SG001	R 111.60	X			
18	REFLEC AY RH (SUPP)	84281SC000	R 20.40	X			
19	REFLEX AY LH	84281SC010	R 20.40	X			
20	ORNAMENT R	93033SG001	R 79.20	X			
21	LETTER MARK FORESTOR R	93079SG000	R 39.60	X			
22	LETTER MK R SUB	93079SG030	R 64.80	X			
23	TRIM PNL AY SKIRTR	94026SG000VH	R 36.00	X			
SUB TOTAL			5318.40	0.00	0.00		0.00
LESS DISCOUNT (NETT-20 %)			1063.68	0.00	0.00		0.00

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE6987U

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
	GRAND TOTAL		4254.72	0.00	0.00	0.00
	OVERALL TOTAL		4254.72			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLE6987U

TOTAL LABOUR CHARGES	5635.00
TOTAL SPARE PARTS CHARGES	4254.72
GRAND TOTAL	9889.72 +

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Authorized
1.B.1
Resurvey B4 paint
6-10 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kw

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0700/2018
DATE : 19-MAR-2018

CHINA TAIPIING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : KOH HUAN CHEW (XU HUANZHOU)
ADDRESS : APT BLK 138A LORONG LA TOA PAYOH
#05-06
S(311138)
TELEPHONE NO : 9761 6737

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100476788
VEHICLE NO : SLE6987U
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y286983
CHASSIS NO : JF1SJ5KCSGG072194
MILEAGE : 1 KM
DATE IN : 19/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 19/03/2018

Print Date : 10/05/2018
Print Time : 09:30:00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE6987U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM CHINA TAIPIING LACATION:PIE SLIP ROAD DATE:19/03/2018 TIME:0830 HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND REAR PANEL	1120.00	1680.00 ✓
4	ZZ/003	RESPRAY REAR BUMPER AND REAR PANEL	840.00	1260.00 ✓
5	ZZ/004	REMOVE/REFIX REAR RIGHT,REAR LEFT,REAR CENTER TO FACILITATE REPAIR	900.00	.00
6	ZZ/005	REMOVE/REFIX EXHAUST	150.00	.00
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	50.00
8	ZZ/007	TRANSFER TAILGATE MACHANISM	150.00	.00
9	ZZ/008	WHEEL ALIGNMENT	200.00	.00
10	ZZ/009	REMOVE/INSTALL REAR WINDSCREEN	300.00	.00
11	ZZ/011	TO CONDUCT REAR LIGHTING TEST	50.00	30.00
12	ZZ/012	TO CONDUCT REAR PROTECTANT COATING	500.00	280.00
13	ZZ/013	TO CONDUCT REAR ANTI-RUST COATING	580.00	290.00
14	ZZ/014	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	300.00
15	ZZ/015	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	.00
16	ZZ/016	SUNDRIES	100.00	50.00
17	ZZ/10	TO REMOVE/REFIX FUEL TANK	200.00	.00
TOTAL LABOUR CHARGES			5635.00	3940.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE6987U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	EXH PIPE ASSY R (SUPP) 608C/N	44200SG011	720.00			X
2	MUFFLER ASSY RH NA (SUPP)	44300SG010	601.20			X
3	R EXH CUTTER RH/LH GE3/SH	44370FG002	72.00			X
4	FLOOR PAN R R CP	52129SG0019P	432.00			X
5	SKIRT COMPL R USE SG0009P (SUPP)	52401SG0109P	288.00			OK
6	BUMPER FACE R (1PC-DTM USE)	57704SG012	540.00			OK
7	BRKT CORNER R RH	57707SG060	54.00			X
8	BRKT CORNER R LH	57707SG070	18.00			X
9	BRKT SD R RH	57707SG080	14.40			X
10	BRKT SD R LH	57707SG090	14.40			X
11	BEAM COMPL R EU	57711SG0219P	288.00			OK
12	COVER HOOK R	57731SG010NN	12.60			OK
13	COVER BMR R (SUPP)	57731SG060	14.40			X
14	PANEL CPL R/G NA	60809SG0109P	1072.80			X
15	GLASS R/G (SUPP)	63019SG000	799.20			X
16	RUBBER DAM GLS * 2	63232SG000	7.20			X
17	RUBBER R/G	63232SG010	12.60			X
18	WSTR DR R G	63516SG001	111.60			X
19	REFLEC AY RH (SUPP)	84281SC000	20.40			X
20	REFLEX AY LH	84281SC010	20.40			X
21	ORNAMENT R	93033SG001	79.20			X
22	LETTER MARK FORESTOR R	93079SG000	39.60			X
23	LETTER MK R SUB	93079SG0030	64.80			X
24	TRIM PNL AY SKIRTR	94026SG000VH	36.00			X

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE6987U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
	SUB TOTAL		1128.60	0.00	0.00	0.00
	LESS DISCOUNT (NETT-20 %)		225.72	0.00	0.00	0.00
	GRAND TOTAL		902.88	0.00	0.00	0.00
	OVERALL TOTAL		902.88			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLE6987U

NETT ITEM 1128.60
LESS 20 % -225.72
NETT AMOUNT 902.88

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 3940.00
TOTAL SPARE PARTS CHARGES 902.88

TOTAL CHARGES 4842.88
ADD 7 % GST 339.00

GRAND TOTAL 5181.88

✓ ok



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18006583/Kwb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJB 3726R	Veh. Inspected	SLE 6987U
Policy No.	DMPCSN3091551700	Coverage (\$)	0.00
Claim No.	SNM18D01460C02/6	Excess (\$)	0.00
Assign From		Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1SJ5KC5GG072194	Colour	METALLIC PEARL WHITE
Odometer	20588	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	9 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	9 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	9 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/03/2018	Inspection Date	09/04/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 6987U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	EXH PIPE ASSY R (N)	TO REPAIR SEE LABOUR	720.00	-
1	MUFFLER ASSY RH NA (N)	TO REPAIR SEE LABOUR	601.20	-
2	R EXH CUTTER RH/LH (N)	SERVICEABLE	72.00	-
1	FLOOR PAN R R CP (N)	TO REPAIR SEE LABOUR	432.00	-
1	SKIRT COMPL R (N)	BENT	288.00	288.00
1	BUMPER FACE R (N)	BENT	540.00	540.00
1	BRKT CORNER R RH (N)	SERVICEABLE	54.00	-
1	BRKT CORNER R LH (N)	SERVICEABLE	18.00	-
1	BRKT SD R RH (N)	SERVICEABLE	14.40	-
1	BRKT SD R LH (N)	SERVICEABLE	14.40	-
1	BEAM COMPL R EU (N)	BENT	288.00	288.00
1	COVER HOOK R (N)	MISSING	12.60	12.60
1	PANEL CPL R/G NA (N)	TO REPAIR SEE LABOUR	1,072.80	-
1	GLASS R/G (N)	NOT NECESSARY	799.20	-
10	RUBBER DAM GLS (N)	NOT NECESSARY	7.20	-
1	RUBBER R/G (N)	NOT NECESSARY	12.60	-
1	WSTR DR R G (N)	SERVICEABLE	111.60	-
1	REFLEC AY RH (N)	SERVICEABLE	20.40	-
1	REFLEX AY LH (N)	SERVICEABLE	20.40	-
1	ORNAMENT R (N)	NOT NECESSARY	79.20	-
1	LETTER MARK FORESTOR R (N)	NOT NECESSARY	39.60	-
1	LETTER MK R SUB (N)	NOT NECESSARY	64.80	-
1	TRIM PNL AY SKIRTR (N)	NOT NECESSARY	36.00	-
	LESS 20% DISCOUNT		-1,063.68	-225.72
			4,254.72	902.88
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	REVERSE SENSOR (SN)	SHORTED	300.00	300.00

Report Ref No. CC3/CT118006583/Kwb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TINTED FILM (SN)	NOT NECESSARY	145.00	-
			545.00	350.00
	LABOUR			
	REPAIR /REPLACE REAR BUMPER AND REAR PANEL.INCLUSIVE OF THE REPAIR OF EXH PIPE ASSY R,MUFFLER ASSY RH NA ,FLOOR PAN R R CP AND PANEL CPL R/G NA .		1,680.00	1,680.00
	RESPRAY REAR BUMPER AND REAR PANEL.		1,260.00	1,260.00
	RMEOVE /REFIX REAR RIGHT ,REAR LEFT ,REAR CENTER TO FACILITATE REPAIR.	NOT NECESSARY	900.00	-
	REMOVE /REFIX EXHAUST .	NOT NECESSARY	150.00	-
	TO CONDUCT WATER SEEPAGE TEST.		100.00	50.00
	TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	150.00	-
	WHEEL ALIGNMENT .	NOT NECESSARY	200.00	-
	REMOVE /INSTALL REAR WINDSCREEN .	NOT NECESSARY	300.00	-
	TO CONDUCT REAR LIGHTING TEST.		50.00	30.00
	TO CONDUCT REAR PROTECTANT COATING .		500.00	280.00
	TO CONDUCT REAR ANTI-RUST COATING.		580.00	290.00
	TO REMOVE/REFIX FUEL TANK.	NOT NECESSARY	200.00	-
			6,070.00	3,590.00
	GRAND TOTAL		10,869.72	4,842.88
RECOMMENDED COST OF REPAIRS				4,842.88

Report Ref No. CC3/CTI18006583/Kwb3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.