

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0700/2018
DATE : 19-MAR-2018

CHINA TAIPING INSURANCE (SINGAPORE)PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : KOH HUAN CHEW (XU HUANZHOU)
ADDRESS : APT BLK 138A LORONG 1A TOA PAYOH
#05-06
S(311138)
TELEPHONE NO : 9761 6737

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100476788
VEHICLE NO : SLE6987U
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y286983
CHASSIS NO : JF1SJ5KC5GG072194
MILEAGE : 1 KM
DATE IN : 19/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 19/03/2018

Print Date : 24/03/2018
Print Time : 12:05:20

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE6987U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM CHINA TAIPING LACATION:PIE SLIP ROAD DATE:19/03/2018 TIME:0830 HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND REAR PANEL	1120.00	✓
4	ZZ/003	RESPRAY REAR BUMPER AND REAR PANEL	840.00	✓
5	ZZ/004	REMOVE/REFIX REAR RIGHT,REAR LEFT,REAR CENTER TO FACILITATE REPAIR	900.00	840
6	ZZ/005	REMOVE/REFIX EXHAUST	150.00	?
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	500
8	ZZ/007	TRANSFER TAILGATE MACHANISM	nn 150.00	X
9	ZZ/008	WHEEL ALIGNMENT	200.00	?
10	ZZ/009	REMOVE/INSTALL REAR WINDSCREEN	nn 300.00	X
11	ZZ/011	TO CONDUCT REAR LIGHTING TEST	50.00	300
12	ZZ/012	TO CONDUCT REAR PROTECTANT COATING	500.00	2800
13	ZZ/013	TO CONDUCT REAR ANTI-RUST COATING	580.00	2900
14	ZZ/014	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	sham 300.00	✓
15	ZZ/015	TO SUPPLY/INSTALL REAR TINTED FILM	nn 145.00	X
16	ZZ/016	SUNDRIES	100.00	500
17	ZZ/10	TO REMOVE/REFIX FUEL TANK	200.00	?
TOTAL LABOUR CHARGES			5635.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE6987U

				DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION		PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	EXH PIPE ASSY R	(SUPP) 608C/N	44200SG011	720.00	7		
2	MUFFLER ASSY RH NA	(SUPP)	44300SG010	601.20	7		
3	R EXH CUTTER RH/LH	GE3/SH	44370FG002	72.00	X		
4	FLOOR PAN R R CP		52129SG0019P	432.00	7		
5	SKIRT COMPL R	USE SG0009P (SUPP)	52401SG0109P	288.00			
6	BUMPER FACE R	(1PC-DTM USE)	57704SG012	540.00			
7	BRKT CORNER R RH		57707SG060	54.00	X		
8	BRKT CORNER R LH		57707SG070	18.00	X		
9	BRKT SD R RH		57707SG080	14.40	X		
10	BRKT SD R LH		57707SG090	14.40	X		
11	BEAM COMPL R EU		57711SG0219P	288.00			
12	COVER HOOK R		57731SG010NN	12.60			
13	PANEL CPL R/G NA		60809SG0109P	1072.80	X		
14	GLASS R/G	(SUPP)	63019SG000	799.20	X		
15	RUBBER DAM GLS * 2		63232SG000	7.20	X		
16	RUBBER R/G		63232SG010	12.60	X		
17	WSTR DR R G		63516SG001	111.60	X		
18	REFLEC AY RH	(SUPP)	84281SC000	20.40	X		
19	REFLEX AY LH		84281SC010	20.40	X		
20	ORNAMENT R		93033SG001	79.20	X		
21	LETTER MARK FORESTOR R		93079SG000	39.60	X		
22	LETTER MK R SUB		93079SG030	64.80	X		
23	TRIM PNL AY SKIRTR		94026SG000VH	36.00	X		
SUB TOTAL				5318.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)				1063.68	0.00	0.00	0.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE6987U

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
GRAND TOTAL		4254.72	0.00	0.00	0.00
OVERALL TOTAL		4254.72			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLE6987U

TOTAL LABOUR CHARGES	5635.00
TOTAL SPARE PARTS CHARGES	4254.72
GRAND TOTAL	9889.72 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Authorized
1.B.1
Resurvey B4 paint
6-10 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: