



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR CHAN CHING SING 39 PASIR PANJANG HILL #02-02 SINGAPORE 118860 Contact No Mobile: 98169380	Cust No/Name	/MR CHAN CHING SING
	Reg No/Reg Date	SLL5078M / 28/02/201
	Date In/Mileage	/ 21699
	Chassis No	KNAPR81AMH7237873
	Engine No	G4NAGH818145
	Make/Model	KIA/SPORTAGE 2.0 A H508
	Colour/Trim	E6S MINERAL SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	09/04/2018/ 19:06	QUE	261 / Edwin Caina	26462
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & RE-ALIGN FRT DAMAGED PORTION: RENEW FRT FENDER LH , FRT FENDER RH , FRT BUMPER & WINGMIRROR LH REPAIR FRT DOOR LH <i>Repair</i>					2200 2750.00
E PNT98000 RESpray FRT BUMPER , FRT FENDER LH , FRT DOOR LH , WINGMIRRRO LH & FRT FENDER RH					1780 2520.00
M SUNDRY RENEW FRT SPORT RIM & TYRE RH					50.00
M SUNDRY RENEW FRT SPORT RIM LH & TRANSFER TYRE					50.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM					30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					200.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment					150.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS					100 150.00
E PNT88000 REMOVE & REFIT FRT PARKING SENSOR					80 100.00
M SUNDRY SUPPLY FRT TYRE RH-HANKOOK KINERGY 245/45R149 (invoice)					cut 380.00
M SUNDRY Sundries					20 50.00
M WHEEL ASSY-ALUMINIUM LHF		1.00	1107.00	00.00	SUR 1107.00
M WHEEL ASSY-ALUMINIUM RHF		1.00	1107.00	00.00	SCR 1107.00
M PANEL-FENDER,LH		1.00	362.00	00.00	PA 362.00
M PANEL-FENDER,RH		1.00	362.00	00.00	R 362.00
M GARNISH ASSY-FNDR SIDE LH		1.00	156.00	00.00	SUR 156.00
M GARNISH ASSY-FNDR SIDE RH		1.00	156.00	00.00	SCR 156.00
M COVER ASSY-FR BUMPER		1.00	638.00	00.00	DE 638.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR CHAN CHING SING 39 PASIR PANJANG HILL #02-02 SINGAPORE 118860 Contact No Mobile: 98169380	Cust No/Name	/MR CHAN CHING SING
	Reg No/Reg Date	SLL5078M / 28/02/201
	Date In/Mileage	/ 21699
	Chassis No	KNAPR81AMH7237873
	Engine No	G4NAGH818145
	Make/Model	KIA/SPORTAGE 2.0 A H508
	Colour/Trim	E6S MINERAL SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	09/04/2018/ 19:06	QUE	261 / Edwin Caina	26462

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER-FR BUMPER,LWR	1.00	375.00	00.00	375.00
M EMBLEM-KIA	1.00	76.00	00.00	76.00
M COVER-FR BUMPER FOG LAMP,LH	1.00	153.00	00.00	153.00
M COVER-FR BUMPER FOG LAMP,RH	1.00	153.00	00.00	153.00
M BRACKET-FR BUMPER SIDE,LH	1.00	21.00	00.00	21.00
M BRACKET-FR BUMPER SIDE,RH	1.00	21.00	00.00	21.00
M MIRROR ASSY-OUTSIDE RR VIEW,LH	1.00	621.00	00.00	621.00

Rasul
Hp 90010068
Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7 days
10/04/18 @ 1650
Reay by paint

Confirm & accepted by

	Nett	11,758.00
7% GST on	11758.00	823.06
Total Payable		12,581.06

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.