

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0433/2018/NK
Date : 10-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured SKD 954 X

EQ Insurance Company Limited

22 Gemmill Lane

Singapore 069257

Motor Claims Dept

Tel: 6223 9433 - Fax: 6223 4190

Owner's Name : Mr. Loo Peng Wah
Address : Blk 607 Senja Road
#14-08
Singapore 670607
Telephone : HP +65 93633444
Type of Claim : Third party Claims
Policy No. : 2100470239-01000
Vehicle No : **SLC 768 K**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Jun-16
Engine No : CVN010841
Chassis No : WAUZZZF46GA100553
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 07-Apr-18
Place of Accident : Entrance Into Westgate Shopping Mall

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 768 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper assy. Reorganise rear crash management components. Reinstall all parts removed.	\$ 900.00 600	
3	To respray rear bumper	\$ 800.00 600	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 768 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>del</i>	\$ 1,907.00	✓
2	SECURING STRIPS <i>new</i>	\$ 191.00	X
3	REAR BUMPER SPOILER <i>new</i>	\$ 216.00	✓
4	REAR REINFORCEMENT <i>new</i>	\$ 786.00	X
5	REAR BUMPER SENSOR REAR INNER/OUTER <i>new</i>	2 \$ 421.00	✓
6	SEAL RING <i>new</i>	4 \$ 14.00	X
7	REAR LIGHT REFLECTOR REAR LH / RH <i>new</i>	2 \$ 70.00	X
8	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES :		\$ 3,905.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 6,157.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King.
Surveyed Date : 17/04/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant