

ASS. REC. BY:

REF:

CS/MSG18006588 / Avd3 12

Special Instruction:

Survivor:

Merimen

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSIG

Date/Time: 10/4/18 @ 4:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 7429Z

Insured:

SJN 9564 M

at Workshop m/s

New Hock Teck

Tel:

6747 9241

of

1 Kaki Bkt Ave 6 Blk C #01-43

Policy No:

8278422348MA

Claim No:

555024

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

11/04/18

H.O.D. Endorsement:

Date/Time:

4:35pm @ 10/4/18

Person Contacted:

Sukyi

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

12/4/18


Informed Jasmine pending workshop est by merimen

9/5/18

Adrian confirmed LS \$4300 (Red 11,612, 736)

10/5/18

Send preli. revised by merimen



REF: MSIG

ASSIGNMENT

From:

Date: 11/04/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLU 7429Z

at Workshop m/s

NW Hock Teck

of

Ikaki Bkt Ave 6 #01-43

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS^{sup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLU7429Z

Yr Regn: 2017 Dec

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Attrage . c.c 1193

Colour:

Black.

A/C: Insured / Std / NI / NA

Sp. Reading

8985.

T/Radio: Insured / Std / NI / NA

Eng/No:

MMBSTA13AJH000439.

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/55R15

R: 195/55R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU4 PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal.

06 mm

R/Bal.

06 mm

L/Bal.

06 mm

L/Bal.

06 mm

D.O.A.

D.O.I.

11/04/18.

Survey held at

NHT.

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MSIG.

RECEIVED 10 MAY 2018

Date/Time File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time File Return to?

2)

10/5- typist

Report Format :

merimen

Lump Sum / I.B.I. (\$) :

4300/2

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

: Photos

: Other

TOTAL

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018		10 Apr 2018 16:05 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOW CHIANG SOON, ID: S1567258G, Tel: +6598377670, Email: NOEMAIL		
Main Claimant:	LIM BOON HOY, ID: S1395463A		
Vehicle Reg. No.:	SLU7429Z	Date of Loss:	07/04/2018 11:00 - :59 [3 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555024	Policy/Cover Note No.:	S27842234SMA(COMP) (Comprehensive) Coverage: 06/03/2018 - 05/03/2019
Vehicle Reg. No. (Insured):	SJN9564M	Policy No. (Claimant):	
		Excess:	
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/04/2018]		
Driver/Custodian (Insured):	LOW CHIANG SOON (56 / Male), NRIC: S1567258G, Tel: +6598377670		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 10 May 2018

Preliminary Advice

Insured Vehicle No	: SJN9564M	Accident Date	: 07/04/2018
TP Vehicle No	: SLU7429Z	Assignment Date	: 10/04/2018
Make	: MITSUBISHI ATTRAGE	Est. Duration of Repair	: 5.00
Date of Inspection	: 11/04/2018		
Inspection At	: NEW HOCK TECK MOTOR PTE LTD (HQ) 1 KAKI BUKIT AVE 6, BLK C #01-43 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,912.00
Revised Amount	:S\$	5,368.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,368.90

Lump Sum Repair (LUMP SUM)	:S\$	4,300.00
----------------------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SLU7429Z (555024)**
[SJN9564M]

TP
LIM BOON HOY
Apr 7 2018 11:00AM
[LOW CHIANG SOON]
New Hock Teck Motor Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/04/2018 13:52 PM.
To MSIG_JLKK
Subject PENDING ESTIMATE FROM REPAIRER

Dear Jasmine,

Please be informed that we have inspected the vehicle SLU 7429Z on 11/4/2018 .

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

MSME18047301 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME 09/04/2018 17:37
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/04/2018 17:37
 Date Of Accident 07/04/2018 11:50
 Exact Location Of Accident PIE TWDS CHANGI BEFORE STEVEN RD EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU7429Z
Insured/Policyholder
 Name Of Registered Owner LIM BOON HOY
 NRIC No S1395463A
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-90271989
 Alternative Phone No OFFICE-90271989

Vehicle Particulars

Manufacturer MITSUBISHI
 Model ATTRAGE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 1700088469
 Cover Note Number

Driver

Name of Driver LIM YIHAO
 NRIC No S9226671J
 Date Of Birth 26/07/1992
 Occupation INDOOR
 Date Of Driving Pass 08/03/2016
 Driving Experience 2 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96729850
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 613 BUKIT PANJANG RING ROAD #02-850
 Postcode 670613
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 NAME: : ALICIA LOW PUI YEE
 GENDER: : FEMALE
 Passenger 2 NAME: : CHING WEI WEI
 GENDER: : FEMALE
 Passenger 3 NAME: : KHOR CHING SIANG
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG PIE TOWARDS CHANGI BEFORE STEVEN RD EXIT AT EXTREME LH LANE OF 3 LANES. HEAVY TRAFFIC. VEHICLE IN FRONT OF ME SLOWED DOWN AND I FOLLOWED SUIT. SUDDENLY, I FELT AN IMPACT. VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES. I ALIGHTED AND REALISED THERE WAS TOTAL 3 VEHICLES INVOLVED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJN9564M
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLV564G
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM YIHAO
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLU7429Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name ALICAI LOW PUI YEE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLU7429Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 3

Name CHING WEI WEI
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLU7429Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 4

Name	KHOR CHING SIANG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLU7429Z
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

11687-1 (General Insurance)

NEW HOCK TUCK

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along Pie Towards Changi before Steven Rd exit at extreme LH lane of 3 lanes.

Heavy traffic, vln in front of me slowed down, I followed suite.

Suddenly, I felt an impact. Vln "B" collided onto rear portion of my vehicle and caused damaged.

I alighted and realised there was total 3 vehicles get involved.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

S463A

Vehicle Details

Vehicle No.:

SLU7429Z

Vehicle to be Exported:

No

Intended De-registration Date:

07 Apr 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

ATTRAGE 1.2 CVT

Primary Colour:

Black

Manufacturing Year:

2017

Engine No.:

3A92UGK5198

Chassis No.:

MMB5TA13AJH000439

Maximum Power Output:

59.0 kW (79 bhp)

Open Market Value:

\$13,488.00

Original Registration Date:

13 Dec 2017

First Registration Date:

13 Dec 2017

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

12 Dec 2027

PARF Rebate Amount:

\$3,750.00

Intended COE Rebate Details

COE Expiry Date:

12 Dec 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$46,791.00

COE Rebate Amount:

\$45,294.00

Total Rebate Amount:**\$49,044.00**

The information contained herein is correct as at 07 Apr 2018

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Arnon. LK
MSG

LIM BOON HOY

09/04/2018

Blk 1 Kaki Bukit Ave 6

TPMSG

01-43

Veron

Singapore 417883

MMBSTA13AJH000439

Accident date: 07/04/2018

SLU

Estimated repair cost for vehicle no: **SLV7429Z MITSUBISHI ATTRAGE 1.2 A '17**

CHASSIS: MMBSTA13AJH000439

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$828.00 <i>x</i>
2	2	Rear Boot Lid Hinges <i>new</i>	\$192.00	\$384.00 <i>x</i>
3	1	Rear Boot Lid Radiant Logo <i>new</i>		\$41.00 <i>✓</i>
4	1	Rear Boot Lid Inner Lock <i>2</i>		\$206.00 <i>x</i>
5	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$327.00 <i>x</i>
6	8	Rear Boot Lid Inner Trim Board Clips	\$6.50	\$52.00 <i>x</i>
7	2	Rear Tail Lamp <i>cracked</i>	\$376.00	\$752.00 <i>✓</i>
8	4	Rear Tail Lamp Clips <i>new</i>	\$8.00	\$32.00 <i>✓</i>
9	2	Rear Tail Lamp Panel <i>new</i>	\$185.00	\$370.00 <i>+</i>
10	1	Rear Bumper <i>Deformed</i>		\$708.00 <i>✓</i>
11	2	Rear Bumper Side Retainer <i>new</i>	\$26.00	\$52.00 <i>✓</i>
12	2	Rear Bumper Side Reflector <i>new</i>	\$35.00	\$70.00 <i>x</i>
13	10	Rear Bumper Clips <i>new</i>	\$6.50	\$65.00 <i>30</i>
14	1	Rear Bumper Body Kit (1 set) (Special Nett) <i>Deformed</i>		\$3,500.00 <i>1200 (SN)</i>
15	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00 <i>200 (SN)</i>
16	1	Rear End Panel <i>Dented</i>		\$650.00 <i>385</i>
17	1	Rear End Panel Top Garnish <i>Deformed</i>		\$175.00 <i>✓</i>
18	1	Rear Spare Tyre Panel <i>Repair</i>		\$906.00 <i>x</i>
19	1	Rear Spare Tyre Panel Top Cover <i>2 Not</i>		\$185.00 <i>x</i>
20	1	Rear Spare Tyre Panel & End Panel Insulator <i>new</i>		\$450.00 <i>x</i>
21	1	Rear Exhaust <i>Best</i>		\$571.00 <i>✓</i>
22	2	Rear Exhaust Chrome Pipe <i>RH Best</i>	\$75.00	\$150.00 <i>75</i>
23	1	Rear Center Exhaust <i>2 Not</i>		\$742.00 <i>x</i>
24	2	Rear Exhaust Mounting <i>new</i>	\$38.00	\$76.00 <i>x</i>

Subtotal :- **\$11,642.00**

2821

SN: 1400

253890

Labour charges

To remove & refit cushion	\$280.00 40
To remove & refit reverse sensors	\$100.00 40
To remove & refit rear camera	\$180.00 *
To remove & refit lower spoiler	\$180.00 *
To remove & refit rear & center exhaust	\$380.00 7.80
To check wiring	1430 \$100.00 30
Tuff kote	\$150.00 40
Towing Fees	\$100.00 *
Panel beating	\$1,400.00 7.600
Spray painting	\$1,400.00 600

Subtotal :- \$4,270.00

Total:- \$4,270.00

15, 912

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King

h/s 11/04/18.

65 Days.

total 5368.40

h/s A3K

A3K

05 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006588/AVD3N2

Date: 14/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	S27842234SMA (COMP)	
Claimant Vehicle No :	SLU7429Z	Insured Vehicle No :	SJN9564M	
Date of Loss:	07/04/2018	Nature of Claim:	TP	Claim No: 555024

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7429Z	Engine No:	3A92UGK5198
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AJH000439
Reg. Date:	13/12/2017 (Man. Year: 2017)	Odometer:	8985 km
Colour:	Black		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,642.00	3,938.90	7,703.10	66.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	1,430.00	2,840.00	66.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,912.00	5,368.90	10,543.10	66.26
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	15,912.00	4,300.00	11,612.00	72.98
+ GST 7.00/7.00% (S\$)	1,113.84	301.00	812.84	72.98
Nett Amount (S\$)	17,025.84	4,601.00	12,424.84	72.98

INSPECTION

Date of Assignment: 10/04/2018
 Date Inspected: 11/04/2018 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 May 2018)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU7429Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	828.00 F	*- FL
2	2		*REAR BOOT LID HINGES	Not Necessary	384.00 F	*- FL
3	1		*REAR BOOT LID RADIANT LOGO	Necessary	41.00 F	*41.00 FL
4	1		*REAR BOOT LID INNER LOCK	Not Necessary	206.00 F	*- FL
5	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	327.00 F	*- FL
6	8		*REAR BOOT LID INNER TRIM BOARD CLIPS	Not Necessary	52.00 F	*- FL
7	2		*REAR TAIL LAMP	Cracked	752.00 F	*752.00 FL
8	4		*REAR TAIL LAMP CLIPS	Necessary	32.00 F	*32.00 FL
9	2		*REAR TAIL LAMP PANEL	Not Necessary	370.00 F	*- FL
10	1		*REAR BUMPER	Deformed	708.00 F	*708.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	52.00 F	*52.00 FL
12	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	70.00 F	*- FL
13	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
14	1		*REAR END PANEL	Dented	650.00 F	*385.00 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	175.00 F	*175.00 FL
16	1		*REAR SPARE TYRE PANEL	Repair	906.00 F	*- FL
17	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	185.00 F	*- FL
18	1		*REAR SPARE TYRE PANEL & END PANEL INSULATOR	Not Necessary	450.00 F	*- FL
19	1		*REAR EXHAUST	Bent	571.00 F	*571.00 FL
20	1		*REAR EXHAUST CHROME PIPE	O/s Bent	150.00 F	*75.00 FL
21	1		*REAR CENTER EXHAUST	Not Necessary	742.00 F	*- FL
22	2		*REAR CENTER MOUNTING	Not Necessary	76.00 F	*- FL
23	1		*SET REAR BUMPER BODY KIT	Deformed	3,500.00 FS	*1,200.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,642.00	4,221.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	282.10
Total Parts (S\$)	11,642.00	3,938.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	280.00	40.00
2	TO REMOVE & REFIT REVERSE SENSORS	New	100.00	40.00
3	TO REMOVE & REFIT REAR CAMERA	New	180.00	-
4	TO REMOVE & REFIT LOWER SPOILER	New	180.00	-
5	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	80.00
6	TO CHECK WIRING	New	100.00	30.00
7	TUFF KOTE	New	150.00	40.00
8	TOWING FEES	New	100.00	-
9	PANEL BEATING	New	1,400.00	600.00
10	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			4,270.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >