

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4513K

DATE 9/4/2018 14:39

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Defunct</i>			\$ 538.80
	Front Bumper Bracket Top (LH) <i>Xm</i>			\$ 22.40
	Front Bumper Protector (LH) <i>Xm</i>			\$ 29.20
	<i>Front LH Fender x 4 parts</i> SUB TOTAL			\$ 590.40
	LESS 20%			\$ 118.08
	DISCOUNTED TOTAL			\$ 472.32
	Front Fender Advertisement Logo (LH) <i>mc</i>			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 250.00 <i>200</i>
	Spray Painting Charge-Bumper/Fender			\$ 500.00 <i>400</i>
	Tuff Kote			\$ 50.00 <i>Xm</i>
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 1,372.32

*Kahin rllkly**9/4/18 1510 L.**2 Dgs**4/5**After Repair pL*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.