



Name: Kevin

REF: \_\_\_\_\_

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate # \_\_\_\_\_

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To: Trip # \_\_\_\_\_ Vehicle No: \_\_\_\_\_

at Work Shop no: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims File \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Bed or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHC 673Y Yr Regn: "Feb 24"

Type: M. Car / M. Cycle / Bus / Van / Lorry / T.O. / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685Colour: Yellow A/C: Ins / Std / NI / NASp. Reading: 654065 T/Radio: Ins / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM HLD414ME4047626Gen. Cond: Good / P / Poor / BurntSteering: In order / J / Jammed / Leaked / Burnt orBrake: In order / J / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 255 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Weld/ste

Front

Rear

R/Bal: 7 mm R/Bal: 7 mmL/Bal: 7 mm L/Bal: 7 mmD.O.A. 6/4/8 D.O.A. 9/4/8Survey held at CDGE (Loyang)

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S B/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>11/4/8</u>	<u>Act 45 \$2450 / 30yr.</u>

EQ  
41LS : \$2,450.00 (Red \$3,640.84 / 60%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)

Phone: \_\_\_\_\_




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI18006592/K1pa3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 10-04-2018	
			Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBD 553B	Veh. Inspected	SHC 673Y	
Policy No.	DMCFHQ17-000203	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	06/04/2018	Inspection Date	09/04/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO305139763

CUSTOMER  
RMS CITYCAB PTE LTD  
CUSTOMER NO 7010070  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
TEL (P) 65551188 (O)  
SCOUT CARD NO.

REGN NO: SHC 673Y	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 07.04.2018 14:30
YR OF MANU 11.02.2014	TARGET DATE
CHASSIS CODE KMHLB41UMEU047626	COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 06.04.2018  
NATURE: 3P 06.04.2018

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Reg: SHC 673Y CHIANG

Vehicle No.: SHC 673Y

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard

Our Job Ref No : 305139480  
Date : 09/04/18

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156



### FINALIZATION FORM

To : LKK  
Attn : KALVIN  
Vehicle Reg No. : SHC673 Y

Fax :

06/04/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ GBD553B
  2. The finalized amount shall be:
    - (a) Spare Parts after List discount \_\_\_\_\_
    - (b) Labour Charges \_\_\_\_\_
    - Total for Part-By-Part Repair Cost** \_\_\_\_\_
    - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$2,450.00
  3. Estimated normal period for repairs: 3 working days.
  4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
  5. Thank you for your assistance.  
  
Signature : \_\_\_\_\_  
Name : **CHIANG**  
Tel : 62148314  
Fax : 65468156
- We confirm the estimates and finalized amount  
  
Signature : \_\_\_\_\_  
Name : Kalvin  
Date : 11/4/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



TYPE OF C: TP

SURVEY B': KALVIN

DATE : 06/04/18

### SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 673X

DATE 9/4/2018 12:06

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (RH) / <i>Part</i>			\$ 1,403.00
	Front Door Mirror (RH) / <i>Broken</i>			\$ 980.50
	Front Windscreen Moulding X "			\$ 60.00
	Front Windscreen Pillar Outer(RH) X <i>repair</i>			\$ 1,843.10
	Frt Wheel Hub Cap, RH / <i>broken</i>			\$ 150.70
	<i>Frt RH Fender X repair</i>			
	<i>Frt Bumper X repair</i>			
	SUB TOTAL			\$ 4,437.30
	LESS 20%			\$ 887.46
	DISCOUNTED TOTAL			\$ 3,549.84
	Front Door City Cab Logo (RH) / <i>me</i>			\$ 75.00
	Front Windscreen Sealant X "			\$ 46.00
				\$ 121.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 850.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Transfer Of Door			\$ 120.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 2,420.00
	ESTIMATE TOTAL			\$ 6,090.84

Nett

Nett

200

1,000.00

850.00

50.00

50.00

120.00

150.00

120.00

80.00

650

20

20

50

X "

X "

X "

Kali (U/C)

9/4/18 133.ks

3 P-1

4/5

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action(s) is allowed
- Survey must be resurveyed and approved by insurance Company

Accepted by repairer:  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 673X

DATE 9/4/2018 12:06

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (RH) ✓			\$ 1,403.00
	Front Door Mirror (RH) ✓			\$ 980.50
	Front Windscreen Moulding ✕			\$ 60.00
	Front Windscreen Pillar Outer(RH) ✕ repair			\$ 1,843.10
	Frt Wheel Hub Cap, RH ✓			\$ 150.70
	Frt RH Fender ✕ repair			
	Frt Bumper ✕ repair			
	<b>SUB TOTAL</b>			<b>\$ 4,437.30</b>
	<b>LESS 20%</b>			<b>\$ 887.46</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,549.84</b>
	Front Door City Cab Logo (RH) ✓			\$ 75.00 <b>Nett</b>
	Front Windscreen Sealant ✕			\$ 46.00 <b>Nett</b>
				<b>\$ 121.00</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 850.00 <b>650</b>
	Wiring Charge			\$ 50.00 <b>20</b>
	Tuff Kote			\$ 50.00 <b>20</b>
	Transfer Of Door			\$ 120.00 <b>50</b>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 ✕
	Remove/Refix Rear Windscreen Glass			\$ 120.00 ✕
	Frt Wheel Alignment			\$ 80.00 ✕
	<b>TOTAL LABOUR</b>			<b>\$ 2,420.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 6,090.84</b>

Kali 11/11/18

9/4/18 133.65

3 0-1

4/5

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



## Mei Kwan (LKKAUTO)

---

**From:** Francis Ng <francis.ng@eqinsurance.com.sg>  
**Sent:** Thursday, 12 April, 2018 12:03 PM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving GBD553B (OI : EQI - TBA) AND SHC673Y (TP : LKK REF - CC3/EQI18006592/K1pa3) on 06.04.2018  
**Attachments:** GBD553B 06.04.2018.PDF  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Mei Kwan,

Our insured's report is attached.


Liability is unclear.

Regards,  
**Francis Ng**  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190  
www.eqinsurance.com.sg



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the :*

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Thursday, April 12, 2018 11:30 AM  
**To:** Francis Ng <francis.ng@eqinsurance.com.sg>  
**Cc:** Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving GBD553B (OI : EQI - TBA) AND SHC673Y (TP : LKK REF - CC3/EQI18006592/K1pa3) on 06.04.2018

**WITHOUT PREJUDICE**

Dear Francis,

We refer to the above matter.

This is a TP direct settlement case.

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 5 May 2018 10:30 AM  
**To:** 'Jim Wong See Pah'  
**Subject:** <Request for Video Footage> Your Ref: CC18040171/ SHC 673Y/ JW(st) \*Our Ref: CC3/EQI18006592/K1pa3 [ACCIDENT INVOLVING GBD 553B(EQ) & SHC 673Y ON 06/04/2018 ]  
**Attachments:** STATEMENT OF GBD 553B.pdf

Your Ref: **CC18040171/ SHC 673Y/ JW(st)**  
Our Ref: CC3/EQI18006592/K1pa3

Without Prejudice

Dear Sirs,

### ACCIDENT INVOLVING GBD 553B(EQ) & SHC 673Y ON 06/04/2018

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client encroached into his lane and hit onto his van. Attached here with a copy of our insured driver accident report for your easy reference.

We would like to request a copy of video footage as stated in your client accident report for our necessary action.

Appreciate an early reply.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAUTO)

---

**From:** Jim Wong See Pah <jimwong@cdge.com.sg>  
**Sent:** Monday, 7 May 2018 9:39 AM  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** Re: <Request for Video Footage> Your Ref: CC18040171/ SHC 673Y/ JW(st) \*Our Ref: CC3/EQ18006592/K1pa3 [ACCIDENT INVOLVING GBD 553B(EQ) & SHC 673Y ON 06/04/2018 ]  
**Attachments:** SHC673Y VC (TS)(4).avi

Final stage.

Best Regards  
Jim Wong  
Claims Department / ComfortDelgro Engineering Pte Ltd  
Off: 62148374 / Fax: 62141843

---

From: Jim Wong See Pah/cdge/delgronotes  
To:  
Cc: "Hsiao Tong (LKKAUTO)" <chewht@lkkauto.com>  
Date: 07/05/2018 09:38 AM  
Subject: Re: <Request for Video Footage> Your Ref: CC18040171/ SHC 673Y/ JW(st) \*Our Ref: CC3/EQ18006592/K1pa3 [ACCIDENT INVOLVING GBD 553B(EQ) & SHC 673Y ON 06/04/2018 ]

---

3rd stage.

Best Regards  
Jim Wong  
Claims Department / ComfortDelgro Engineering Pte Ltd  
Off: 62148374 / Fax: 62141843  
[attachment "SHC673Y VC (TS)(3).avi" deleted by Jim Wong See Pah/cdge/delgronotes]

---

From: Jim Wong See Pah/cdge/delgronotes  
To:  
Cc: "Hsiao Tong (LKKAUTO)" <chewht@lkkauto.com>  
Date: 07/05/2018 09:37 AM  
Subject: Re: <Request for Video Footage> Your Ref: CC18040171/ SHC 673Y/ JW(st) \*Our Ref: CC3/EQ18006592/K1pa3 [ACCIDENT INVOLVING GBD 553B(EQ) & SHC 673Y ON 06/04/2018 ]

---

2nd stage.

Best Regards  
Jim Wong  
Claims Department / ComfortDelgro Engineering Pte Ltd  
Off: 62148374 / Fax: 62141843  
[attachment "SHC673Y VC (TS)(2).avi" deleted by Jim Wong See Pah/cdge/delgronotes]

From: Jim Wong See Pah/cdge/delgronotes  
To: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>  
Date: 07/05/2018 09:36 AM  
Subject: Re: <Request for Video Footage> Your Ref: CC18040171/ SHC 673Y/ JW(st) \*Our Ref: CC3/EQ118006592/K1pa3 [ACCIDENT INVOLVING GBD 553B(EQ) & SHC 673Y ON 06/04/2018 ]

---

Dear Ms Chew

Please find the attached video footage.

Best Regards

Jim Wong

Claims Department / ComfortDelgro Engineering Pte Ltd

Off: 62148374 / Fax: 62141843

[attachment "SHC673Y VC (TS)(1).avi" deleted by Jim Wong See Pah/cdge/delgronotes]

---

From: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>  
To: Jim Wong See Pah <jimwong@cdge.com.sg>  
Date: 05/05/2018 10:30 AM  
Subject: <Request for Video Footage> Your Ref: CC18040171/ SHC 673Y/ JW(st) \*Our Ref: CC3/EQ118006592/K1pa3 [ACCIDENT INVOLVING GBD 553B(EQ) & SHC 673Y ON 06/04/2018 ]

---

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Monday, 7 May 2018 11:20 AM  
**To:** 'Francis Ng'  
**Cc:** Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving GBD553B (OI : EQI - TBA) AND SHC673Y (TP : LKK REF - CC3/EQI18006592/K1pa3) on 06.04.2018  
**Attachments:** SHC673Y VC (TS)(3).avi; SHC673Y VC (TS)(4).avi

Hi Francis,

We refer to the above matter.

We attached here with a copy of video from third party for your easy reference. The video shows that third party was driving within his lane, our insured driver had encroached into third party's lane and collided onto third party taxi. We are of the opinion that liability is not in our insured's favour.

We will engage insured and update if there is any issue.

Thank you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Francis Ng [mailto:[francis.ng@eqinsurance.com.sg](mailto:francis.ng@eqinsurance.com.sg)]

**Sent:** Thursday, 12 April 2018 12:03 PM

**To:** Mei Kwan (LKKAUTO) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>

**Cc:** Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Joy Irene (LKKAUTO) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Direct Settlement - Accident Involving GBD553B (OI : EQI - TBA) AND SHC673Y (TP : LKK REF - CC3/EQI18006592/K1pa3) on 06.04.2018

Dear Mei Kwan,

Our insured's report is attached.

Liability is unclear.

Regards,

**Francis Ng**

Executive | Claims

**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190

www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately by email.

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

**Sent:** Thursday, April 12, 2018 11:30 AM

**To:** Francis Ng <francis.ng@eqinsurance.com.sg>

**Cc:** Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>

**Subject:** Direct Settlement - Accident Involving GBD553B (OI : EQI - TBA) AND SHC673Y (TP : LKK REF - CC3/EQI18006592/K1pa3) on 06.04.2018

**WITHOUT PREJUDICE**

Dear Francis,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 673Y at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Tuesday, 22 May 2018 4:27 PM  
**To:** 'jimwong@cdge.com.sg'  
**Cc:** Hsiao Tong (LKKAUTO); Vic (LKKAUTO)  
**Subject:** offer, Our Ref: CC3/EQ18006592/K1pa3/ Your Ref: CC18040171/ SHC 673Y/JW(st)

**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC3/EQ18006592/K1pa3  
Your Ref: CC18040171/ SHC 673Y/ JW(st)

Dear Sirs,

### **ROAD TRAFFIC ACCIDENT INVOLVING GBD 553B AND SHC 673Y ALONG TAMPINES AVENUE 4 ON 06.04.2018**

We refer to the above matter and your letter of demand dated 17<sup>th</sup> April 2018.

We propose settlement at a global sum of **\$3,280.00(all-in)**.

Please confirm acceptance.

Kindly let us have your reply as soon as possible.

Your prompt reply will be very much appreciate.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



## Poh Kin (LKKAUTO)

---

**From:** Jim Wong See Pah <jimwong@cdge.com.sg>  
**Sent:** Wednesday, 23 May 2018 9:42 AM  
**To:** Poh Kin (LKKAUTO)  
**Cc:** Hsiao Tong (LKKAUTO); Vic (LKKAUTO)  
**Subject:** Re: offer, Our Ref: CC3/EQ18006592/K1pa3/ Your Ref: CC18040171/ SHC 673Y/ JW(st)

Dear Poh Kin

Please process settlement in sum \$ 3280.00 for resolving our property damage claim amicably.

Thank you.

Best Regards

Jim Wong

Claims Department / ComfortDelgro Engineering Pte Ltd

Off: 62148374 / Fax: 62141843

---

From: "Poh Kin (LKKAUTO)" <pohkin@lkkauto.com>  
To: "jimwong@cdge.com.sg" <jimwong@cdge.com.sg>  
Cc: "Hsiao Tong (LKKAUTO)" <chewht@lkkauto.com>, "Vic (LKKAUTO)" <vicalpeh@lkkauto.com>  
Date: 22/05/2018 04:27 PM  
Subject: offer, Our Ref: CC3/EQ18006592/K1pa3/ Your Ref: CC18040171/ SHC 673Y/ JW(st)

---

### WITHOUT PREJUDICE

Our Ref: CC3/EQ18006592/K1pa3  
Your Ref: CC18040171/ SHC 673Y/ JW(st)

Dear Sirs,

### **ROAD TRAFFIC ACCIDENT INVOLVING GBD 553B AND SHC 673Y ALONG TAMPINES AVENUE 4 ON 06.04.2018**

We refer to the above matter and your letter of demand dated 17<sup>th</sup> April 2018.

We propose settlement at a global sum of **\$3,280.00(all-in)**.

Please confirm acceptance.

Kindly let us have your reply as soon as possible.

Your prompt reply will be very much appreciate.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 31/05/2018

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	GBD 553B (Insd Veh)	Your Ref. No. : DMCFHQ17-000203
	SHC 673Y (TP Veh)	Our Ref. No. : CC3/EQI18006592/K1pa3s2
Date of Accident	6/4/2018	

Liability	100%	
Final Repair Cost	: \$ 2,621.50	(W/GST)
Loss of Income	: \$ 200.00	4 days
Rental (If any)	: \$ 452.00	4 days
Others:	: \$ 7.49	
	: \$	
	3,280.99	
Final Settlement Sum	: \$ 3,280.00	(GLOBAL SUM)
Remarks	:	

**Payment Instruction: Payee's Breakdown**

1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 3,280.00
		: \$

NUR SHAQILAH  
LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI18006592/K1pa3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 31-05-2018	
		Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBD 553B	Veh. Inspected	SHC 673Y
Policy No.	DMCFHQ17-000203	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU047626	Colour	YELLOW
Odometer	654065	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/60R16	WEST LAKE	7 mm
L/H Front Tyre	205/60R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60R16	WEST LAKE	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	06/04/2018	Inspection Date	09/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 673Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT DOOR (RH)	DENTED	1,403.00	1,403.00
1	FRONT DOOR MIRROR (RH)	BROKEN	980.50	980.50
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
1	FRONT WINDSCREEN PILLAR OUTER (RH)	TO REPAIR SEE LABOUR	1,843.10	-
1	FRT WHEEL HUB CAP, RH	GRAZED	150.70	150.70
1	RH GARNISH DELTA (ADDITIONAL)	CUT	46.50	46.50
	LESS 20% DISCOUNT		-896.76	-516.14
			3,587.04	2,064.56
<b>SPECIAL NETT ITEMS</b>				
1	FRONT DOOR CITY CAB LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			121.00	75.00
<b>LABOUR</b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT WINDSCREEN PILLAR OUTER (RH).		1,000.00	200.00
	SPRAY PAINTING CHARGE.		850.00	650.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE		50.00	20.00
	TRANSFER OF DOOR.		120.00	50.00
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	NOT NECESSARY	150.00	-
	REMOVE / REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			-	-
			-	-
			-	-
			2,420.00	940.00
<b>GRAND TOTAL</b>			<b>6,128.04</b>	<b>3,079.56</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,450.00</b>

Report Ref No. CC3/EQ118006592/K1pa3s2



Report Ref No. CC3/EQ118006592/K1pa3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.