

KIM CHWEE AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-48 AUTOBAY
SINGAPORE 417883

VEHICLE NO: SLG 9696D

Not Authorised
10/8/18

Repair Sum \$ 6400
3 day.

| QTY | PARTICULAR | AMOUNT |
|-------|--|--------------------|
| 1 PCS | FRONT BUMPER 1503.60 | 10/cu \$1,951.12 ✓ |
| 1 PCS | FRONT BUMPER PDC SENSOR N/S | 11 \$248.70 X |
| 1 PCS | FRONT BUMPER FOG LAMP N/S | 11 \$385.60 X |
| 1 PCS | FRONT BUMPER FOG LAMP CHROME MOULDING N/S | 11 \$295.40 X |
| 1 PCS | FRONT BUMPER SPONGE 166.30 | 10/cu \$288.20 ✓ |
| 1 PCS | FRONT BUMPER REINFORCEMENT | 11 \$671.45 X |
| 1 PCS | FRONT BUMPER CENTRE GRILLE 299.30 | 10/cu \$362.50 ✓ |
| 1 PCS | HEADLAMP ASSY LED N/S 4845.10 | 10/cu \$5,853.80 ✓ |
| 1 PCS | FRONT FENDER N/S | 11 \$1,012.35 X |
| 1 PCS | FRONT SUPPORT PANEL | 11 \$866.02 X |
| | TO CHECK WIRING | \$50.00 20 |
| | TO DISMANTLE & REPLACING PDC SENSOR | \$80.00 50 |
| | TO SPRAY RUST PROOFING | 11 \$50.00 X |
| | TO REFILL AIR CON GAS | 11 \$120.00 X |
| | LABOUR FOR PANEL BEATING & REPLACING PARTS | \$680.00 300 |
| | TO PUTTY & SPRAY PAINTING | \$680.00 300 |
| | TOTAL | \$13,595.14 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6814.3
6473.58
7143.58