



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/AXA(SJT7859U)
DOA:06/04/2018@0900

AXA INSURANCE PTE LTD

09/04/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKS 1509 M - MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
CHASSIS NO: JM6BM42A8G0304199 (2015)

1 pc	Rear boot logo	\$ 75.00	nel ✓
1 pc	Rear boot emblem' MAZDA 3'	\$ 52.50	nel ✓
1 pc	Rear bumper	\$ 998.00	de ✓
1 pc	Rear bumper tow cover LH	\$ 18.50	mi's ✓
2 pcs	Rear bumper sensor @ \$180	\$ 360.00	?
1 pc	Rear bumper reinforcement	\$ 537.50	?
		\$ 2,041.50	
	LESS 20%	\$ 408.30	
		\$ 1,633.20	

Remove necessary action: jacking, panel beating, repair and
straighten rear inner panel, rear end panel, rear boot and rear
bumper.

\$ 400.00

Putty and respray rear inner panel, rear end panel, rear boot and
and rear bumper.

\$ 450.00

ADD 7% GST

\$ 2,483.20

\$ 173.82

\$ 2,657.02

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

KKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged: Repairer

Signature:

Date:

Tanjim 97495749
WP
11/4/18 @ 1550
3 days
sur@kkkauto.com
Resurvey before paint.