



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

DA/AXA(SJT7859U)  
DOA:06/04/2018@0900

AXA INSURANCE PTE LTD

09/04/2018

ATTN: THE MOTOR CLAIMS DEPT

## THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKS 1509 M - MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

CHASSIS NO: JM6BM42A8G0304199 (2015)

1 pc	Rear boot logo	\$ 75.00
1 pc	Rear boot emblem' MAZDA 3'	\$ 52.50
1 pc	Rear bumper	\$ 998.00
1 pc	Rear bumper tow cover LH	\$ 18.50
2 pcs	Rear bumper sensor @ \$180	\$ 360.00
1 pc	Rear bumper reinforcement	\$ 537.50
		<hr/>
		\$ 2,041.50
	LESS 20%	\$ 408.30
		<hr/>
		\$ 1,633.20

Remove necessary action: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot and rear bumper.

\$ 400.00

Putty and respray rear inner panel, rear end panel, rear boot and and rear bumper.

\$ 450.00

---

\$ 2,483.20

ADD 7% GST

\$ 173.82

---

\$ 2,657.02

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....