

25-00000

ASS. REC. BY

REP: csl/FCI18006600 / Urd3n7

Special Instruction

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Sithara

of FCI

Date/Time: 10/04/18 @ 3:05pm

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGS 994Z

Insured: SHC 0972J

at Workshop m/s: NPH Auto Service

Tel: 678 4 0663

of Blk 9005 Tampines Street # 01-246 / 254

Policy No:

Claim No: D18 002544MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 26/03/2018

CA / REV / REP. / REV 24 HRS ^{lwp}

H.O.D. Endorsement:

Date/Time: 3:22pm @

Person Contacted: Peggy

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGS 994Z *

SHC 972J - NJA / UOI 109012977 / y1

DOA: 9/6/2009

16/4/18

Revert to Insurance thru email

08/11/13 wof
ASS. REC. BY: Morcos

REF:

Fci

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SG59947

at Workshop m/s NPH

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GA / PR Seen: u Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG59947 Yr Regn: 3 / 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Mitance C.C. 1584

Colour: Red A/O: Insured / Std / NI / NA

Sp. Reading: 318739 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTCS3A74006176

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 26/3/18

Survey held at _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 10/4/18

Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/4/18 LTA 43940
conf. m/s \$1150 with Roy
Red. \$ 561.00, 33%

RECEIVED 17 APR 2018

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 3

1) Agriet

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) _____

Add Fee:

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

100

Transportation:

50

S -> RS: \$ _____

50

Photos

20

Others

TOTAL

220

Report Format: TP

Lump Sum / H.H.: (\$ 1150)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002544MFSH

Date: 13 April 2018

Our Ref: CS/FC118006600/Urd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGS 994Z.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/04/2018 at the premises of M/s NPH Auto Service and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 1,711.00</u>
Revised Estimate Amount	: <u>S\$ 1,456.00</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Repair days: 3 Days

Comments/ Present Status:
Damages Consistent.

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-03-2018	Our Ref No. D18002544MFSH
Accident Date	26-03-2018	Claim Type. Third Party
Insured Vehicle	SHC0972J	Third Party Vehicle. SGS994Z
Survey Location	BLK 9005 TAMPINES STREET 93 #01-246/254	
Contact Person.	PEGGY FOO	
Contact No.	67840663/ 67840663	Fax No. 67840692
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NPH AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236486)



PRI Documents



Close



PRI Header Details

Claim No	D18002544MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & NPH AUTC
Workshop Name	NPH AUTO SERVICE (Contact Person : PEGGY FOO)	Survey Location & Contact Details	BLK 9005 TAMPINES STREET 93 #01-246/254 Mobile: 67840663 , Phone: 67840663 , Fax: 6784069; EmailId: PEGGY@NPHAUTO.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0972J	TP Vehicle No	SGS994Z
PRI Recieved Date	10-04-2018 04:05:12 PM	Surveyor Appointed Date	10-04-2018 03:03:43 PM	Surveyor Accept Date	10-04-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	10-04-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, April 16, 2018 9:06 AM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002544MFSH/1
Attachments: SGS 994Z .pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **SGS 994Z**.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, April 10, 2018 3:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002544MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 10 April 2018 3:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002544MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	7375B

Vehicle No.:	SGS994Z
Vehicle to be Exported:	No
Intended De-registration Date:	09 Apr 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	4G18HS5685
Chassis No.:	JMYSTCS3A7U006176
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,046.00
Original Registration Date:	02 Mar 2007
First Registration Date:	02 Mar 2007
Transfer Count:	4
Actual ARF Paid:	\$12,151.00

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	01 Mar 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$49,429.00
COE Rebate Amount:	\$43,955.00
Total Rebate Amount:	\$43,955.00

The information contained herein is correct as at 09 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7375B
Vehicle Details	
Vehicle No.:	SGS994Z
Vehicle to be Exported:	No
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	4G18HS5685
Chassis No.:	JMYSTCS3A7U006176
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,046.00
Original Registration Date:	02 Mar 2007
First Registration Date:	02 Mar 2007
Transfer Count:	4
Actual ARF Paid:	\$12,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$49,429.00
COE Rebate Amount:	\$43,940.00
Total Rebate Amount:	\$43,940.00

The information contained herein is correct as at 10 Apr 2018

OK



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0037/04/18 Date : 10/04/2018

THIRD PARTY CLAIM

M/S : NURHASHIDA BTE HAMID
BLK 233 PASIR RIS DRIVE 4
#02-490 SINGAPORE 510233

Attn :
Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SGS994Z - MITSUBISHI LANCER
INSURED : NURHASHIDA BTE HAMID ENGINE# :
DATE OF ACCIDENT : 26/03/2018 CHASSIS# :
POLICY NO : 5088276032-01

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

Qty	U/Cost	U/Price	Total
	\$	\$	\$
Netts Items			
1	rear bumper	1@ 645.00	645.00
2	rear bumper side retainer RH <i>Deep cut</i>	1@ 45.00	45.00
3	rear bumper side retainer rivet (set) <i>leaf</i>	20@ 1.00	20.00
4	rear lamp RH <i>scr</i>	1@ 130.00	130.00
			840.00
Less 10%			-84.00
Total Nett			\$756.00
Labour & Misc			
1	Remove and install rear lamp, rear bumper, knocking rear fender & restraighten body.	220	350.00
2	Spray painting.	400	500.00
3	Check wiring system.	20	25.00
4	Remove and install rear boot carpet.	60	80.00
			955.00
Total Labour			\$955.00
Nett Total Before Gst			\$1,711.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer
Signature:

Not Authorised
nph
2/5/18
3 day.
10/4/18
Take photo after repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006600/Urd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 972J	Veh. Inspected	SGS 994Z
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18002544MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	10/04/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI LANCER (A)	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JMYSTCS3A7U006176	Colour	RED
Odometer	318739	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	DUNLOP	6 mm
L/H Front Tyre	195/60 R15	DUNLOP	6 mm
R/H Rear Tyre	195/60 R15	DUNLOP	6 mm
L/H Rear Tyre	195/60 R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/03/2018	Inspection Date	10/04/2018
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 994Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	DEEP CUT	645.00	645.00
1	REAR BUMPER SIDE RETAINER RH (N)	BENT	45.00	45.00
20	SET REAR BUMPER SIDE RETAINER RIVET @\$1.00 (N)	NECESSARY	20.00	20.00
1	REAR LAMP RH (N)	SCRATCHED	130.00	130.00
	LESS 10% DISCOUNT		-84.00	-84.00
			756.00	756.00
LABOUR				
	REMOVE AND INSTALL REAR LAMP, REAR BUMPER, KNOCKING REAR FENDER & RESTRAIGHTEN BODY.		350.00	220.00
	SPRAY PAINTING.		500.00	400.00
	CHECK WIRING SYSTEM.		25.00	20.00
	REMOVE AND INSTALL REAR BOOT CARPET.		80.00	60.00
			955.00	700.00
GRAND TOTAL			1,711.00	1,456.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00

Report Ref No. CS/FC118006600/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.