



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

1 2007 HONDA JAZZ 1.4 A (SJA5863U)

Date of Loss

7 April 2018

Time of Loss

18.10

Loss Description

SJA5863U (INSD) C/W SKR7813A (TP)

Comment

### Workshop Details

Total Rebate Amount

40442

Nett Loss Amount

\$9,558.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion \*

24/06/2018



Days of work completion \*

75



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

SJA5863U

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

13/12/2007



Mileage

93843

Age of Vehicle

10

### Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT...

2007

CATEGORY

Driver Name

FNOL INFORMATI...

LI YING, IDA

ASSESSMENT INFO...

2007

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... JAZZ 1.4 A

ASSESSMENT INFO... JAZZ 1.4A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JHMGD18507S234225

CATEGORY Date of Birth

FNOL INFORMATI... 29 December 1979

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 38

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JHMGD18507S234225

CATEGORY Engine No

POLICY INFORMAT... L13A54003762

ASSESSMENT INFO... L13A54003762

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1339

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 50000

FNOL INFORMATI... 13

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2005

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... -, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Female

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S7938861J

POST SURVEY INF...





SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

12/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

200

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

185/55R15

## Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair

## Tyre Condition

Spare wheel

Rear Tyre Size

185/55R15

---

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

---

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

### Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

### Assessment Details

### General & Workshop Details

### Vehicle & Driver Details

Vehicle Condition

Taxes &amp; Ratio

### Parts & Labour

Miscellaneous

## Summary

## Parts

|     |         |      |
|-----|---------|------|
| Add | Approve | Deny |
|-----|---------|------|

|                                                                                     | EDIT                                                                                | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME             | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACT (PAF |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------|-----------|----------|------|-----------------------|-------------|------------------------|-------------|------------|--------------|------------|-----------|-----------------|----------|
|    |    | 1     | 1         |          |      | FACEFR.BUMPER         |             |                        | Deformed    | 344.82     |              |            |           | 344.82          | Rev      |
|    |    | 2     | 1         |          |      | SPACERR FR BPR SIDE   |             |                        | Necessary   | 6.82       |              |            |           | 6.82            | Rev      |
|    |    | 3     | 1         |          |      | SPACERL FR BPR SIDE   |             |                        | Necessary   | 6.82       |              |            |           | 6.82            | Rev      |
|    |    | 4     | 1         |          |      | CLIPBUMPER FACE-2 PCS |             |                        | Necessary   | 5.07       |              |            |           | 5.07            | Rev      |
|    |    | 5     | 1         |          |      | CLIP ABUMPER-10 PCS   |             |                        | Necessary   | 25.35      |              |            |           | 25.35           | Rev      |
|    |    | 6     | 1         |          |      | FENDERL.FR.INNER      |             |                        | Serviceable | 0          | 0            | 0          | 0         | 0               | Den      |
|    |    | 7     | 1         |          |      | CLIP ABUMPER-4 PCS    |             |                        | Necessary   | 10.14      |              |            |           | 10.14           | Rev      |
|    |    | 8     | 1         |          |      | CLIPINNER FENDER-6PCS |             |                        | Necessary   | 15.21      |              |            |           | 15.21           | Rev      |
|  |  | 9     | 1         |          |      | SHIELDFR.SPLASH       |             |                        | Serviceable | 0          | 0            | 0          | 0         | 0               | Den      |
|  |  | 10    | 1         |          |      | PANELL.FR.FENDER      |             |                        | Bent        | 259.41     |              |            |           | 259.41          | Rev      |
|  |  | 11    | 1         |          |      | BEAM LFR BUMPER       |             |                        | Serviceable | 0          | 0            | 0          | 0         | 0               | Den      |
|  |  | 12    | 1         |          |      | HEADLIGHT UNIT L      |             |                        | Damaged     | 340.79     |              |            |           | 340.79          | Rev      |

## Labour

|     |         |      |
|-----|---------|------|
| Add | Approve | Deny |
|-----|---------|------|

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT |
|------|-------|-------------------------|-----------|------------|---------------|-------|-----------------|---------|
|------|-------|-------------------------|-----------|------------|---------------|-------|-----------------|---------|

| EDIT                                                                              | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                         | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT |
|-----------------------------------------------------------------------------------|-------|-------------------------|---------------------------------------------------|------------|---------------|-------|-----------------|---------|
|  | 1     |                         | INSPECT FR LIGHTING MECHANISMS & FOCUS            | 120        | 0             | 0     | Reviewing       |         |
|  | 2     |                         | REMOVE & RENEW FR L FENDER                        | 1120       | 0             | 0     | Reviewing       |         |
|  | 3     |                         | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P) | 900        | 0             | 0     | Reviewing       |         |

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR  
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF  
REPAIR : 4  
DAYS

Reviewing



2

SUNDRIES

Reviewing

40



# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount

\$2,994.43

Claim Amount

\$2,994.43

| CATEGORY      | ESTIMATE   | REVISED AMOUNT |
|---------------|------------|----------------|
| Labour        | \$2,140.00 | \$2,140.00     |
| Miscellaneous | \$40.00    | \$40.00        |
| Excess        | -\$200.00  | -\$200.00      |

Submit for Review