

Assessment Details

|                            |                          |                   |               |                |               |         |       |
|----------------------------|--------------------------|-------------------|---------------|----------------|---------------|---------|-------|
| General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary | Parts |
|----------------------------|--------------------------|-------------------|---------------|----------------|---------------|---------|-------|

Add

Approve

Deny

|                          | EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME              | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE |
|--------------------------|------|-------|-----------|----------|------|------------------------|-------------|------------------------|-----------|------------|--------------|------------|-----------|-----------------|----------------|--------|
| <input type="checkbox"/> |      | 1     | 1         |          |      | BONNET                 |             |                        | Damaged   | 980        |              |            |           | 980             | Reviewing      |        |
| <input type="checkbox"/> |      | 2     | 13        |          |      | BONNET INSULATOR CLIPS |             |                        | Necessary | 3.2        |              |            |           | 41.6            | Reviewing      |        |
| <input type="checkbox"/> |      | 3     | 1         |          |      | BONNET MERCEDES LOGO   |             |                        | Necessary | 42         |              |            |           | 42              | Reviewing      |        |
| <input type="checkbox"/> |      | 4     | 1         |          |      | HEAD LAMP - LH         |             |                        | Cracked   | 1500       |              |            |           | 1500            | Reviewing      |        |
| <input type="checkbox"/> |      | 5     | 2         |          |      | ACTUATOR               |             |                        | Damaged   | 95         |              |            |           | 190             | Reviewing      |        |

Labour

Add

Approve

Deny

|                          | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                          | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE |
|--------------------------|------|-------|-------------------------|----------------------------------------------------|------------|---------------|-------|-----------------|---------|--------|
| <input type="checkbox"/> |      | 1     |                         | TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS | 300        | 0             | 0     | Reviewing       |         |        |
| <input type="checkbox"/> |      | 2     |                         | TO RESPRAY PAINT ON ACCIDENT PORTIONS              | 400        | 0             | 0     | Reviewing       |         |        |
| <input type="checkbox"/> |      | 3     |                         | TO CHECK WIRING                                    | 20         | 0             | 0     | Reviewing       |         |        |
| <input type="checkbox"/> |      | 4     |                         | TO REMOVE, REPLACE FRONT BUMPER SENSOR             | 50         | 0             | 0     | Reviewing       |         |        |
| <input type="checkbox"/> |      | 5     |                         | TO RESET CHECK LIGHT                               | 0          | 0             | 0     | Deny            |         |        |