

INS. CASE OWNER:

CC 4 / AIG1800 6614 R26039

LKK:

IDAC:

Surveyor:

Rasm

DOI:

ASSIGNMENT

10/4/18

Date / Time:

10/4/18

Registered in Merimen:

10/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SF T 8839T

Name of Insured:

YEO SOON HOE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

14/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

YEO XIAPUN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

01470631256

Policy No.:

200395M4

Make / Model:

MERCEDES

Place of Accident:

BRADDEW RD TWSTON
pmlon

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

FX 97880



INSRS:

WSP:

Tel:

Liability:

RMKS:

Southern
Motor

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

10/4/18
Rasm

FX 97880? 3000/4000/5000/6000/7000/8000/9000/10000/11000/12000/13000/14000/15000/16000/17000/18000/19000/20000/21000/22000/23000/24000/25000/26000/27000/28000/29000/30000/31000/32000/33000/34000/35000/36000/37000/38000/39000/40000/41000/42000/43000/44000/45000/46000/47000/48000/49000/50000/51000/52000/53000/54000/55000/56000/57000/58000/59000/60000/61000/62000/63000/64000/65000/66000/67000/68000/69000/70000/71000/72000/73000/74000/75000/76000/77000/78000/79000/80000/81000/82000/83000/84000/85000/86000/87000/88000/89000/90000/91000/92000/93000/94000/95000/96000/97000/98000/99000/100000

10/4/18 * 2:44

CALLED OI CONFIRMED ACCIDENT. O/D CHANGED LANE TO THE RH AND COLLIDED INTO TP. INFORM TP WHILST CLAIM AGREED TO SETTLE AND AWAIR ABOUT MCD ISSUE.

EMPH VOS LIABILITY CLEAR.

RECEIVED 21 MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / CIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 21-4-18

Confirm with: Lm

Confirm by: Rasm

Repair Cost:

45

SS 3,200

(3 days)

Reduction:

47%

Email

Call

FINAL SETTLEMENT

Date/Time: 17-5-18

Confirm with: Lm

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

4/657

SS 3,514.00

O/D CHANGED TO TP.

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 90.00

(\$30 x 3 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+320 +220

Total:

SS 3,514.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 17-5-18

Confirm with: Lm

Email

Call

Payee 1:

SS 3,514.00

Name 1:

SOUTHERN MOTOR

Payee 2: (Strike if N.A.):

SS

Name 2:

Payee 3: (Strike if N.A.):

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18006614/R1eb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 10-04-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFT 8839T	Veh. Inspected	FX 9788D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/03/2018	Inspection Date	
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 5th April 2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16 AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to Honda CR400FV - 7K97882

- 1 pc of meter complete
- " Head lamp complete
- 3 pc of front signal
- 1 pc of front spoke rim
- 1 set of front brake disc
- 1 pc of engine guard
- " handle bar
- " mirror
- " Brake lever
- " Front footrest
- " Lower cowling
- " Handle balancer
- " Rear Yoshimura exhaust pipe
- " Front exhaust manifold
- " Throttle cable
- " Throttle pipe
- " Handle switch
- " Brake pedal

RASUL

HP 90010068

3 days

HS

10/04/18 @ 1500

Resurvey after repair

- LKK Auto
- To resurvey after spray painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 pc of meter complete 380.00 BR /
 " Head lamp complete 380.00 CR /
 3 pc of front signal 130.00 SR /
 1 pc of front spoke rim 460.00 R
 1 set of front brake disc 760.00 SR /
 1 pc of engine guard 120.00 PT /
 " handle bar 130.00 PA /
 " mirror 110.00 SR /
 " Brake lever 410.00 SR /
 " Front footrest 410.00 SR /
 " Lower cowling 90.00 CR /
 " Handle balancer 250.00 SR /
 " Rear Yoshimura exhaust pipe 900.00 PT /
 " Front exhaust manifold 820.00 X MN
 " Throttle cable 90.00 3 cut /
 " Throttle pipe 25.00 3 X MN
 " Handle switch 140.00 X MN
 " Brake pedal 65.00 PA /
 4,476.00 5160
 447.60 516
 4028.40 4644

Less 10%

Nett

- Transport
- Spray painting
- Jack fork
- Jack fork bracket
- Rear horn
- Repacked seat
- Labels

30.00 /
 120.00 60
 165.00 BR /
 75.00 60
 65.00 X MN
 110.00 SR /
 410.00 X MN
 300.00 200
 4,988.40 5,604

Yours faithfully,
SOUTHERN MOTOR

Tel 64193000
Fax 64153727



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18006614/R1eb3

26 APRIL 2018

YEO SOON HOE
15 PASIR RIS RISE
#02-29
SINGAPORE 518087

Dear Sir/Madam,

ACCIDENT INVOLVING SFT 8839T AND FX 9788D ON 14/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, MUHAMMAD FAUZIE BIN ALIAS ("the third party claimant")
of 216 203 A Punggol Field #05-232 Singapore 11202 (address),
owner of Fx 9788 D (vehicle no.) hereby authorize
Southern Motor
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. Fx 9788 D that was
damaged pursuant to the accident which occurred on 16-03-2018 (date) along
Braddell Road (location)
involving vehicle no/s SF7 SP397 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 10th day of May (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"
 **SOUTHERN MOTOR**
Blk 1006, Bukit Merah Lane 2
#01-10 Singapore 159762
Tel: 62730369 Fax: 62746614

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Southern Motor ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. 1. Mohammed Rasol (Uk Auto Consultants Pte) ("name of surveyor") with respect to the amount claimed for S\$ 342400 (repair costs), S\$ 9000 (loss of use/rental) S\$ - (search fees) for vehicle no. Fx 97880 that was damaged pursuant to the accident which occurred on 14-03-2018 (date) along Braddell Road (location) involving vehicle no/s SF7 SP297.

This is pursuant to the inspection conducted on 10-04-2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner MUHAMMAD FAUZIE BIN ALIAS ("third party claimant") of vehicle no. Fx 97880 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to Fx 97880 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17th day of May (month) 2018 (year)



MRS

Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"



SOUTHERN MOTOR
Blk 1006, Bukit Merah Lane 2
#01-10 Singapore 159762
Tel: 62730369 Fax: 62746614

**SOUTHERN MOTOR**

Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762

Tel:62730369 Fax:62746614 CO/GST Reg No:23414700L

TAX INVOICE NO : INV27888
Invoice Date : 10th May 2018
Payment Terms : CASH
Vehicle No. : FX9788D - HONDA CB400
SF4J
Mechanic : CASH

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING Singapore 079120

Tel: 64193000 Fax: 64153727

S/No	DESCRIPTION	QTY	U/PRICE	Amount
1	7% GST ON COST OF LUMP SUM REPAIR	1	\$224.00	\$224.00
2	COST OF LUMP SUM REPAIR	1	\$3,200.00	\$3,200.00

TOTAL : \$3,424.00

BALANCE : \$3,424.00

Goods Sold Are Not Returnable. Deposit Paid Are Not Refundable. All cheques should be made payable to "SOUTHERN MOTOR".
Interest Rate of ____% per month will be imposed on overdue Accounts. Thank you.

Received by



Issued by

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Mar 2018 Edit Reg		10 Apr 2018 00:00 Edit Adj Rpt	\$53,200.00 Edit Estimates	\$53,200.00 View Rpt		Pending for Survey Report Cancel Case


















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	YEO SOON HOE , ID: -								
Main Claimant:	MUHAMMAD FAUZI BIN ALIAS , ID: S86265713								
Vehicle Reg. No.:	FX9788D	Date of Loss:	14/03/2018 18:00 - :59 [166 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0143063122SG	Policy/Cover Note No.:	2100395224 (Comprehensive) Coverage: 15/12/2017 - 14/12/2018						
Vehicle Reg. No. (Insured):	SFT8839T	Policy No. (Claimant):	MOMVM000001926-00-000						
		Excess:							
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FX9788D (0143063122SG)
[SFT8839T]
TP
MUHAMMAD FAUZI BIN ALIAS
Mar 14 2018 6:00PM
[YEO SOON HOE]
Southern Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown											1			Edit			
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail			Print			
1	11/04/18 11:55		Accident Statement From:OD - Reg. No: SFT8839T, Claimant: YEO SOON HOE											1			Load HTM			
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print			
1	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
2	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
3	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
4	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
5	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
6	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
7	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
8	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
9	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
10	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
11	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
12	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
13	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
14	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
15	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
16	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
17	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
18	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
19	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
20	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
21	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
22	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
23	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
24	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
25	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
26	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
27	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
28	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
29	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			
30	27/04/18 17:39		General View											1			Load JPG <input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
34	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
35	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
36	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
37	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
38	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
56	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
57	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
58	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
60	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
61	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
62	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
63	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
64	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
65	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
66	27/04/18 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
67	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	27/04/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/18 16:47	EMAIL FROM AIG DD 10042018	 Load PDF	
2	10/04/18 16:47	TP EST & GIA REPORT	 Load PDF	
3	12/04/18 16:56	TP ESTIMATE- MARKED	 Load PDF	
4	17/05/18 10:55	LETTER TO OI	 Load PDF	
5	25/05/18 08:38	WORKSHOP INVOICE	 Load PDF	
6	25/05/18 08:38	AUTHORISATION TO ACT FORM	 Load PDF	
7	25/05/18 08:38	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/04/18 11:58	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFT8839T (Insd veh)	Model:	HONDA CB400SF4J 399CC
	FX9788D (TP veh)		
Date of Accident:	14/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	5,996.28	
Final Repair Cost	:	\$	3,424.00	
Loss of Use	:	\$	90.00	3.00 days at \$30.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	3,514.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Southern Motor	:	\$ 3,514.00
2)		:	\$

JOANNE LEE KHANG MIN

25 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18006614/R1EB3Q2

Date: 25/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100395224
Claimant Vehicle No : FX9788D **Insured Vehicle No :** SFT8839T
 Date of Loss: 14/03/2018 Nature of Claim: TP Claim No: 0143063122SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FX9788D**
 Make & Model: HONDA CB400SF4J, 399cc Engine No: NC23E2061902
 Reg. Date: 26/04/2004 (Man. Year: 2004) Chassis No: NC391051893
 Colour: Black Odometer: 33969 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17 Rear Tyre Size: 160/80Z R17
 Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,104.00	3,728.00	1,376.00	26.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	290.00	210.00	42.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,604.00	4,018.00	1,586.00	28.30
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	5,604.00	3,200.00	2,404.00	42.90
+ GST 7.00/7.00% (S\$)	392.28	224.00	168.28	42.90
Nett Amount (S\$)	5,996.28	3,424.00	2,572.28	42.90
+ Loss of Use (3.0 x S\$30.00/day) (S\$)		90.00		
Nett Liability (S\$)		3,514.00		

INSPECTION

Date of Assignment: 10/04/2018
 Date Inspected: 10/04/2018 Inspected At: Southern Motor (HQ)
 BLK 1006 BUKIT MERAH LANE 2, #01-10
 Singapore 159762
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*METER COMPLETE	Broken	880.00 FL	*880.00 FL
2	1		*HEAD LAMP COMPLETE	Cracked	380.00 FL	*380.00 FL
3	2		*FRONT SIGNAL	Scratched	130.00 FL	*130.00 FL
4	1		*FRONT SPOKE RIM	Repair	560.00 FL	*- FL
5	1		*SET FRONT BRAKE DISC	Scratched	760.00 FL	*760.00 FL
6	1		*BUMPER GUARD	Bent	120.00 FL	*120.00 FL
7	1		*HANDLE BAR	Bent	130.00 FL	*130.00 FL
8	1		*MIRROR	Scratched	110.00 FL	*110.00 FL
9	1		*BRAKE LEVER	Scratched	45.00 FL	*45.00 FL
10	1		*FRONT FOOTREST	Scratched	45.00 FL	*45.00 FL
11	1		*LOWER COWLING	Cracked	90.00 FL	*90.00 FL
12	1		*HANDLE BALANCER	Scratched	25.00 FL	*25.00 FL
13	1		*REAR YOOHIMURA EXHAUST PIPE	Bent	900.00 FL	*900.00 FL
14	1		*FRONT EXHAUST MANIFOLD	Not Necessary	650.00 FL	*- FL
15	1		*THROTTLE CABLE	Cut	90.00 FL	*90.00 FL
16	1		*THROTTLE PIPE	Not Necessary	35.00 FL	*- FL
17	1		*HANDLE SWITCH	Not Necessary	145.00 FL	*- FL
18	1		*BRAKE PEDAL	Bent	65.00 FL	*65.00 FL
19	1		*I.U	Broken	165.00 FS	*165.00 FS
20	1		*JACK FORK	Necessary	75.00 FS	*60.00 FS
21	1		*JACK FORK BRACKET	Not Necessary	65.00 FS	*- FS
22	1		*REAR BOX	Scratched	110.00 FS	*110.00 FS
23	1		*REPEAKED SEAT	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,620.00	4,105.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	516.00	377.00
Total Parts (\$\$)	5,104.00	3,728.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	30.00	30.00
2	SPRAY PAINTING	New	120.00	60.00
3	LABOUR	New	350.00	200.00
Gross Labour Cost (S\$)			500.00	290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >