



南方摩哆 SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 5th April 2018
Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Raffles Way #07-16 AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to Honda CB400SF45 - 7K97888

1 pc of meter complete
" Head lamp complete
2 pcs of front signal
1 pc of front spoke rim
1 set of front brake disc
1 pc of engine guard
" handle bar
" mirror
" brake lever
" front footrest
" lower cowling
" handle balancer
" Rear Yoshimura exhaust pipe
" front exhaust manifold
" throttle cable
" throttle pipe
" handle switch
" brake pedal

RASUL

HP 90010068

3 days

HS

10/04/18 @ 1500

Resurvey after
repair

LKK Auto Parts has already
the Repairer the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2200.00 BRU

320.00 CRA

130.00 SUR

460.00 R

76.00 SUR

120.00 PA

130.00 PA

110.00 SUR

45.00 SUR

45.00 SUR

90.00 CRA

25.00 SUR

900.00 PA

650.00 X

90.00 ~~3~~ cut

25.00 ~~3~~ X

145.00 X

65.00 PA

4476.00

447.60

4028.40

Less 10%

Nett

Transport
Spray painting
1. "

Jack fork

Jack fork bracket

Rear box

Repacked seat

Labour

30.00

120.00 60

165.00 BRU

75.00 60

65.00 X

110.00 SUR

45.00 X

200.00 200

4,988.40

Yours faithfully,
SOUTHERN MOTOR

Tel 64193000
Fax 64153727