

Surveior

CWS

Taufikh
Lurene

ASSIGNMENT (Office)

of FCI

Date/Time 11/04/2018 @ 10:42am.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHD 2010S

Insured:

SHD 8549R

at Workshop m/s

Prime Auto

Tel:

686/0908

of

G Benoi place

Policy No:

Claim No:

D18002816 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

10/04/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

10:37am @ 11/4/18

Person Contacted:

Chrissy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 2010S - CC71A1G11026335 / Kph 3y D.O.A: 21/12/2011
	SHD 8549R - CC31A1G16023992 / Hlyb3q2 D.O.A: 14/12/16
12/4/18	Revert preli advise
	lump Sum \$6150/- (Red: 4894.01 : 44%)

Schedule: *Tu/Th*

REF: *FCI*

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐
To inspect Vehicle No: _____
at Workshop/m.s: _____
of _____
Insured _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Sal. or Market Value: _____
IDAO Accident Report: _____ Consistent? : Yes or No
GIA / PR. Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
WP'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SHD 2010S* Vn Regn: *2014 Aug*
Type: M/Car / M/Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /
Truck / Trailer or
Make: *Toyota Prius* C: *1747*
Colour: *Orange* A.C. Insured / Std / NI / NA
Sp. Reading: *37490* T. Radio: Insured / Std / NI / NA
Eng. No: _____
C. No: *ZVW 400007608*
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *205/60R16*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Westlake*
Front Rear
R. Bal. *6* mm R. Bal. *6* mm
L. Bal. *6* mm L. Bal. *6* mm
D.O.A. _____ D.O.I. *11/4/18 @ 1615*
Survey held at: *Prime Auto*
Des. of Damages: Fnt / ☒ Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 MAY 2018

Date/Time File Pass to? ☐ Prel. Report
Ms Typist ☒ Final Report
Date/Time File Return to?

Days Of Repair: *8*
Resurvey No. of Trip: *1*

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech \$
☐ Rep \$

Survey Fee
Transaction
Phone
Other

Report Format:
Lump Sum / L.B. \$ *6150*

170+15
50
50
64
349



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002816MFSH

Date: 12/4/2018

Our Ref: CS/FCI18006620/T1td3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 2010S.

Please be informed that we had conducted the inspection of the abovementioned vehicle
11/04/2018 at the premises of M/s Prime Auto and have the following to report: -

Workshop Estimate Amount	: S\$ <u>11,044.01</u>
Revised Estimate Amount	: S\$ <u>7,345.64</u>
"Check" Items Amount	: S\$ <u>746.48</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the
Rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-04-2018	Our Ref No. D18002816MFSH
Accident Date	10-04-2018	Claim Type. Third Party
Insured Vehicle	SHD8549R	Third Party Vehicle. SHD2010S
Survey Location	6 BENOI PLACE	
Contact Person.	CHRISSY	
Contact No.	68610908/ 68610908	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236822)



PRI Documents



Close



PRI Header Details

Claim No	D18002816MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PRIME AU LTD.
Workshop Name	PRIME AUTO CLAIMS SERVICE PTE. LTD. (Contact Person : CHRISSY)	Survey Location & Contact Details	6 BENOI PLACE Mobile: 68610908 , Phone: 68610908 , Fax: 65152941 EmailId: CHRISSY@PRIMEAUTOCLAIMS.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHD8549R	TP Vehicle No	SHD2010S
PRI Recieved Date	10-04-2018 10:08:03 PM	Surveyor Appointed Date	11-04-2018 10:41:02 AM	Surveyor Accept Date	11-04-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-04-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 12 April 2018 3:40 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002816MFSH/1
Attachments: PRELI ADVISED SHD 2010S.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 2010S**.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 11 April 2018 11:04 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002816MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 11 April 2018 10:41 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002816MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team



Prime Auto Claims Service Pte Ltd.

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 10.04.2018

MS First Capital Insurance Ltd

36 Robinson Road #16-01

City House

Singapore 068877

Attn: Motor Claims Dept

Tanjah 97495747

11/4/18 P 1650

Lump sum

Reasoning after repair

8 days

Sum @ 1/10/18

RE: ESTIMATE COST OF REPAIR TO SHD2010S TOYOTA PRIUS ALPHA 1.8L

To Supply

1)	1pc	rear bumper	\$	1,217.85 <i>de ✓</i>
2)	1pc	rear bumper right side retainer	\$	122.25 <i>nei ✓</i>
3)	1pc	rear bumper left side retainer	\$	122.25 <i>nei ✓</i>
4)	1set	rear bumper clip	\$	30.00 <i>nei ✓</i>
5)	1pc	right rear bumper reflector	\$	81.50 <i>ana ✓</i>
6)	1set	rear glass moulding (3pcs)	\$	88.80 <i>nei ✓</i>
7)	1set	rear exhaust tail pipe with silencer box	\$	628.60 <i>Rx ✓</i>
8)	1pc	right side panel deck trim side	\$	413.10 <i>Xnn ✓</i>
9)	1pc	right tail lamp	\$	515.30 <i>cut ✓</i>
10)	1pc	left tail lamp	\$	515.30 <i>? cut ✓</i>
11)	1pc	right tail lamp housing	\$	316.50 <i>Rx ✓</i>
12)	1pc	right tail lamp lower bracket	\$	55.87 <i>nei ✓</i>
13)	1pc	tailgate	\$	1,450.00 <i>bt ✓</i>
14)	1pc	tailgate "Toyota" emblem	\$	62.00 <i>nei ✓</i>
15)	1pc	tailgate "Prius cx" emblem	\$	72.00 <i>nei ✓</i>
16)	1pc	tailgate "Hybrid Synergy Drive" emblem	\$	51.00 <i>nei ✓</i>
17)	1pc	tailgate weatherstrip	\$	284.00 <i>nei ✓</i>
18)	1pc	tailgate lock	\$	391.60 <i>bt ✓</i>
19)	1pc	tailgate catch	\$	66.10 <i>bt ✓</i>
20)	1pc	tailgate trim board	\$	480.00 <i>Xnn ✓</i>
21)	1pc	rear floor panel	\$	871.00 <i>Rx ✓</i>
22)	1pc	rear deck floor box	\$	560.00 <i>de ✓</i>
23)	1pc	rear end panel	\$	782.00 <i>bt ✓</i>
24)	1pc	rear end panel top garnish	\$	285.00 <i>de ✓</i>
25)	1set	rear end panel top garnish clip	\$	30.00 <i>nei ✓</i>

Sub total parts	\$	9,492.02
Less: 25% discount	\$	(2,373.01)
	\$	7,119.01

To Supply S.Nett Parts

1) 1pc	"Prime Taxi" sticker		\$	55.00 <i>net</i>
2) 2pcs	"Dial-A-Cab" sticker	@\$45.00	\$	90.00 <i>net</i>
3) 1tube	rear glass sealant		\$	40.00 <i>net</i>
4) 1pc	anti slip mat		\$	80.00 <i>net</i>
5) 1set	rear floor panel sealant		\$	150.00 <i>net</i>

Sub total S.Nett Parts \$ 415.00

L/charges

1) Towing charges (use king trolley)	\$	80.00 ✓
2) To tuff-kote	\$	150.00 <i>60</i>
3) To remove & refit tailgate glass	\$	120.00 ✓
4) To transfer tailgate trim cover, garnish & mechanism parts	\$	120.00 <i>60</i>
5) To remove & replace rear exhaust tail pipe & silencer	\$	120.00 <i>60</i> <i>1000</i>
6) To remove rear tailgate, rear bumper, right & left tail lamp, cut/welding rear end panel, floor panel, straighten right chassis panel, replace the above parts	\$	1,500.00 <i>1000</i>
7) To putty, respray painting tailgate inlet & outer, end panel, floor panel & rear bumper & etc. To polish	\$	1,500.00

Sub total L/charges \$ 3,510.00
Estimated Grand Total \$ 11,044.01

11124.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 10.04.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

Tanjah 97495747

11/4/18 @ 1630

lump sum
Ready after repair
8 days

Sun @ 11km from

RE: ESTIMATE COST OF REPAIR TO SHD2010S TOYOTA PRIUS ALPHA 1.8L

To Supply

1)	1pc	rear bumper	\$	1,217.85	de ✓
2)	1pc	rear bumper right side retainer	\$	122.25	nei ✓
3)	1pc	rear bumper left side retainer	\$	122.25	nei ✓
4)	1set	rear bumper clip	\$	30.00	ae ✓
5)	1pc	right rear bumper reflector	\$	81.50	an ✓
6)	1set	rear glass moulding (3pcs)	\$	88.80	nei ✓
7)	1set	rear exhaust tail pipe with silencer box	\$	628.60	Rio X
8)	1pc	right side panel deck trim side	\$	413.10	X X
9)	1pc	right tail lamp	\$	515.30	cut ✓
10)	1pc	left tail lamp	\$	515.30	? ✓
11)	1pc	right tail lamp housing	\$	316.50	Ry X
12)	1pc	right tail lamp lower bracket	\$	55.87	nei ✓
13)	1pc	tailgate	\$	1,450.00	bt ✓
14)	1pc	tailgate "Toyota" emblem	\$	62.00	nei ✓
15)	1pc	tailgate "Prius cx" emblem	\$	72.00	nei ✓
16)	1pc	tailgate "Hybrid Synergy Drive" emblem	\$	51.00	nei ✓
17)	1pc	tailgate weatherstrip	\$	284.00	nei ✓
18)	1pc	tailgate lock	\$	391.60	bt ✓
19)	1pc	tailgate catch	\$	66.10	bt ✓
20)	1pc	tailgate trim board	\$	480.00	? X
21)	1pc	rear floor panel	\$	871.00	Rio X
22)	1pc	rear deck floor box	\$	560.00	de ✓
23)	1pc	rear end panel	\$	782.00	bt ✓
24)	1pc	rear end panel top garnish	\$	285.00	de ✓
25)	1set	rear end panel top garnish clip	\$	30.00	nei ✓

Sub total parts	\$	9,492.02	6782.82
Less: 25% discount	\$	(2,373.01)	-1695.71
	\$	7,119.01	5087.11

To Supply S. Nett Parts

- 1) 1pc "Prime Taxi" sticker
- 2) 2pcs "Dial-A-Cab" sticker
- 3) 1tube rear glass sealant
- 4) 1pc anti slip mat
- 5) 1set rear floor panel sealant

@ \$45.00

\$	55.00	✓
\$	90.00	✓
\$	40.00	✓
\$	80.00	✓
\$	150.00	✓

Sub total S. Nett Parts \$ 415.00 265.00

L/charges

- 1) Towing charges (use king trolley) \$ 80.00 ✓
- 2) To tuff-kote \$ 150.00 80
- 3) To remove & refit tailgate glass \$ 120.00 ✓
- 4) To transfer tailgate trim cover, garnish & mechanism parts \$ 120.00 60
- 5) To remove & replace rear exhaust tail pipe & silence \$ 120.00 60
1000
- 6) To remove rear tailgate, rear bumper, right & left tail lamp, cut/welding rear end panel, floor panel, straighten right chassis panel, replace the above parts \$ 1,500.00
1000
- 7) To putty, respray painting tailgate inlet & outer, end panel, floor panel & rear bumper & etc. To polish \$ 1,500.00

Sub total L/charges \$ 3,510.00 2580.00
Estimated Grand Total \$ 11,044.01

7732.11
- 1546.42
6185.69
↓
6150.11 ✓



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006620/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8549R	Veh. Inspected	SHD 2010S	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18002816MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	10/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	ZVW400009608	Colour	ORANGE	
Odometer	37490	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/04/2018	Inspection Date	11/04/2018	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2010S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,217.85	1,217.85
1	REAR BUMPER RIGHT SIDE RETAINER	NECESSARY	122.25	122.25
1	REAR BUMPER LEFT SIDE RETAINER	NECESSARY	122.25	122.25
1	SET REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	RIGHT REAR BUMPER REFLECTOR	CRACKED	81.50	81.50
1	SET REAR GLASS MOULDING (3PCS)	NECESSARY	88.80	88.80
1	SET REAR EXHAUST TAIL PIPE WITH SILENCER BOX	TO REPAIR SEE LABOUR	628.60	-
1	RIGHT SIDE PANEL DECK TRIM SIDE	NOT NECESSARY	413.10	-
1	RIGHT TAIL LAMP	CUT	515.30	515.30
1	LEFT TAIL LAMP	CUT	515.30	515.30
1	RIGHT TAIL LAMP HOUSING	TO REPAIR SEE LABOUR	316.50	-
1	RIGHT TAIL LAMP LOWER BRACKET	NECESSARY	55.87	55.87
1	TAILGATE	BENT	1,450.00	1,450.00
1	TAILGATE "TOYOTA" EMBLEM	NECESSARY	62.00	62.00
1	TAILGATE "PRIUS CX" EMBLEM	NECESSARY	72.00	72.00
1	TAILGATE "HYBRID SYNERGY DRIVE" EMBLEM	NECESSARY	51.00	51.00
1	TAILGATE WEATHERSTRIP	TWISTED	284.00	284.00
1	TAILGATE LOCK	BENT	391.60	391.60
1	TAILGATE CATCH	BENT	66.10	66.10
1	TAILGATE TRIM BOARD	NOT NECESSARY	480.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	871.00	-
1	REAR DECK FLOOR BOX	DEFORMED	560.00	560.00
1	REAR END PANEL	BENT	782.00	782.00
1	REAR END PANEL TOP GARNISH	DEFORMED	285.00	285.00
1	SET REAR END PANEL TOP GARNISH CLIP	NECESSARY	30.00	30.00
	LESS 25% DISCOUNT		-2,373.01	-1,695.71
			7,119.01	5,087.11

Report Ref No. CS/FCI18006620/T1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	"PRIME TAXI" STICKER (SN)	NECESSARY	55.00	55.00
2	"DIAL-A-CAB" STICKER @\$45.00 (SN)	NECESSARY	90.00	90.00
1	TUBE REAR GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	ANTI SLIP MAT (SN)	NECESSARY	80.00	80.00
1	SET REAR FLOOR PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
			415.00	265.00
	LABOUR			
	TOWING CHARGES (USE KING TROLLEY).		80.00	80.00
	TO TUFF-KOTE.		150.00	60.00
	TO REMOVE & REFIT TAILGATE GLASS.		120.00	120.00
	TO TRANSFER TAILGATE TRIM COVER,GARNISH & MECHANISM PARTS.		120.00	60.00
	TO REMOVE & REPLACE REAR EXHAUST TAIL PIPE & SILENCER.		120.00	60.00
	TO REMOVE REAR TAILGATE,REAR BUMPER,RIGHT & LEFT TAIL LAMP,CUT/WELDING REAR END PANEL,FLOOR PANEL,STRAIGHTEN RIGHT CHASSIS PANEL,REPLACE THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF SET REAR EXHAUST TAIL PIPE WITH SILENCER BOX,RIGHT TAIL LAMP HOUSING AND REAR FLOOR PANEL.		1,500.00	1,000.00
	TO PUTTY,RESPRAY PAINTING TAILGATE INLET & OUTER,END PANEL,FLOOR PANEL & REAR BUMPER & ETC.TO POLISH.		1,500.00	1,000.00
			3,590.00	2,380.00
	GRAND TOTAL		11,124.01	7,732.11
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,150.00

Report Ref No. CS/FC118006620/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.