

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

SUPPLYMENTRY ESTIMATE

CHINA TAIPING INSURANCE

QUOTE NO :
ACCIDENT DATE : 03/04/2018@12:05
VRN : SKX6777X
MODEL : TOYOTA HARRIER
TP VRN :

ATTN: MOTOR CLAIMS DEPT

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR LH WHELL HOUSE AIR DUCT	1	\$ 189.00	\$ 189.00 <i>de</i>	
2 REAR TAIL GATE CATCH TOP COVEI	1	\$ 885.00	\$ 885.00 <i>de</i>	
3 REAR DECK TRIM COVER	1	\$ 443.00	\$ 443.00 <i>de</i>	
4 Discount 25%	1	\$ (379.25)	\$ (379.25)	
TOTAL				
		Sub Total	: 1137.75	1137.75
		Grand Total	: \$ 1,137.75	
		Add 7% GST	: \$ 79.64	
		Nett Total	: \$ 1,217.39	

No. of repair days: 7



CUSTOMER SIGNATURE _____

HITACHI CAPTIAL ASIA PACIFIC PTE LTD
(MANAGER)