

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

\$4103.20
Sundays

EST. No. EST0018981
Tay Puay Siong Desmond

Page 1 of 1
Your ref. TP-GBD 2647B AXA
Job No. 69380
Our ref. 18.04.10
Payment
Date 11/4/2018

Attn:

Vehicle No. SKV 7065X
Vehicle Model: Honda Vezel
Accident on: 8/4/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts					
1.00	Pc	Front bumper	del. 801.80	20.00	641.44
1.00	Pc	Front bumper lower garnish	del. 344.20	20.00	275.36
1.00	Pc	Front bumper lower grille	77.50	20.00	62.00
1.00	Pc	Front fog lamp cover RH	cur. 38.40	20.00	30.72
1.00	Pc	Front fender RH	at. 415.90	20.00	332.72
1.00	Pc	Front fender arc garnish RH	del. 150.60	20.00	120.48
1.00	Pc	Front fender inner shield RH	del. 112.40	20.00	89.92
3.00	Pcs	Front fender inner shield clips RH	h.c. 3.50	20.00	8.40
1.00	Pc	Front bumper side retainer RH	del. 20.40	20.00	16.32
1.00	Pc	Front headlamp RH	eva. 1,715.10	20.00	1,372.08
Labour & Misc:					2887.44
1.00		To remove and renew above parts	400.00		400.00
1.00		To spray paint (Pearl paint)	500.00		500.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Sub-Total
GST 7.00%
Total

3,849.44
269.46
4,118.90

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Signature:
Date:

Mo Aunhan
Before paint photo

LKK Auto (MA) 900
19/4/2018
4wdays

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

SUPPLEMENTARY ESTIMATE

EST. No EST0018981
Tay Puay Siong Desmond

Page 1 of 1
Your ref. TP-GBD 2647B AXA
Job No. 69380
Our ref. 18.04.10
Payment
Date 20/4/2018

Attn

Vehicle No SKV 7065X
Vehicle Model Honda Vezel
Accident on 8/4/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts.					

SUPPLEMENTARY ITEM.

1.00	Pc	Front radiator grille	328.30	20.00	✓ 262.64
1.00	Pc	Front headlamp lower beam RH	37.50	20.00	✓ 30.00
1.00	Pc	Front 'H' logo emblem	28.90	20.00	✓ 23.12

LKK Auto (MMA) : **315.76**
20/4/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total
GST 7.00%
Total

315.76
22.10
S\$ 337.86

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."