

ASS. REC. BY

REF

CS/CTI18006663/ Ktd3 n2

Special Instructions

Surveyor
Meimien

ASSIGNMENT (Office)

From (Person)

Adeline chng

of

CTI

Date/Time

10/4/18 @ 5:04pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SLP 6650 H

Insured:

SLK 3399E

at Workshop m/s

Hui Yang Motor

Tel:

64515752

of 176 Sin Ming Drive # 04-02

Policy No:

DMPC SN 3048021700

Claim No:

SNM18D01830C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

24/03/2018

CA / REV / REP. / REV 24 HRS ^{1 up}

H.O.D. Endorsement:

Date/Time: 10:19am @ 11/4/18

Person Contacted:

Belle

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLP 6650 H - x
	SLK 3399E - x

ASS. REC. BY:

REF: C721

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/4

File pass to Catherine

11/20 8 2400 (Red 3207:57%)

RECEIVED 18 APR 2018

Date/Time, File Pass to?

11/18/4 Typist

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

Report Format:

Lump Sum / I.B.I: (\$

2400

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18006663/Ktd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 11-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 3399E	Veh. Inspected	SLP 6650H	
Policy No.	DMPCSN3048021700	Coverage (\$)	0.00	
Claim No.	SNM18D01830C02	Excess (\$)	0.00	
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	11/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/03/2018	Inspection Date		
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018		10 Apr 2018 17:04 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ACE FLEET MANAGEMENT PTE LTD		
Vehicle Reg. No.:	SLP6650H	Date of Loss:	24/03/2018 00:00 - :59
Claim Type:	TP / SNM18D01830C02	Policy/Cover Note No.:	DMPCSN3048021700
Vehicle Reg. No. (Insured):	SLK3399E	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/04/2018]		
Adj Asg. Remarks:	EST \$5607, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

CNTAiping

16/04/18

monday

(LKK)

call Kenneth Wan
Veh In

24/03/2018

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR MERCEDES E220 - SLP6650H

1pc rear RH fender
1pc rear RH door
1pc rear RH door chrome

1pc \$ 1,930.00 ✓
1pc \$ 2,005.00 X
1pc \$ 195.00 X

less 10%

\$ 4,130.00
\$ 413.00
\$ 3,717.00

remove & refix rear windscreen
sealant n/c
wiring
tuffkote
spray painting
labour charges
Total

\$ 150.00 1201
\$ 80.00 805m
\$ 80.00 201
\$ 80.00 301
\$ 800.00 5001
\$ 700.00 6001
\$ 5,607.00

Not Authorized
Call @ 2400
Mercedes After Paint
5 days



LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006663/KTD3N2

Date: 19/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3048021700		
Claimant Vehicle No :	SLP6650H	Insured Vehicle No :	SLK3399E		
Date of Loss:	24/03/2018	Nature of Claim:	TP	Claim No:	SNM18D01830C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP6650H		Engine No:	65492080096308	
Make & Model:	MERCEDES-BENZ E220, 2.0 (A)		Chassis No:	WDD2130042A216891	
Reg. Date:	14/06/2017 (Man. Year: 2017)		Odometer:	109738 km	
Colour:	Black				
Engine Capacity:	1950 cc				
Market Value/New Car Price:	N/A				
Sum Insured (\$\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55ZR17	Rear Tyre Size:	215/55ZR17
Front Left Side:	Champro 5 mm	Rear Left Side:	Champro 3 mm
Front Right Side:	Champro 5 mm	Rear Right Side:	Champro 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,797.00	1,777.00	2,020.00	53.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,270.00	540.00	29.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,607.00	3,047.00	2,560.00	45.66
Approved Total (Overridden) (\$\$)		2,400.00		
(\$\$)	5,607.00	2,400.00	3,207.00	57.20
+ GST 7.00/7.00% (\$\$)	392.49	168.00	224.49	57.20
Nett Amount (\$\$)	5,999.49	2,568.00	3,431.49	57.20

INSPECTION

Date of Assignment:	10/04/2018	
Date Inspected:	16/04/2018	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2018)
Parts: 143	MERCEDES-BENZ E220 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP6650H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER	Bent	1,930.00 FL	*1,930.00 FL
2	1		*REAR RH DOOR	Repair	2,005.00 FL	*- FL
3	1		*REAR RH DOOR CHROME	Serviceable	195.00 FL	*- FL
4	1		*SEALANT	Necessary	80.00 FS	*40.00 FS
					Sub Total (\$\$)	4,210.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	413.00
					Total Parts (\$\$)	3,797.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
2	WIRING	New	80.00	20.00
3	TUFFKOTE	New	80.00	30.00
4	SPRAY PAINTING	New	800.00	500.00
5	LABOUR CHARGE	New	700.00	600.00
Gross Labour Cost (S\$)			1,810.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >