

EDIT	SF NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	4		TO PUTTY AND SPRAY REPLACED PARTS.	900	0	0	Reviewing		
	5		TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.	700	0	0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONCITION	LIST PRICE	DEPL/ BTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	14	8			FENDER INNER SHIELD RIVET			Necessary	3.8		10		27.36	Reviewing	
	15	1			FRONT O/S FENDER			Buckled	1134		10		1020.6	Reviewing	
	16	1			FRONT BUMPER FASCIA			Damaged	1565		10		1426.5	Reviewing	
	17	1			FRONT BUMPER REINFORCEMENT			Bent	563		10		524.7	Reviewing	
	18	1			O/S REINFORCEMENT BRACKET			Repair	0		10		0	Reviewing	
	19	1			FRONT O/S BUMPER SPONGE			Cracked	58		10		52.2	Reviewing	
	20	1			FRONT BUMPER SPONGE (CENTRE)			Cracked	117		10		105.3	Reviewing	
	21	1			FRONT O/S BUMPER SIDE RETAINER			Damaged	18		10		16.2	Reviewing	
	22	1			FRONT O/S BUMPER FOG LAMP			Cracked	246		10		221.4	Reviewing	
	23	1			FRONT BUMPER DAY RUNNING LAMP			Cracked	125		10		112.5	Reviewing	
	24	2			FRONT BUMPER FOG LAMP CHROME			Necessary	45		10		81	Reviewing	
	25	1			FRONT O/S BUMPER FOG LAMP GRILLE			Necessary	45		10		40.5	Reviewing	
	26	1			FRONT BUMPER FOG LAMP BRACKET			Bent	51		10		45.9	Reviewing	
	27	1			FRONT BUMPER TOW COVER			Necessary	86		10		77.4	Reviewing	
	28	2			FRONT BUMPER LOWER SIDE CHROME			Necessary	98		10		176.4	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured			License Issue Date		
Market Value			License Expiration Date		
			Address	TBC, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	59546988D	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
VISHNU BATHAM Shekhar	4/10/18 10:59 AM	14629.68	14629.68	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
After Repair Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 16, 2018
GIA SEARCH.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 16, 2018
Immediate Advice-SKD 1319Z.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 16, 2018
LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 16, 2018
LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 16, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	May 28, 2018
GA140725-Certificate of Insurance (2).pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	April 12, 2018
GA140725-Policy Schedule (2).pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	April 12, 2018
SKD 1319Z.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	April 12, 2018
OID's DL.pdf	Forms / Claim Documents	Driver's License / IDP	LKK AUTO CONSULTANTS PTE LTD (TP)	April 12, 2018
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	April 11, 2018
Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	April 11, 2018
TP GIA.PDF	Reports & Statement	GIA Report	LOH Cynthia	April 10, 2018
EMAIL FROM WORKSHOP.msg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	April 10, 2018
GIA GBE4293U INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	April 10, 2018