

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05761

Vehicle Insured : GBE4293U

Accident Date : 07-Apr-2018

Date : 10-Apr-2018

Our Ref : 218065 (AXA) / CHAN

PAGE : 1

TAN YEW HUAT

BLK 753 WOODLANDS CIRCLE

#07-552

Singapore 730753

Not Authored
L/S & ?
Resurvey After Painting
6 days

ESTIMATED COST OF REPAIR FOR M/BENZ E200 CGI SKD1319Z

=====

1 pc Bonnet		<i>R</i> 2,575.00	✓
1 pc Bonnet insulator		<i>S</i> 291.00	X
1 pc O/s bonnet inner lock		<i>D/I</i> 138.00	✓
2 pcs Bonnet hinge	@ S\$164.00	<i>D/I</i> 328.00	✓
2 pcs Bonnet emergency activator	@ S\$447.00	<i>Act</i> 894.00	✓
1 pc Bonnet lock release handle		<i>R</i> 28.00	X
2 pcs Bonnet damper	@ S\$161.00	322.00	?
2 pcs Bonnet spring stopper	@ S\$ 37.00	74.00	?
2 pcs Headlamp asst	<i>d/s CM</i> @ \$1268.00	2,536.00	✓
2 pcs Headlamp clip	<i>d/s M</i> @ S\$ 18.00	36.00	✓
1 pc O/s headlamp top panel		<i>R</i> 282.00	✓
1 pc O/s headlamp lower panel		56.00	?
1 pc Front o/s fender inner shield		<i>D/I</i> 215.00	✓
8 pcs Fender inner shield rivet	@ S\$ 3.80	<i>M</i> 30.40	✓
1 pc Front o/s fender		<i>R</i> 1,134.00	✓
1 pc Front bumper fascia		<i>M</i> 1,585.00	✓
1 pc Front bumper reinforcement		583.00	?
1 pc O/s reinforcement bracket		342.00	?
1 pc Front o/s bumper sponge		<i>CM</i> 58.00	✓
1 pc Front bumper sponge (centre)		<i>CM</i> 117.00	✓
1 pc Front o/s bumper side retainer		<i>D/I</i> 18.00	✓
1 pc Front o/s bumper foglamp		<i>CM</i> 246.00	✓
1 pc Front bumper day running lamp		<i>CM</i> 125.00	✓
2 pcs Front bumper foglamp chrome	@ S\$ 45.00	<i>M/I</i> 90.00	✓
1 pc Front o/s bumper foglamp grille		<i>M/I</i> 45.00	✓
1 pc Front bumper foglamp bracket		<i>R</i> 51.00	✓
1 pc Front bumper tow cover		<i>M/I</i> 86.00	✓
2 pcs Front bumper lower side chrome	@ S\$ 98.00	<i>M</i> 196.00	✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE4293U

Page : 2

1 pc	Front bumper lowe grille		56.00	?
3 pcs	Front o/s bumper parking sense @ S\$279.00		837.00	?
1 pc	Front parking sensor wire(set)		281.00	?
1 pc	Front bumper cover	<i>NSP</i>	248.00	X
2 pcs	Front bumper side inner parts @ S\$ 75.00		150.00	?
1 pc	Front bumper centre inner part		85.00	?
16 pcs	Frnot bumper onner psrt revit @ S\$ 3.80	<i>NSP</i>	60.80	?
1 pc	Radiator support panel		196.00	?
1 pc	Support panel top cover		186.00	?
1 pc	O/s horn	<i>NSP</i>	199.00	?

			14,780.20	
Less 10% :			1,478.02	

			13,302.18	

To rewire damaged parts and refocus
headlamp beam, daynositce headlamp

150.00 *sol*

To remove air con condenser, pipes
and drier, vacuum and to recharge

120.00 ?

To apply undersealing

60.00 *3ol*

To putty and spray replaced parts

1,100.00 *9od*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 *7od*

Total : S\$15,632.18

=====

Singapore Dollars Fifteen Thousand Six Hundred
and Thirty Two and Cents Eighteen Only