

ASS. REC. BY: Rasul

REF: CS/MSG18006684/Rlvdzex Special Instruction: _____

SURVISOR: Merimen

ASSIGNMENT (Office)

From (Person): Monica chung of MSIG

Date/Time: 11/4/18 @ 10:39am

Estimated Cost: _____ Bill to: _____

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP6578E Insured: YM1798K

at Workshop m/s: SMRT Automotive Tel: 6555 5556

of Go woodlands Ind. Park E4

Policy No: A28737484TMV Claim No: 554427

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS ^(sup)

H.O.D. Endorsement: _____

Date/Time: 10:51am @ 11/4/18 Person Contacted: Esther

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>YP6578E - x</u>
	<u>YM1798K - CS/INC12017644/T1qk3</u> D.O.A. <u>7/8/2012</u>
<u>16/4/18</u>	<u>Send preli revised by merimen</u>
<u>22/5/18</u>	<u>Final fig \$772 confirmed by email (Ref 3830.60, 83/0)</u>

Surveyor

Paran

REF:

2555N

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **YP 6578E**

at Workshop m/s **SMRT**

of _____

Insured: **MS14/TP**

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time-of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **YP 6578E** Yr Regn: **2017 / Jun**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **HINO XZU 700R** c.c **4009**

Colour: **WHITE** A/C: Insured / Std / NI / NA

Sp. Reading: **33481** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JHH TCS3H 70K 503285**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **7.00 R16**

R: **- D1P**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. **7** mm R/Bal. **7/7** mm

L/Bal. **7** mm L/Bal. **7/7** mm

D.O.A. **29/03/18** D.O.I. **11/04/18**

Survey held at **SMRT**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

[Signature]
22/5/2018

RECEIVED 23 MAY 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) **22/5 - typist**

Report Format : **Merimen**

Lump Sum / I.B.I.: (\$ **772/2**)

Days Of Repair: **2**

Resurvey No. of Trip: **1**

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation: _____ \$ + RS _____ \$

Photos

Others

TOTAL

150
10
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Apr 2018 11:16 Sendback Est	10 Apr 2018 14:01 S\$4,602.60	11 Apr 2018 10:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	BIAN HIN CO (S) PTE LTD, Co. Reg. No.: 195800167W, Tel: +6598781227		
Main Claimant:	CK SEAFOOD PTE LTD, Co. Reg. No.: 200412555N		
Vehicle Reg. No.:	YP6578E	Date of Loss:	29/03/2018 13:00 - :59 [9 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554427	Policy/Cover Note No.:	A28737484TMV (Third Party Only) Coverage: 29/05/2017 - 28/05/2018
Vehicle Reg. No. (Insured):	YM1798K	Policy No. (Claimant):	
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/04/2018]		
Driver/Custodian (Insured):	PEH KIM CHUAN (62 / Male), NRIC: S1107582G, Tel: +6598781227		
Adj Asg. Remarks:	Esther SMRT confirmed survey appointment at 3pm today.		

ASSOCIATED MAIL RECEIVED	
There are no mail for this case.	View All Compose Case Mail

ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Monica Chung Pei Zhen	
Date: 16 Apr 2018	
<h3><u>Preliminary Advice</u></h3>	

Insured Vehicle No	: YM1798K		
TP Vehicle No	: YP6578E	Accident Date	: 29/03/2018
Make	: HINO XZU700R	Assignment Date	: 11/04/2018
Date of Inspection	: 11/04/2018	Est. Duration of Repair	: 2.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

	Repairer's Estimate (Gross)	:S\$	4,602.60
	Revised Amount	:S\$	787.00
	Check Items (Estimated)	:S\$	0.00
	Total	:S\$	787.00
	Lump Sum Repair	:S\$	

Total Loss Consideration

	New for Old Value	:S\$	
	Pre-Accident Value	:S\$	
	COE / PARF Rebate	:S\$	
	Salvage Value	:S\$	
	Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/04/2018 11:55
Date Of Accident	29/03/2018 13:30
Exact Location Of Accident	WOODLANDS AVE 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6578E
Insured/Policyholder	
Name Of Registered Owner	CK SEAFOOD PTE LTD
Co Reg No	200412555N
Email Address	KARL@BROADWAY.COM.SG
Mobile Phone No	(LOCAL) +65-90698461
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	HINO
Model	HINO XZU700R-HKFMS3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE


Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28978421 MKC
Cover Note Number	

Driver

Name of Driver	ZHU HONGLIN
NRIC No	G6558391M
Date Of Birth	07/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	10/07/2017
Driving Experience	0 YEAR AND 8 MONTH
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The driver Zhu Honglin, Licence number G6558391m of CK Seafood Pte Ltd. Drive and exit from SLR toward woodland Ave 12, stop at the middle lane of the Junction of nearest landmark (Woodland ave 5) before and stop at the red light traffic. Out of sudden, the other Party / Driver Pet Kim Chuan, S11075826 (Pink). Drivers of YM1798K - hit on our vehicle no. XP6578E white cold-truck back right rear. (with damage of. (Right Rear).

- Stainless steel handle.
- stainless steel bar.
- Scretch of cold truck Panel.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 5/4/18



ZHU HONG LIN
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 2018.4.5. PM: 12:07

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

5/4/2018

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 5/4/18




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

2018.4.5. PM 12:07


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Accident Photo

Hino Motors, Ltd. 
MODEL XZU700R-HKFMS3
ENGINE N04C US 4009 HINO
FRAME No. JHHTCS3H70K003285 mL
COLOR TRIM PLANT GVM(kg)
058 LA18 P11
TM/A/BUILT MYY6S A06A 250
MADE IN JAPAN

Accident Photo



Accident Photo



Accident Photo



Accident Photo



SMRT AUTOMOTIVE
SERVICES PTE LTD
60 WOODLANDS
INDUSTRIAL PARK E4
757705

For Surveyor Marking

Claim Reference: WL/APR2018/003
Assessment Number: CTI10135
Version: SMRTAUTO/1
Date Calculated: 09/04/2018 04:37

Full Report - V1
Registration: YP6578E
Printed: 09/04/2018 11:38

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR Raymond	Date of Incident:	29/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	WL/APR2018/003	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	TOYOTA	FROM 06/2017	GWR 5500KG
Model:	Dyna	STANDARD CAB	PAINTING OFF VEHICLE
Sub Model:	BASE MODEL		
Model Sheet Number:	Y1C 01		
Registration:	YP6578E		
Registration Month:	June		
Registration Year:	2017		
VIN Number:			
Odometer:	Not Known		
Colour:	White		
Engine Number:			
Fuel Level:	%		



Vehicle Condition

Vehicle Status			
Pre-Accident Condition:		Severity of Impact:	
Steering:		Vehicle Status on Inspection:	
Brakes Pedal Travel:		Date of Inspection:	07/04/2018
Place of Inspection:			
Pre-Accident Damage:			
Tyres Condition:		Tread Depth RHF:	
Tread Depth LHF:		Tread Depth RHR:	
Tread Depth LHR:		Direction of Impact:	
Damage Areas:			

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/APR2018/003
Assessment Number: CTI10135
Version: SMRTAUTO/1
Date Calculated: 09/04/2018 04:37

Full Report - V1
Registration: YP6578E
Printed: 09/04/2018 11:38



Primary Impact →
 Secondary Impact - - - - - →

Addresses

Cost Summary

Total Labour	\$15.00
Total Parts	\$2,405.60
Total of Additional Costs	\$2,182.00
Excess:	TBA
Grand Total Exc GST:	\$4,602.60
7 % GST:	\$322.18
Grand Total Inc GST:	\$4,924.78

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details
 811011 R + R RIGHT TAIL LAMP

LABOUR COST

Total Work Units	3.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	0.3HRS	\$15.00
Total Labour	0.3HRS	\$15.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

- PAINTING OFF VEHICLE

LABOUR COST - PAINT

TIME(PAINT)	0.0	
Total Work Units (10WU/HR)	0.0	
Total Paintwork Labour	0.0HRS	\$0.00

MATERIAL COST - PAINT

Total Excluding Pearlescent Uplift	\$0.00
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$0.00

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3282	1	R/R LAMP ASSY	81550 37260		0%	125.60*
1000	1	REAR NUMBER PLATE	Renew		0%	40.00*
1000	1	REAR SAFETY BAR	Renew		0%	800.00*
1000	1	RR BOX DR MOUNT LH	Renew		0%	80.00*

Price Valid: 01/06/2015

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Finalise

Claim Reference: WL/APR2018/003
Assessment Number: CTI10135
Version: SMRTAUTO/2
Date Calculated: 21/05/2018 08:24

Full Report - V1
Registration: YP6578E
Printed: 21/05/2018 15:24

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	29/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	WL/APR2018/003	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Dyna
Sub Model:	BASE MODEL
Model Sheet Number:	Y1C 01
Registration:	YP6578E
Registration Month:	June
Registration Year:	2017
VIN Number:	
Odometer:	Not Known
Colour:	White
Engine Number:	
Fuel Level:	%

Model Specs

FROM 06/2017	GWR 5500KG
STANDARD CAB	PAINTING OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	07/04/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

TRANS-CAB SERVICES PTE LTD

No. 58 Defu Lane 1 Singapore 539498
Tel No. : 6287 6666 Fax No.: 6281 1400
Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-Cab Services Pte Ltd of Company Registration No. : 200303878K

hereby authorize Trans-Cab Auto Services Pte Ltd to act on behalf to claim

for all losses incurred for the accident involving **SHC 5921Z** AND


SGK 6395E along **BLK 316 UBI AVENUE 1 CAR PARK** on

7.10.2012 at **1200HRS**hrs.



In addition, we also hereby authorize the above payment to be made in favour of Trans-Cab Auto Services Pte Ltd upon settlement.

Dated this **8** day of **January 2013**

Yours faithfully
TRANS-CAB SERVICES PTE LTD



JASMINE TAN
General Manager



Primary Impact →
Secondary Impact - - - - - →

Addresses

Cost Summary

Total Parts	\$480.00
Total of Additional Costs	\$292.00
Excess:	TBA
Grand Total Exc GST:	\$772.00
7 % GST:	\$54.04
Grand Total Inc GST:	\$826.04

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

LABOUR COST

	WU	Cost Price (\$)
Total Work Units	0.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	0.0HRS	\$0.00
Total Labour	0.0HRS	\$0.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

- PAINTING OFF VEHICLE
LABOUR COST - PAINT

	WU	Cost Price (\$)
TIME(PAINT)	0.0	
Total Work Units (10WU/HR)	0.0	
Total Paintwork Labour	0.0HRS	\$0.00

MATERIAL COST - PAINT

	Cost Price
Total Excluding Pearlescent Uplift	\$0.00
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$0.00

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	L/DR FRAME ALU PLATE	Renew		0%	0.00
1000	1	R/DR FRAME ALU PLATE	Renew		0%	300.00*
1000	1	REAR NUMBER PLATE	Renew		0%	0.00
1000	1	REAR SAFETY BAR	Renew		0%	0.00
1000	1	RR BOX DOOR HOOK LH	Renew		0%	0.00
1000	1	RR BOX DOOR HOOK RH	Renew		0%	0.00

LETTER OF DISCHARGE

We, Trans-cab Auto Services Pte Ltd (workshop), hereby agreed and confirmed that we are authorized by the owner of motor vehicle SHC 5921Z to accept the sum of \$ 4,264.60 (inclusive of inte alia, damages, interests, loss of use, costs and disbursements) from M/s LKK Auto Consultants Pte Ltd, the authorized surveyors of M/s AXA Singapore Pte Ltd, the Third Party's insurers on this matter.

This acceptance is in full and final settlement of any claim made against SGK 6395E pursuant to the road accident which occurred along BLK 316 UBI AVENUE 1 CAR PARK ON 7.10.2012.

We, Trans-cab Auto Services Pte Ltd (workshop) are further authorized by the said owner that this settlement is reached on a strictly without prejudice basis on the part of M/s AXA Insurance Singapore Pte Ltd. And or their insured or other person or persons arising out of this said accident.

In consideration of the said payment by the said M/s AXA Singapore Pte Ltd, we, the said authorized workshop, shall fully discharge them from any further claim whatsoever in respect of the said accident.

We also declare that we are authorized by the said owner to receive the said settlement sum and hereby undertake to indemnify M/s AXA Insurance Pte Ltd, against any claim made or which may be made in respect of this matter.



For and on behalf of the owner of
(SHC 5921Z)
(workshop stamp and authorized signature)



For and on behalf of M/s AXA
Insurance Singapore Pte Ltd
(LKK stamp and authorized signature)

1000	1	RR BOX DR FRAME RUBB	Renew	0%	0.00
1000	1	RR BOX DR HINGE LH	Renew	0%	0.00
1000	1	RR BOX DR HINGE RH	Renew	0%	180.00*
1000	1	RR BOX DR MOUNT LH	Renew	0%	0.00
1000	1	RR BOX DR MOUNT RH	Renew	0%	0.00
1000	1	RR SAFETY MOUNT LH	Renew	0%	0.00
1000	1	RR SAFETY MOUNT RH	Renew	0%	0.00
f: OEM Parts				Sub Total	\$480.00
g: Original				Total Parts	\$480.00
h: Secondhand					
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REALIGN ALL PARTS SPECIALIST	0%	\$250.00
RESPRAY PAINT SPECIALIST		\$0.00
TUFFCOAT SPECIALIST	0%	\$0.00
WIRING CHECK SPECIALIST		\$0.00
REMOVE/REP SPECIALIST	0%	\$0.00
R/SENSOR		\$0.00
DOOR MECHANISM SPECIALIST		\$42.00
AUDATEX FEE SPECIALIST	0%	\$292.00
Total Extras		\$292.00

Final Calculation

Total Parts		\$480.00
Labour		
Total Panel/Mechanical	\$0.00	
Total Paintwork	\$0.00	
Total Labour		\$0.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$292.00	
Total of Additional Costs		\$292.00
Total Paint/Material Costs		\$0.00
Grand Total Excludes GST		\$772.00
GST @ 7 %		\$54.04
Grand Total Includes GST		\$826.04

Assessment Notes

Trans-Cab Auto Services Pte Ltd

No. 58 Defu Lane 1

Tel: 6287 6666

Fax: 6287 7764


Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice

TO: AXA INSURANCE (S) PTE LTD	INVOICE NO. : INV1212-049 DATE : 7. December 2012 REFERENCE N : AAD1210-100 TERMS : DUE DATE : 7. December 2012 PAGE : 1
ATTENTION:	

NO.	CODE	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1.	6050101	Repair Cost (Lump sum)SHC5921Z DOA:07.10.12	1	3,852.00	3,852.00



Total SGD Excl. GST : 3,600.00

7% GST : 252.00

Total SGD Incl. GST : 3,852.00

****** THREE THOUSAND EIGHT HUNDRED FIFTY TWO AND 0/100 SGD**

- 1) All cheques should be crossed and made payable to **"Trans-Cab Auto Services Pte Ltd"**
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to change interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.

THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE

Veron Chen (LKKAuto)

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
<TeyChorKeng@smrt.com.sg>
Sent: Tuesday, 22 May 2018 11:14 AM
To: Veron Chen (LKKAuto)
Cc: SUR; Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: RE: YP 6578E-DOA: 29/3/2018 (MSIG TP)
Attachments: IMG_3184.JPG; IMG_3185.JPG; IMG_3186.JPG; IMG_3187.JPG; IMG_3188.JPG; IMG_3189.JPG

Dear Veron,

We have confirmed to accept the finalise amount \$772 @ 2days.

Attached is the After repair photo.

Regards,
Esther

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: 21 May 2018 15:40
To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Cc: SUR
Subject: YP 6578E-DOA: 29/3/2018 (MSIG TP)

Dear Esther,

WITHOUT PREJUDICE

Finalise amount \$772 @ 2 days .

Kindly confirmed.

Please provides us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Handwritten signature



6R0821106F	FRT FENDER RH	1 NORA ORDER (TUE 070812)
061103138F	OIL SUMP INNER BRACKET	1 NORA ORDER (TUE 070812)
110973703B	SOCKET	1 NORA ORDER (TUE 070812)
6R0867255K 989	TRIM	1 NORA ORDER (TUE 070812)
3C8845011E NVB	W/SCREEN	2 NORA ORDER (TUE 070812)
4L0853736 2Z	LOGO	1 NORA ORDER (TUE 070812)
7L6807699B	RADIATOR GRILLE BRACKET	1 NORA ORDER (TUE 070812)
7L0825285C	FRT ENGINE LOWER COVER	1 NORA ORDER (TUE 070812)
1K0853651E VW8	FRT GRILLE	3 NORA ORDER (TUE 070812)
1T0853601A FDY	FRT GRILLE LOGO	1 NORA ORDER (TUE 070812)
8E0853651M TOP	FRT GRILLE	1 NORA ORDER (TUE 070812)
8E0807105F GRU	FRT BUMPER	1 NORA ORDER (TUE 070812)
8E0807109J	FRT BUMPER REINFORCEMENT	1 NORA ORDER (TUE 070812)
4F0853736A 2ZZ	FRT GRILLE LOGO S LINE	1 NORA ORDER (TUE 070812)
8R0821106A	FENDER	1 NORA ORDER (TUE 070812)
1T0807369 GRU	REAR BUMPER TOW COVER	1 NORA ORDER (TUE 070812)
1T0807863C	BUMPER TOW COVER EYE	1 NORA ORDER (TUE 070812)
1T0807305F	BUMPER REINFORCEMENT	1 NORA ORDER (TUE 070812)
1T0945096N	TAIL LAMP	1 NORA ORDER (TUE 070812)
1T0945095N	TAIL LAMP	1 NORA ORDER (TUE 070812)
1T0807375C	BUMPER BKT R/LH	1 NORA ORDER (TUE 070812)
1T0807376C	BUMPER BKT R/RH	1 NORA ORDER (TUE 070812)
1T0945106A	REAR LIGHT REFLECTOR	1 NORA ORDER (TUE 070812)
1T0945105A	REAR LIGHT REFLECTOR	1 NORA ORDER (TUE 070812)
8I2611021D	BRAKE MASTER PUMP	1 NORA ORDER (TUE 070812)
7L6422891L	LOW PRESSURE HOSE	1 NORA ORDER (TUE 070812)
7L6422895G	P/STG HOSE	1 NORA ORDER (TUE 070812)
7L6422893BD	HIGH PRESSURE HOSE	1 NORA ORDER (TUE 070812)
7L6422889N	INTAKE HOSE	1 NORA ORDER (TUE 070812)
7L0317801J	OIL PRESSURE LINE	1 NORA ORDER (TUE 070812)
7L6945105A	BUMPER REFLECTOR	1 NORA ORDER (TUE 070812)
6R0941511	mounting clip	4 NORA ORDER (TUE 070812)
6R0121207C	FAN COWLING	1 NORA ORDER (TUE 070812)
4F0998281B	RR BRAKE SWITCH MOTOR	2 NORA ORDER (TUE 070812)
4E0945093G	TAIL LAMP LH (INNER)	1 NORA ORDER (TUE 070812)
3T0819465	AIR VENT	1 NORA ORDER (TUE 070812)
8P3807394A	TAIL LAMP LOWER BRACKET RH	1 NORA ORDER (TUE 070812)
8P3809460F	TAIL LAMP INNER PANEL RH	1 NORA ORDER (TUE 070812)
1K0823031J	BONNET	2 NORA ORDER (TUE 070812)
8E0831051L	FRT DOOR LH	1 NORA ORDER (TUE 070812)
8E0833051J	RR DOOR LH	1 NORA ORDER (TUE 070812)
6R1823509D	BONNET LOCK	1 NORA ORDER (TUE 070812)
6R0121283J	AIR GUIDE LH	1 NORA ORDER (TUE 070812)
6R0121284D	AIR GUIDE RH	1 NORA ORDER (TUE 070812)
6R0807221R GRU	FRT BUMPER	1 NORA ORDER (TUE 070812)
6R0959455C	FAN MOTOR	1 NORA ORDER (TUE 070812)
6R0805071E	FRT HEADLAMP BEAM LH	2 NORA ORDER (TUE 070812)

Claim Documents

YP6578E (554427)
[YM1798K]
TP
CK SEAFOOD PTE LTD
Mar 29 2018 1:00PM
[BIAN HIN CO (S) PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	10/04/18 14:01	Repairer Estimates	Load HTM	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/04/18 15:56	Accident Statement <small>From: SC - Reg. No: YM1798K, Claimant: BIAN HIN CO (S) PTE LTD</small>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/04/18 09:48	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	12/04/18 12:34	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
31	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
32	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
33	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
34	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
35	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
36	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
37	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
38	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
39	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
40	12/04/18 12:34	General View	Load JPG	<input checked="" type="checkbox"/>
41	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	22/05/18 11:58	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	07/04/18 11:17	Singapore Accident Statement	Load PDF	
2	07/04/18 11:25	Driver's Driving License	Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 11:56	Audatex Estimates	Load PDF	
4	09/04/18 11:56	Singapore Accident Statement	Load PDF	
5	09/04/18 11:56	Driver's Driving License	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006684/R1VD3E2

Date: 28/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28737484TMV
Claimant Vehicle No : YP6578E	Insured Vehicle No :	YM1798K
Date of Loss: 29/03/2018	Nature of Claim:	TP
		Claim No: 554427

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP6578E	Engine No:	N04CUS31676
Make & Model:	HINO XZU700R, 4.0 D (M)	Chassis No:	JHHTCS3H70K003285
Reg. Date:	21/06/2017 (Man. Year: 2016)	Odometer:	33481 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,405.60	480.00	1,925.60	80.05
Miscellaneous Items	582.00	42.00	540.00	92.78
Labour	815.00	250.00	565.00	69.33
Paintwork Labour	800.00	0.00	800.00	100.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,602.60	772.00	3,830.60	83.23
+ GST 7.00/7.00% (S\$)	322.18	54.04	268.14	83.23
Nett Amount (S\$)	4,924.78	826.04	4,098.74	83.23

INSPECTION

Date of Assignment:	11/04/2018 Present Location:	SMRT Automotive Services Pte Ltd (Woodlands)
Date Inspected:	11/04/2018 Inspected At:	60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 May 2018)	
Parts:	N/A	HINO XZU700R 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6578E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		2,405.60 F	*480.00 F
					Total Parts (S\$)	480.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AUDATEX FEE	42.00	42.00
2	1	TUFFCOAT / WIRING CHECK / REMOVE & REPLACE REVERSE SENSOR / REMOVE & REPLACE TRANSFER DOOR MECHANISM	540.00	0.00
Sub Total (\$\$)			582.00	42.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Paint Labour	New	800.00	0.00
Labour Items				
2	Labour	New	815.00	250.00
Gross Labour Cost (\$\$)			1,615.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >