



AUTO PTE LTD

# 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

No. : 29655

Vehicle Insured : SLB 1250 K  
Accident Date : 20-Mar-2018

Date : 23-Mar-2018

Our Ref : 180221 (AXA) / SHUMAN

PAGE : 1

PING MIN MEDICAL HALL  
Singapore

*Not Ashair*  
*Runway B4 pain 3 days*

ESTIMATED COST OF REPAIR FOR HYUNDAI H1 STAREX 2.5 CRDI (2017) PC6294Z

- =====
- 1 pc rear bumper
  - 1 pc rear bumper step garnish
  - 1 pc rear bumper sponge
  - 1 pc rear bumper reinforcement
  - 1 pc o/s rear bumper side retainer
  - 10 pcs rear bumper clips @ S\$ 2.00
  - 1 pc o/s rear bumper corner garnish
  - 1 pc o/s rear bumper corner garnish side retainer
  - 1 pc o/s taillamp

*Del 1 cm* 435.00 ✓  
*Sn* 57.90 X  
*Sn* 74.30 X  
*Sn* 347.00 X  
*Sn* 29.50 X  
*cm* 20.00 ✓  
*cm* 98.30 ✓  
           29.50 7  
*Gm* 384.90 ✓

1,476.40  
Less 20% : -295.28  
----- 1,181.12

- 1 pc reverse sensor

*Sn* 220.00 sn X

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

700.00 *400l*

To focus taillamps. To check rear  
wiring and lighting operation.

50.00 *20l*

To remove and refit reverse sensor  
assy.

80.00 *50l*

To putty and respray on affected  
portions.

600.00 *320l*

-----  
Total : S\$ 2,831.12  
-----

Singapore Dollars Two Thousand Eight Hundred  
and Thirty One and Cents Twelve Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: